



Huatong Contractor Pte Ltd

NO. 9 Bend Crescent, Singapore 629972
TEL: 6366 1005 FAX: 6368 1391
Co. Registration No: 198364322E

Repair Estimate

Damage Assessed by:	Kemmy
Classification:	Claim 3rd Party
Owner:	HUATONG CONTRACTOR PTE LTD
Date:	3/12/2019
Vehicle Type:	L200 Triton Double Cab A/T No Sunroof
Registration Number:	GBD9366R
Chassis No:	MMBJYKB40FD062406
Engine No:	4D56UCFS7763
Year of Make:	2015
Date of Registration:	22/07/2015

Labour Type	Operation	Line Item	Description	Dollar Amount
BODY				
	Remove/Replace	Tailgate Assy	✓ 00	\$2,500.00
	Remove/Replace	Rear left Taillamp assy	✓ RR	\$650.00
	Replace	Rear left reflector	✓ OR	\$200.00
	Remove/Replace	Rear number plate assy	✓ X	\$50.00
	Remove/Replace	Rear Reverse sensor complete assy	✓ X	\$850.00
				\$4,250.00

Estimate Totals

Labour Subtotal	Hours	Rate	Total
Body	16	\$ 30.00	\$480.00
Additional Costs			
Paint			\$500.00
Parts Replacement Summary			\$4,250.00
Total Labour Costs			\$480.00
Total Parts Replacement Costs			\$4,250.00
Total Additional Costs			\$500.00
Gross Total			\$5,230.00

*PS: Price quoted above shall subject to 7% GST.

Steve (LKK) wtl #101 11/12/19, 2:00pm
83228813 3 days
Steve.chn@lkkautp.com L/S
Ry AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: