

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AXA DATE : 06/12/2019
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SKZ3039C
MODEL : KIA CERATO K3 1.6A
CHASSIS NO

ACCIDENT DETAILS DATE : 2-Dec-19
TIME : 11:45HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 710.00	\$ 710.00
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	2	\$ 58.00	\$ 116.00 58.
3	HEADLAMP LH <i>lt</i>	1	\$ 2,255.00	\$ 2,255.00
4	HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 80.00	\$ 80.00
5	FRONT FENDER LH <i>Dented</i>	1	\$ 580.30	\$ 580.30
6	FRONT FENDER INNER COWLING <i>Replaced</i>	1	\$ 180.00	\$ 180.00

TOTAL PRICE \$ 3,921.30

LESS 10% \$ 392.13

SUB TOTAL PRICE \$ 3,529.17

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	WHEEL RIM <i>lt</i>	1	\$ 900.00	\$ 900.00 400.

TOTAL \$ 940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	
3	TUFF COAT	\$ 150.00	X	
4	WIRING CHECK	\$ 50.00	30	
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X	
6	REMOVE AND REFIX FRONT SENSOR	\$ 100.00	50	

TOTAL

\$2,380.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,469.17

TOTAL LABOUR COST : \$ 2,380.00

TOTAL REPAIR COST : \$ 6,849.17

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King,
L/S 10/12/19.
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: