



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4 Premier @ KB #07-08 S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SJR7656Z

GB31034258

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition	Per Unit	Our Estimates
1	1 pc	Replace New Rear Boot with Windscreen	Distorted		\$2,950.00 1247.
2	1 pc	Replace New Rear Bumper	Rehd		\$1,850.00 685
3	2 pc	Honda & Freed Emblem	new		\$250.00 95
4	1 set	Rear Tail Light	new	\$550.00	\$1,100.00 x.
5	1 pc	Carplate	Best		\$50.00 30
6	1 pc	Carplate Holder	Rehd		\$60.00 30.
7	1 pc	Reverse Sensor	Dmgd		\$320.00 200 (sn)
8	1 pc	Rear Bumper Retainer	new		\$580.00 35
9	1 pc	Rear End Panel	Dented		\$780.00 590
10	1 pc	Rear Exhaust	new		\$620.00 x
11	1 pc	Rear Bumper Bracket	new	\$90.00	\$360.00 x
12	1 pc	Reverse Camera	Dmgd		\$180.00 ✓
13	1 pc	Rear Door Locking System	Dmgd		\$480.00 ✓
14	1 pc	Rear Door Absorber Hinge	new		\$350.00 x
15	1 pc	Weather Strip	Cut	4092	\$280.00 ✓
16	1 pc	Rear Boot Cover	can be	3273.60	\$250.00 ✓
17	1 pc	Rear boot Cover	Rehd		\$180.00 ✓
		End Panel			SN: 200
Parts Total :					\$10,640.00



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4 Premier @ KB #07-08 S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SJR7656Z

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	Labour for remove and installation of damaged & affected Parts Rear Bumper and Rear Boot with Windscreen & Necessary Parts	\$890.00 800
1	Spray Painting to Rear Bumper, Rear Boot & Reverse Sensor & Necessary Parts	\$820.00 800
3	Diagnostic To Vehicle & Electrical System	\$250.00 x
4	Rewiring Of Camera & Reverse Sensor	1720 \$220.00 120
5	Panel Beating & Re-Alignment Of Chassis Body	\$490.00 x
6	Remove and Install Rear Exhaust	\$280.00 x

Labour Total : \$2,950.00

Parts Total : \$10,640.00

Total (Parts & Labour) : \$13,590.00

For Lump Sum Repairs

The estimated amount calculated is \$13,590.00

Under normal circumstances, the repairs should be completed within a reasonable period

Of 5 Working Days. (Exclude waiting days of PRI, Sunday and Public Holiday)

Adrian L

w/s 04/12/19.

07 Days.

total: 5193.6

w/s : 4150.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: