

INS. CASE OWNER:

Suling
Lup

CC 4/AIG190 21645 / A ea3 9/

LKK:
IDAC

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

6/12/19

6/12/19
9/12/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 7870E

Claim No.:

Name of Insured:

BRN Rent A Car Pte Ltd

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A:

04/12/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKR 6784G



INSRS:

WSP: VISION

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SKR 6784G - NBR / TM119021442 / 4	Non-Reporting Itr (1st):	04/12/2019
	SJB 7870E - NBR / TM119021442 / 4	Non-Reporting Itr (2nd):	04/12/2019
		Non-Reporting Itr (Final):	
31-12-19	EMAIL RESP LIABILITY CLAIM.	Notification Itr (if non-pickup):	
		Call OI:	3/12
		After call Itr to OI:	
11-02-20	FILE PASD TO TYPST TO POST-PAGE REPORT.	Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup)	
		After call Itr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:		Confirm by: Lup	
FINALIZATION Date/Time:		Confirm with:		Confirm by: Lup	
Repair Cost:	S\$13,300	(13 days) Reduction:	55 %	Email	Call
FINAL SETTLEMENT Date/Time: 05-03-20		Confirm with: MICHELLE		Email	
Final Liability:	S\$100	(Agreed / Assessed) BOLA S/N No.:	28	If NO or B 28, Ass. Lia: 100%	
Repair Cost:	S\$14,231.00	3 YRS CC OND LPRG			
Loss of Rental (LOR):	S\$ -	(days)			
Loss of Use (LOU):	S\$ 960.00	(500 x 12 days)			
Loss of Income (LOI):	S\$ -	(5 x days)			
LOR only	☐	LOU only	☐	LOR + LOU	☐
LOR + LO	☐	(Tick only one)			
GIA/LTA Search	S\$36.45				
Medical:	S\$ -				
Disbursement:	S\$ -	(e.g. Tow/ Independent)			
Legal Cost	S\$ -				
Total:	S\$15,221.45	Global Sum S\$:			
FINAL PAYMENT Date/Time: 05-03-20		Confirm with: MICHELLE		Email	
Payee 1:	S\$15,221.45	Name 1:	VISION AUTOCODEX PTE LTD		
Payee 2: (Strike if N.A.)	S\$	Name 2:			
Payee 3: (Strike if N.A.)	S\$	Name 3:			

COPY SENT
9/13/2022

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 04.12.19

TO : AIG MOTOR CLAIMS DEPTS

VEHICLE NO : SKR6784G

MODEL : TOYOTA WISH

DATE OF ACCIDENT : 04.12.19

TIME OF ACCIDENT : 08:25HRS

Asher

JTDFR12W303001743

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 510.00	\$ 510.00
2	FRONT BUMPER LOWER GRILLE <i>New</i>	1	\$ 130.00	\$ 130.00
3	FRONT BUMPER FOGLAMP COVER <i>New</i>	2	\$ 70.00	\$ 140.00
4	FRONT BUMPER SIDE RETAINER <i>New</i>	2	\$ 55.00	\$ 110.00
5	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 300.00	\$ 300.00
6	FRONT BUMPER SPONGE <i>Combined</i>	1	\$ 150.00	\$ 150.00
7	FRONT BUMPER UNDER COVER GARNISH <i>New</i>	1	\$ 180.00	\$ 180.00
8	HEADLAMP <i>Combined</i>	2	\$ 1,070.00	\$ 2,140.00
9	FRONT FENDER COWLING <i>New</i>	2	\$ 146.00	\$ 292.00
10	CENTRE GRILLE <i>Combined</i>	1	\$ 360.00	\$ 360.00
11	BONNET <i>Dented</i>	1	\$ 665.00	\$ 665.00
12	BONNET MOULDING <i>Lot</i>	1	\$ 205.00	\$ 205.00
13	BONNET LOGO <i>New</i>	1	\$ 60.00	\$ 60.00
14	BONNET LOCK <i>Damaged</i>	1	\$ 90.00	\$ 90.00
15	BONNET LOCK CABLE <i>Not New</i>	1	\$ 85.00	\$ 85.00
16	BONNET STOPPER <i>2</i>	2	\$ 20.00	\$ 40.00
17	BONNET HINGE <i>New</i>	2	\$ 30.00	\$ 60.00
18	BONNET INSULATOR	1	\$ 245.00	\$ 245.00
19	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 890.00	\$ 890.00
20	FRONT BRACE PANEL <i>Best</i>	1	\$ 90.00	\$ 90.00
21	HORN <i>Not New</i>	2	\$ 85.00	\$ 170.00
22	TEMPERATURE SENSOR <i>New</i>	1	\$ 160.00	\$ 160.00
23	AIR GUARD GARNISH <i>New</i>	2	\$ 120.00	\$ 240.00
24	AIRCON CONDENSOR <i>Dented</i>	1	\$ 1,600.00	\$ 1,600.00
25	RADIATOR SUPPORT PANEL <i>Replaced</i>	1	\$ 985.00	\$ 985.00
26	RADIATOR <i>Combined</i>	1	\$ 1,810.00	\$ 1,810.00
27	RADIATOR MOUNTING <i>New</i>	4	\$ 42.00	\$ 168.00
28	RADIATOR BRACKET <i>New</i>	2	\$ 91.00	\$ 182.00
29	RADIATOR FAN COWLING <i>Not New</i>	1	\$ 260.00	\$ 260.00

1425

1543

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKR6784G**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 04.12.19
 TIME OF ACCIDENT : 08:25HRS

30	TAILGATE <i>Dented</i>	1	\$ 1,280.00	\$ 1,280.00	✓
31	TAILGATE OUTER MOULDING <i>could</i>	1	\$ 240.00	\$ 240.00	✓
32	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00	✓
33	TAILGATE INNER LOCK <i>Repair</i>	1	\$ 445.10	\$ 445.10	✓
34	TAILGATE LOWER LOCK <i>new</i>	1	\$ 35.00	\$ 35.00	✓
35	TAILGATE DAMPER <i>new</i>	2	\$ 194.00	\$ 388.00	✓
36	TAILGATE STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00	✓
37	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 320.00	\$ 320.00	✓
38	TAILGATE INNER TRIM (LOWER) <i>could</i>	1	\$ 395.00	\$ 395.00	✓
39	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00	✓
40	REAR BUMPER <i>Dented</i>	1	\$ 590.00	\$ 590.00	✓
41	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 68.00	\$ 136.00	✓
42	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 70.10	\$ 140.20	✓
43	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00	✓
44	TAILLAMP C/W BRACKET <i>could</i>	2	\$ 520.00	\$ 1,040.00	8/8 ✓
45	REAR FENDER INNER COWLING <i>new</i>	2	\$ 380.00	\$ 760.00	✓
46	REAR FENDER INNER TRIM <i>could</i>	2	\$ 738.10	\$ 1,476.20	1321 ✓
47	REAR END PANEL <i>Dented</i>	1	\$ 480.00	\$ 480.00	✓
48	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 245.00	\$ 245.00	✓
49	REAR END PANEL (EXTEND) <i>Dented</i>	2	\$ 298.70	\$ 597.40	✓
50	REAR END PANEL BOTTOM (CENTRE) <i>Repair</i>	1	\$ 311.10	\$ 311.10	✓
51	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,150.00	\$ 1,150.00	✓
52	REAR TOP BOARD INNER SUPPORT <i>new</i>	1	\$ 585.00	\$ 585.00	✓
53	REAR FLOOR TOP BOARD (CENTER) <i>could</i>	1	\$ 395.00	\$ 395.00	✓
54	REAR FLOOR TOP BOARD (SIDE) <i>new</i>	2	\$ 140.00	\$ 280.00	✓
55	SPARE TYRE CHAIN <i>new</i>	1	\$ 350.00	\$ 350.00	✓
56	REAR EXHAUST PIPE <i>2</i>	1	\$ 980.00	\$ 980.00	✓
57	REAR EXHAUST MOUNTING <i>new</i>	5	\$ 45.00	\$ 225.00	✓
58	REAR EXHAUST INSULATOR	1	\$ 160.00	\$ 160.00	✓
59	REAR CHASSIS MEMBER LH <i>Repair</i>	1	\$ 1,450.00	\$ 1,450.00	✓

1616970
1212727

TOTAL PRICE \$ 27,116.00
 LESS 25% \$ 6,779.00
SUB TOTAL PRICE \$ 20,337.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE Bent	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) New	1	\$ 80.00	\$ 80.00
3	FRONT FENDER COWLING CLIP (SET) New New	1	\$ 80.00	\$ 80.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKR6784G**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 04.12.19
 TIME OF ACCIDENT : 08:25HRS

4	BONNET SEALANT <i>3m</i>	1	\$ 150.00	\$ 150.00	+
5	BONNET INSULATOR CLIP (SET) <i>me</i>	1	\$ 80.00	\$ 80.00	+
6	CENTRE GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10.
7	RADIATOR SUPPORT PANEL SEALANT <i>me</i>	1	\$ 120.00	\$ 120.00	+
8	COOLANT <i>new</i>	1	\$ 60.00	\$ 60.00	40
9	REAR NUMBER PLATE <i>not new</i>	1	\$ 50.00	\$ 50.00	+
10	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
11	REAR BUMPER REFLEC STICKER <i>new</i>	1	\$ 60.00	\$ 60.00	20
12	TAILGATE SEALANT <i>not in</i>	1	\$ 150.00	\$ 150.00	+
13	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20
14	TAILGATE EMBLEM 'AERO TOURER' (SPECIAL TYPE) <i>new</i>	1	\$ 120.00	\$ 120.00	60
15	TAILGATE EMBLEM 'BORNEO' <i>new</i>	1	\$ 80.00	\$ 80.00	50.
16	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30.
17	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	30
18	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	40
19	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	60.
20	REAR FENDER INNER COWLING CLIP (SET) <i>not new</i>	1	\$ 80.00	\$ 80.00	+
21	REAR FENDER INNER TRIM 'LED' LIGHT (SPECIAL TYPE) <i>new</i>	1	\$ 350.00	\$ 350.00	+
22	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60.
23	REAR END PANEL TOP GARNISH <i>Clips new</i>	1	\$ 60.00	\$ 60.00	20
24	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
25	REVERSE CAMERA <i>not new</i>	1	\$ 480.00	\$ 480.00	+
26	REVERSE SENSOR <i>changed</i>	1	\$ 220.00	\$ 220.00	200

760 TOTAL \$2,970.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600
3	REFOCUS HEADLAMP BEAM	\$ 80.00	x
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60

1520

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKR6784G**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : **04.12.19**
TIME OF ACCIDENT : **08:25HRS**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	x
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	/
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 8,370.00

ESTIMATE REPORT

TOTAL PARTS COST : \$23,307.00
TOTAL LABOUR COST : \$8,370.00
TOTAL REPAIR COST : \$31,677.00

Adrian King. total: 16627.27
h/s 06/12/19. h/s: 13.31c
12 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

- To be used by authorised parties during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	782C
Vehicle Details	
Vehicle No.:	SKR6784G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1ZZ3225118
Chassis No.:	JTDER12W303001743
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	20 Feb 2009
First Registration Date:	20 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$18,803.00
Intended PARF Eligibility Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$28,673.00
Total Rebate Amount:	\$28,673.00

The information contained herein is correct as at 06 Dec 2019

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal COE Toyota Wish 2.0A

2.88% P.A, \$0 Admin, Monthly From \$688, 2 Years Warranty Engine And Gearbox
GV Credit StarAd

CERTIFIED PRE-OWNED MERCEDES BENZ

[View Our Store](#)

Browse by Category

Save Search Print

◀ Back (1 2 3 4 5 6 7) Next ▶

Sort by Date Posted

20 results/page

140 vehicles

Search Toyota Wish

Advanced Search Search view All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	Toyota Wish	Any	Any	2009	Any	Any	Any	Available
------------------	-------------	-----	-----	------	-----	-----	-----	-----------

☐ **Toyota Wish 1.8A X (New 5-yr COE)**

\$37,800

\$7,550 /yr

21-Nov-2009

1,797 cc

-

MPV

Available

2.88% Per Annum By GV In House Financing. No Admin Fees! All Wear And Tear Done! 2 Years Warranty Engine And Gearbox. New Paintwork Of Y...
2.88% P.A, \$0 Admin, Monthly From \$688, 2 Years Warranty Engine And Gearbox.
GV Credit Pte Ltd

Posted: 04-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

☐ **Toyota Wish 1.8A X (COE till 01/2029)**

\$51,500

\$5,650 /yr

16-Jan-2009

1,794 cc

-

MPV

Available

1 Owner Only! Intend To Drive Longer For This Beloved Family Car, Therefore Rewrapped The Leather Seats, Changed The Tyres And Renew The COE For Another 10 Years. But Wife Wants To Change To Another Bigger MPV As Family Is Growing! Therefore Have To Sell...

Posted: 05-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

☐ **Toyota Wish 1.8A Aero Tourer (COE till 02/2024)**

\$25,800

\$6,150 /yr

16-Feb-2009

1,794 cc

200,000 km

MPV

Available

Very Nice Paint Work.

Posted: 06-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

☐ **Toyota Wish 1.8A (COE till 02/2029)**

\$51,800

\$5,610 /yr

02-Mar-2009

1,794 cc

100,000 km

MPV

Available

Consignment Code: A399. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Posted: 29-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

☐ **Toyota Wish 1.8A (COE till 02/2024)**

\$40,800

\$9,630 /yr

02-Mar-2009

1,794 cc

134,033 km

MPV

Available

\$756 Monthly Instalment, Over 48 Months, 100% Loan Available. Flexible Loan Options From Bank/In-House Curated To Your Financing Needs, With Attractive Interest Rates! Consignment Unit, Free 6 Months Road Tax, External Checks And Evaluation Welcome, Trade-Ins...

Posted: 22-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

☐ **Toyota Wish 1.8A (COE till 03/2024)**

\$33,800

\$7,930 /yr

11-Mar-2009

1,794 cc

-

MPV

Available

Full Loan Monthly \$800! Grab, Go-Jek Are Welcome! Many Other Loan Scheme At Your Comfort. Cheap And Practical 7 Seaters Up For Sale. Reliable Engine And Gearbox, Low Maintenance Cost. Call Us View And Test Drive! Don't Miss It Hurry!

68 Motor Trading

Posted: 20-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

Compare

☐ **Toyota Wish 1.8A (COE till 02/2029)**

\$52,000

\$5,630 /yr

20-Mar-2009

1,794 cc

107,000 km

MPV

Available

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 31 December 2019 12:00 PM
To: Vision Autowork
Subject: ACCIDENT INVOLVING SKR 6784G AND SJB 7870E ON 04/12/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

ACCIDENT INVOLVING SKR 6784G AND SJB 7870E ON 04/12/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Authorization To Act

I, Cheng Cheong Hiam ("the third party claimant") of
Blk 253 Banger Road #13-22B S(2567)
(address), owner of SR6784G (vehicle no.) hereby
authorize Vision Autowork Pte. Ltd
("the workshop") to act for me with respect to my claim for repair
costs and/or rental and/or loss of use ("claim") for my vehicle
no. SR6784G that was damaged pursuant to the accident which
occurred on 04/12/19 (date) along BKE towards PIE
(After Dairy Farm Road Exit) (location) involving
vehicle no/s SJ57870E
("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that
they deem fit and the workshop is further authorized to receive payment further to
settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on
a without prejudice and without admission of liability basis in so far as the
driver/owner/insurers of the other vehicle/s is concerned.

Dated this 04 day of 12 (month) 20 19 (year)



Signed by "the third party claimant"

Handwritten signature of the workshop, Vision Autowork Pte. Ltd.



Signed by "the workshop"

VISION AUTOWORK PTE. LTD.
 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875
 Tel: 6341 6789 Fax: 6341 6778
 Co. Reg. No. : 201500371E

Letter of Authorisation & Indemnity

Accident Involving Vehicle no. SKR6754G and 57A7870E On 04/12/19

At BKE towards PIE (After Dairy Farm Road Exit)

1. I/We, the owner of vehicle no. SKR6754G hereby instruct and authorize Vision AutoWork Pte Ltd ("the workshop") to commence repairs to the said vehicle. Pending the outcome of my/our claim against the third party, I/we forthwith pay you the sum of \$ _____ being refundable deposit of the repair to my/our said vehicle.
2. You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in court in my/our name against the third party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit.
4. Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional costs and disbursement for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account. In the event that my/our claim or legal costs of the third party as well as the professional costs and disbursements of my/our solicitors notwithstanding that my/our solicitors were appointed by you on our behalf.
5. I/we also hereby instruct and authorise you deduct directly from the claim monies received from the third party all outstanding balances that are still owing to you, namely the balance of repair costs and rental of substitute vehicles.
6. In the event that I/we are required to attend at my/our solicitors office or to attend court in connection with my/our claim, I/we shall render full co-operation.
7. In the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with and/or if any Judgement or settlement is not honoured or satisfied by the third party, I/we authorise you to revert the claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respect, I/we understand and accept that the excess amount applicable under policy of insurance shall be borne by me/us.
8. If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I/we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
9. I/we shall keep you informed of any correspondences and/or summons that I may receive due to this action agreeing to pay or receive any monies due to this claim.

Dated this 04 day of 12 2019

Signature of vehicle owner [Signature]

Name - Cheng Chong Heng

IC No: S1630782C

(Company stamp, if applicable)

Address: B1K 253 Bukit Kit Road

#13-228, SC2367

Tel: _____



Witnessed by:

[Signature]

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	09 Dec 2019 15:29	Clim Dtl Modified	Claimant's Name: -> CHENG CHOONG HIANG. Claimant's ID: -> S1630782C.	[A] Suwanna Te-Uttaruang	
2	09 Dec 2019 15:29	Clim Veh Model Changed	(201172) TOYOTA WISH 1.8 (A).	[A] Suwanna Te-Uttaruang	
3	09 Dec 2019 15:29	Clim Created	Reg No: SKR6784G. Acct Date: 2019/12/04. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: Tokio Marine Insurance Singapore Ltd (HQ). Workshop: Vision Autowork Pte L td (HQ)	[A] Suwanna Te-Uttaruang	
4	09 Dec 2019 15:29	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Suwanna Te-Uttaruang	
5	09 Dec 2019 15:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/18	[A] Suwanna Te-Uttaruang	
6	09 Dec 2019 15:29	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Suwanna Te-Uttaruang	
7	09 Dec 2019 15:29	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator	
8	09 Dec 2019 15:29	Label Added	(23):Express.	[A] Suwanna Te-Uttaruang	
9	09 Dec 2019 15:29	Adj Adjuster Assigned	[None] -> Asher Sng Rong Yi	[A] Suwanna Te-Uttaruang	
10	09 Dec 2019 17:18	Adj Adjuster Assigned	Asher Sng Rong Yi -> ADRIAN LING	[A] Suwanna Te-Uttaruang	
11	13 Dec 2019 11:54	Clim Registration Modified	Acct Time:00:00:00->08:00:00.	[I] AIG OneClaim Integration User	
12	14 Dec 2019 17:11	Label Removed	(23):Express.	[A] HOW MEI KWAN	
13	14 Dec 2019 17:11	Label Added	(19):Fastlane.	[A] HOW MEI KWAN	
14	17 Feb 2020 12:38	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN	
15	17 Feb 2020 12:38	Clim Dtl Modified	Insured ID: -> -, Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN	
16	17 Feb 2020 12:38	Clim Dtl Modified	JPJ Reg. Date: -> 2009/02/20.	[A] JOANNE LEE KHANG MIN	
17	17 Feb 2020 12:38	Clim Details Notified		[A] JOANNE LEE KHANG MIN	
18	17 Feb 2020 17:18	Adj Mandate Request	Cur.Req:15227.45:LIABILITY: 100% B:28 3VEH CC OLD LAST	[A] Asher Sng Rong Yi	

Date From

Date To

Audit Type

None

Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2371373	09 Dec 2019 15:36:06	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SKR6784G	SJB7870E	11.77
2440289	17 Feb 2020 12:38:40	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR6784G	SJB7870E	11.77

Print Received Message

This mail is associated with :

***SKR6784G (3490551604SG)**
[SJB7870E]

TP
CHENG CHOONG HIANG
Dec 4 2019 8:00AM
[BKW RENT A CAR PTE LTD]
Vision Autowork Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/03/2020 14:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15227.45) - SKR6784G - Claim Handler: Syed-Yusoff, Saliha

Approved:15227.45:pls proceed with settlement @ \$15,227.45 [COR-\$14,231 LOU-\$960 DOC-\$36.45] ** subject to final repair bill & ATA

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Dec 2019 Edit Reg		06 Dec 2019 00:00 Edit Adj Rpt	\$13,300.00 Edit Estimates	\$13,300.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BKW RENT A CAR PTE LTD, ID: -		
Main Claimant:	CHENG CHOONG HIANG, ID: S1630782C		
Vehicle Reg. No.:	SKR6784G	Date of Loss:	04/12/2019 08:00 - :59 [129 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3490551604SG	Policy/Cover Note No.:	0999993979 (Comprehensive)
Vehicle Reg. No. (Insured):	SJB7870E	Policy No. (Claimant):	19-MWD01819-RD4
		Excess:	
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (04/03/2020): Alert - Adj Mandate Approved (\$15227.45) - SKR6784G - Claim Handler: Syed-Yusof...
- AIG_SG (10/12/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKR6784G (3490551604SG)
[SJB7870E]
TP
CHENG CHOONG HIANG
Dec 4 2019 8:00AM
[BKW RENT A CAR PTE LTD]
Vision Autowork Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit				
															3 per page		☒			
Photos/Images																				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	29/01/20 10:18	General View														Load JPG	☒			
2	29/01/20 10:18	General View														Load JPG	☒			
3	29/01/20 10:18	General View														Load JPG	☒			
4	29/01/20 10:18	General View														Load JPG	☒			
5	29/01/20 10:18	General View														Load JPG	☒			
6	29/01/20 10:18	General View														Load JPG	☒			
7	29/01/20 10:18	General View														Load JPG	☒			
8	29/01/20 10:18	General View														Load JPG	☒			
9	29/01/20 10:18	General View														Load JPG	☒			
10	29/01/20 10:18	General View														Load JPG	☒			
11	29/01/20 10:18	General View														Load JPG	☒			
12	29/01/20 10:18	General View														Load JPG	☒			
13	29/01/20 10:18	General View														Load JPG	☒			
14	29/01/20 10:18	General View														Load JPG	☒			
15	29/01/20 10:18	General View														Load JPG	☒			
16	29/01/20 10:18	General View														Load JPG	☒			
17	29/01/20 10:18	General View														Load JPG	☒			
18	29/01/20 10:18	General View														Load JPG	☒			
19	29/01/20 10:18	General View														Load JPG	☒			
20	29/01/20 10:18	General View														Load JPG	☒			
21	29/01/20 10:18	General View														Load JPG	☒			
22	29/01/20 10:18	General View														Load JPG	☒			
23	29/01/20 10:18	General View														Load JPG	☒			
24	29/01/20 10:18	General View														Load JPG	☒			
25	29/01/20 10:18	General View														Load JPG	☒			
26	29/01/20 10:18	General View														Load JPG	☒			
27	29/01/20 10:18	General View														Load JPG	☒			
28	29/01/20 10:18	General View														Load JPG	☒			
29	29/01/20 10:18	General View														Load JPG	☒			
30	29/01/20 10:18	General View														Load JPG	☒			
31	29/01/20 10:18	General View														Load JPG	☒			
32	29/01/20 10:18	General View														Load JPG	☒			
33	29/01/20 10:18	General View														Load JPG	☒			
34	29/01/20 10:18	General View														Load JPG	☒			
35	29/01/20 10:18	General View														Load JPG	☒			
36	29/01/20 10:18	General View														Load JPG	☒			
37	29/01/20 10:18	General View														Load JPG	☒			
38	29/01/20 10:18	General View														Load JPG	☒			
39	29/01/20 10:18	General View														Load JPG	☒			
40	29/01/20 10:18	General View														Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	29/01/20 10:18	General View	 Load JPG	☒
42	29/01/20 10:18	General View	 Load JPG	☒
43	29/01/20 10:18	General View	 Load JPG	☒
44	29/01/20 10:18	General View	 Load JPG	☒
45	29/01/20 10:18	General View	 Load JPG	☒
46	29/01/20 10:18	General View	 Load JPG	☒
47	29/01/20 10:18	General View	 Load JPG	☒
48	29/01/20 10:18	General View	 Load JPG	☒
49	29/01/20 10:18	General View	 Load JPG	☒
50	29/01/20 10:18	General View	 Load JPG	☒
51	29/01/20 10:18	General View	 Load JPG	☒
52	29/01/20 10:18	General View	 Load JPG	☒
53	29/01/20 10:18	General View	 Load JPG	☒
54	29/01/20 10:18	General View	 Load JPG	☒
55	29/01/20 10:18	General View	 Load JPG	☒
56	29/01/20 10:18	General View	 Load JPG	☒
57	29/01/20 10:18	General View	 Load JPG	☒
58	29/01/20 10:18	General View	 Load JPG	☒
59	29/01/20 10:18	General View	 Load JPG	☒
60	29/01/20 10:18	General View	 Load JPG	☒
61	29/01/20 10:18	General View	 Load JPG	☒
62	29/01/20 10:18	General View	 Load JPG	☒
63	29/01/20 10:18	General View	 Load JPG	☒
64	29/01/20 10:18	General View	 Load JPG	☒
65	29/01/20 10:18	General View	 Load JPG	☒
66	29/01/20 10:18	General View	 Load JPG	☒
67	29/01/20 10:18	General View	 Load JPG	☒
68	29/01/20 10:18	General View	 Load JPG	☒
69	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
70	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
71	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
72	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
73	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
74	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
75	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
76	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
77	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
78	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
79	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
80	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
81	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
82	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
83	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
84	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
85	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
86	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
87	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
88	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
89	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
90	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
91	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
92	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
93	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
94	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
95	29/01/20 10:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
97	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
98	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
99	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
100	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
101	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
102	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
103	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
104	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
105	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
106	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
107	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
108	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
109	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
110	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
111	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
112	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
113	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
114	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
115	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
116	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
117	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
118	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
119	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
120	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
121	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
122	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
123	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
124	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
125	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
126	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
127	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
128	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
129	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
130	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
131	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
132	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
133	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
134	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
135	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
136	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
137	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
138	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
139	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
140	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
141	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
142	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
143	29/01/20 10:19	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/19 17:11	ACKNOWLEDGEMENT EMAIL TO AIG DD 06.12.19	 Load PDF	
2	14/12/19 17:11	EMAIL FROM AIG DD 06.12.19	 Load PDF	
3	14/12/19 17:11	TP GIA REPORT	 Load PDF	
4	14/12/19 17:11	NOTIFICATION FROM WORKSHOP	 Load PDF	
5	31/12/19 10:54	LETTER TO OI	 Load PDF	
6	09/03/20 14:56	LOD	 Load PDF	
7	09/03/20 14:56	Authorisation to Act	 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
8	09/03/20 14:56	WORKSHOP INVOICE		Load PDF	
9	16/03/20 10:14	Release Voucher		Load PDF	
10	16/03/20 10:14	LTA SEARCH		Load PDF	
11	16/03/20 10:14	GIA SEARCH		Load PDF	
No	Finalized On			Thumbnail	Print
		AIG Asia Pacific Insurance Pte. Ltd. (SG)			
1	10/12/19 17:33	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJB7870E (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SKR6784G (TP veh)		
Date of Accident:	04/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	33,894.39
Final Repair Cost	:	\$	14,231.00
Loss of Use	:	\$	960.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	36.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	15,227.45
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: ____%(%)		Assessed Liability (*):__100____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Vision Autowork Pte Ltd	:	\$ 15,227.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021645/AEA3Q2

Date: 16/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993979
 Claimant: SKR6784G Insured Vehicle No: SJB7870E
 Vehicle No: SKR6784G
 Date of Loss: 04/12/2019 Nature of Claim: TP Claim No: 3490551604SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR6784G
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3225118
 Reg. Date: 20/02/2009 (Man. Year: 2009) Chassis No: JTDER12W303001743
 Colour: White Odometer: 267821 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,307.00	12,887.27	10,419.73	44.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,370.00	3,740.00	4,630.00	55.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,677.00	16,627.27	15,049.73	47.51
Approved Total (Overridden) (\$\$)		13,300.00		
(\$\$)	31,677.00	13,300.00	18,377.00	58.01
+ GST 7.00/7.00% (\$\$)	2,217.39	931.00	1,286.39	58.01
Nett Amount (\$\$)	33,894.39	14,231.00	19,663.39	58.01
+ Loss of Use (12.0 x S\$80.00/day) (\$\$)		960.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		15,227.45		

INSPECTION

Date of Assignment: 06/12/2019
 Date Inspected: 06/12/2019 Inspected At: Vision Autowork Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4,, #08-09
 PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	510.00 FL	*510.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	130.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	140.00 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	300.00 FL	*300.00 FL
6	1		*FRONT BUMPER SPONGE	Cracked	150.00 FL	*150.00 FL
7	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	180.00 FL	*- FL
8	2		*HEADLAMP	Cracked	2,140.00 FL	*2,140.00 FL
9	2		*FRONT FENDER COWLING	Not Necessary	292.00 FL	*- FL
10	1		*CENTRE GRILLE	Cracked	360.00 FL	*360.00 FL
11	1		*BONNET	Dented	665.00 FL	*665.00 FL
12	1		*BONNET MOULDING	Cut	205.00 FL	*205.00 FL
13	1		*BONNET LOGO	Necessary	60.00 FL	*60.00 FL
14	1		*BONNET LOCK	Damaged	90.00 FL	*90.00 FL
15	1		*BONNET LOCK CABLE	Not Necessary	85.00 FL	*- FL
16	2		*BONNET STOPPER	Not Necessary	40.00 FL	*- FL
17	2		*BONNET HINGE	Not Necessary	60.00 FL	*- FL
18	1		*BONNET INSULATOR	Not Necessary	245.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Buckled	890.00 FL	*890.00 FL
20	1		*FRONT BRACE PANEL	Bent	90.00 FL	*90.00 FL
21	2		*HORN	Not Necessary	170.00 FL	*- FL
22	1		*TEMPERATURE SENSOR	Not Necessary	160.00 FL	*- FL
23	2		*AIR GUARD GARNISH	Not Necessary	240.00 FL	*- FL
24	1		*AIRCON CONDENSOR	Dented	1,600.00 FL	*1,425.00 FL
25	1		*RADIATOR SUPPORT PANEL	Repeated	985.00 FL	*- FL
26	1		*RADIATOR	Cracked	1,810.00 FL	*1,543.00 FL
27	4		*RADIATOR MOUNTING	Not Necessary	168.00 FL	*- FL
28	2		*RADIATOR BRACKET	Not Necessary	182.00 FL	*- FL
29	1		*RADIATOR FAN COWLING	Not Necessary	260.00 FL	*- FL
30	1		*TAILGATE	Dented	1,280.00 FL	*1,280.00 FL
31	1		*TAILGATE OUTER MOULDING	Cracked	240.00 FL	*240.00 FL
32	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
33	1		*TAILGATE INNER LOCK	Damaged	445.10 FL	*445.10 FL
34	1		*TAILGATE LOWER LOCK	Not Necessary	35.00 FL	*- FL
35	2		*TAILGATE DAMPER	Not Necessary	388.00 FL	*- FL
36	2		*TAILGATE STOPPER	Not Necessary	40.00 FL	*- FL
37	1		*TAILGATE WEATHERSTRIP	Cut	320.00 FL	*320.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*TAILGATE INNER TRIM (LOWER)	Cracked	395.00 FL	*395.00 FL
39	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
40	1		*REAR BUMPER	Distorted	590.00 FL	*590.00 FL
41	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
42	2		*REAR BUMPER BRACKET	Dented	140.20 FL	*140.20 FL
43	2		*REAR BUMPER SIDE RETAINER	Necessary	120.00 FL	*120.00 FL
44	2		*TAILLAMP C/W BRACKET	Cracked	1,040.00 FL	*818.00 FL
45	2		*REAR FENDER INNER COWLING	Not Necessary	760.00 FL	*- FL
46	2		*REAR FENDER INNER TRIM	Cracked	1,476.20 FL	*1,381.00 FL
47	1		*REAR END PANEL	Dented	480.00 FL	*480.00 FL
48	1		*REAR END PANEL TOP GARNISH	Cracked	245.00 FL	*245.00 FL
49	2		*REAR END PANEL (EXTEND)	Dented	597.40 FL	*597.40 FL
50	1		*REAR END PANEL BOTTOM (CENTRE)	Repair	311.10 FL	*- FL
51	1		*REAR FLOOR PANEL	Repair	1,150.00 FL	*- FL
52	1		*REAR TOP BOARD INNER SUPPORT	Not Necessary	585.00 FL	*- FL
53	1		*REAR FLOOR TOP BOARD (CENTER)	Deformed	395.00 FL	*395.00 FL
54	2		*REAR FLOOR TOP BOARD (SIDE)	Not Necessary	280.00 FL	*- FL
55	1		*SPARE TYRE CHAIN	Not Necessary	350.00 FL	*- FL
56	1		*REAR EXHAUST PIPE	Not Necessary	980.00 FL	*- FL
57	5		*REAR EXHAUST MOUNTING	Not Necessary	225.00 FL	*- FL
58	1		*REAR EXHAUST INSULATOR	Not Necessary	160.00 FL	*- FL
59	1		*REAR CHASSIS MEMBER LH	Repair	1,450.00 FL	*- FL
60	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
61	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
62	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
63	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
64	1		*SET BONNET INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
65	1		*SET CENTRE GRILLE CLIP	Necessary	40.00 FS	*10.00 FS
66	1		*RADIATOR SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
67	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
68	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
69	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
70	1		*REAR BUMPER REFLEC STICKER	Necessary	60.00 FS	*20.00 FS
71	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
72	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	80.00 FS	*30.00 FS
73	1		*TAILGATE EMBLEM AERO TOURER (SPECIAL TYRE)	Necessary	120.00 FS	*60.00 FS
74	1		*TAILGATE EMBLEM BORNEO	Necessary	80.00 FS	*50.00 FS
75	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
76	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
77	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*40.00 FS
78	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*60.00 FS
79	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
80	1		*REAR FENDER INNER TRIM LED LIGHT (SPECIAL TYRE)	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
81	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
82	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
83	1		*REAR END PANEL (EXTEND) SEALANT	Not Necessary	80.00 FS	*- FS
84	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
85	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
				Sub Total (\$\$)		
				30,086.00		
				16,929.70		
				- List Item Discount on L Items 25.00/25.00% (\$\$)		
				6,779.00		
				4,042.43		
				Total Parts (\$\$)		
				23,307.00		
				12,887.27		

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	1,000.00
7	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
8	TUFF COAT	New	250.00	60.00
9	WIRING AND BULB CHECK	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REAR CHASSIS ALIGNMENT	New	250.00	0.00
13	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
14	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
15	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
16	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
17	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	100.00	0.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			8,370.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >