



## SMRT Accident Vehicle Repair Estimates

542.55 +  
38.92 +  
670.8 +  
58.77 =  
1,311.04 \*

1,311.04 x  
80 %  
1,048.832 \*

0 \* C

350 \* +  
0 =  
350 \* \*

0 \* C

200 \* +  
200 \* +  
80 \* =  
480 \* \*

0 \* C

60 \* +  
20 \* +  
40 \* +  
20 \* +  
40 \* +

296.88 +  
=  
476.88 \*

0 \* C

~~1,048.83 +  
350 \* +  
480 \* +  
296.88 =  
2,175.71 \*~~



0 \* C

1,048.83 +  
350 \* +  
480 \* +  
476.88 =  
2,355.71 \*

450 \$2,350

| Section A - Accident Details       |                           |  |
|------------------------------------|---------------------------|--|
| Registration Number                | SHF475L                   |  |
| Case Reference Number              | TAX/11/19/2144            |  |
| Registration Date                  | 30/9/2014                 |  |
| Company Type                       | SMRT Taxis Pte Ltd        |  |
| Make                               | TOYOTA                    |  |
| Model                              | PRIUS                     |  |
| Name of Driver                     | SIVASANKAR S/O MANOHARAN  |  |
| Type of Accident                   | Side Swipe                |  |
| Accident Date and Time             | 30/11/2019 6:45 PM        |  |
| Accident Reported Date and Time    | 5/12/2019 10:01 AM        |  |
| Is Surveyor Required?              | Yes                       |  |
| Survey by                          |                           |  |
| Vehicle is Towed Back?             | Yes                       |  |
| Towed Back Date and Time           | 30/11/2019 7:27 PM        |  |
| Replacement Vehicle Issued?        | No                        |  |
| Job Card Number                    | 24104705                  |  |
| Special Instruction to ARC, if any | TOWED \$540 / CHINA - LKK |  |
| Prepared Date and Time             | 5/12/2019 8:22 PM         |  |
| Chassis Number                     |                           |  |
| Mileage                            |                           |  |
| Work Shop                          |                           |  |
| Repair Completion Date and Time    |                           |  |

| Section B - Summary of Repair Estimates |   |   |
|---|---|---|
| Summary of Repair Estimates             |   |   |
|   | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost                       | \$507.00  | \$350.00  |
| Total Spray Cost                        | \$1,494.00  | \$480.00  |
| Total Spare Part Cost                   | \$4,364.38  | \$1,048.84  |
| Total Other Cost                        | \$832.88  | \$476.88  |
| TOTAL COST                              | \$7,298.26  | \$2,355.72  |
| Lump Sum Total                          | \$7,300.00  | \$2,350.00  |
| Number of Repair Days                   | 5.0   | 3.0   |
| Prepared / Adjusted By                  | Ang Bang Kien   | Sun Pin (LKK) / China Tai ping  |
| ARC / Surveyor Sign Off Date            | 06/12/2019 2:17 PM  | 06/12/2019 11:55 AM   |
| Signature                               |  |  |
| Remarks                                 | Lump Sum repair, Take after spray photo.  |   |