


Section A - Accident Details	
Registration Number	SHF475L
Case Reference Number	TAX/11/19/2144
Registration Date	30/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SIVASANKAR S/O MANOHARAN
Type of Accident	Side Swipe
Accident Date and Time	30/11/2019 6:45 PM
Accident Reported Date and Time	5/12/2019 10:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/11/2019 7:27 PM
Replacement Vehicle issued?	No
Job Card Number	24104705
Special Instruction to ARC, if any	TOWED \$540 /CHINA - LKK
Prepared Date and Time	5/12/2019 8:22 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

L/S = 2,350

3 days

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$350.00
Total Spray Cost	\$1,494.00	\$480.00
Total Spare Part Cost	\$4,364.38	\$1,048.84
Total Other Cost	\$932.88	\$476.88
TOTAL COST	\$7,298.26	\$2,355.72
Lump Sum Total	\$7,300.00	\$2,350.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Tai Ping
ARC / Surveyor Sign Off Date	06/12/2019 2:17 PM	06/12/2019 11:55 AM
Signature		
Remarks	Lump Sum repair, Take after spray photo.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0337	Invoice Number	
Quotation Date	22.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$507.00	\$350.00
Total Labour	\$507.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$1,494.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$932.88	\$476.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	0.00	\$482.00	0.00	\$0.00	Replace	Not Given X
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given X
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52118-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Check X
		42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given Y
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757105
FAX Number : 63885592
Estimate Telephone Number : 66662823
Accident Reporting Number : 68662672

Data Generated : 22/11/2018
User ID : PehSuan

75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X
43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$870.80	Replace	Replace	
	STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X
68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X
68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
75710-47021	DOOR BELT FRT/RH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given	X
87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Check	X
81730-52090	MIRROR LAMP RH	1.00	\$65.30	10.00	\$58.77	Replace	Replace	
879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	
Total			\$7,184.15		\$1,311.05			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1311.05

- 20%

1048.84

+ 350.00

+ 956.88

2355.72

L/S \$2350/-

3 days

L/S = 2350



Case Details

Case Reference Number :

TAX/11/19/2144

Type of Repair : Accident Repair

Vehicle Registration Number : SHF475L

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9627-ID

Assigned By : Tax Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 30/11/2019 10:45 AM

Vehicle Age(In Months) : 62

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Parts Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	361.50	25.00	361.50	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	* / PD
One Time Key In	Main			NAME PLATE (HYBRID)	1	81.90	81.90	25.00	38.92	Replace	1	38.92	Replace	* / Nec
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Check	* X SVC
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	* X SVC

Total Spare Part Cost 5,455.48

Surveyor Total 1,311.04

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,364.38

Final Sur Total 1,048.83

12/6/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

SMRT Recommendation											Surveyor Approval			
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	506.20	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			WHEEL HUB FRT	1	548.70	548.70	25.00	412.28	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			DOOR FRT/RH	1	694.40	694.40	25.00	520.80	Replace	1	670.80	Replace	/ PP
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			HINGE LOWER RHF, DOOR	1	60.10	60.10	25.00	45.08	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			HINGE UPPER RHF, DOOR	1	60.50	60.50	25.00	45.38	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			DOOR BELT FRT/RH	1	69.20	69.20	25.00	51.90	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.33	Replace	0	0	Check	X SVC
One Time Key In	Main			MIRROR LAMP RH	1	66.30	66.30	10.00	59.67	Replace	1	66.77	Replace	/ SCH
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	0	Repair	X R

Total Spare Part Cost 5,455.48

Surveyor Total 1,311.04

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,364.38

Final Sur Total 1,048.83

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			507.00	350.00	/

<https://vacswb.smrt.com.sg/Estimation.aspx>

12/6/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	350	/
Total:			507.00	350.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	0	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	/
3	Main	TO RESPRAY FRONT DOOR RH	378.00	200	/
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
5	Main	RESPRAY MIRROR COVER RH	180.00	80	/
Total:			1,494.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	80	/
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	/
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	/
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
6	Main	TO WASH AND VACUUM	80.00	0	
7	Main	TOWING CHARGE	56.00	0	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	X SVC
Total:			1,229.76	733.76	

476.88

<https://vacswb.smrt.com.sg/Estimation.aspx>

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,364.38	1,048.83
Total Labour Cost	507.00	350.00
Total Spray Painting	1,494.00	480.00
Other	1,229.78	733.78
Overall Total	7,595.14	2,612.59
Lump Sum Repair Option		✓
Lump Sum Total	8,800.00	2,800.00
Surveyor Approved Amount		2,800.00
No of Repair Days*	5	3
Remarks		Lump Sum repair, Take after spray photo.
Surveyor Name		Sun Pin (LKK)
Signature		

Save Clear

Survey Date

06/12/2019

Repair day - 3 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: