

Trans-cab Auto Services Pte Ltd**AAD1912-033**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

Vehicle No.:

SHC 5830C

Chassis No.:

VF1ABL15AUC282211

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

4.12.19

Third Party Insurer :

AIG

Date of Registration:

3/8/2015

	PART		LIST
1	DOOR PANEL REAR LH X Repair ✓ BUC	\$	758.70 ✓
1	DOOR GUIDE REAR LH X	\$	136.40
1	DOOR HINGE UPPER LH L70Y X } NN	\$	180.70
1	DOOR HINGE LOWER L70Y X	\$	169.90
1	DOOR CHECK REAR LH X	\$	114.90
1	DOOR SEAL REAR LH / TN	\$	119.40 ✓
1	DOOR WAIST SEAL OUTER REAR LH X	\$	169.60
1	DOOR GLASS RUNNER SEAL REAR LH X } NN	\$	116.10
1	DOOR WHEATHERSTRIP REAR LH X	\$	240.50
1	DOOR PANEL FRT LH / BUC	\$	2,844.66 ✓
1	DOOR REGULATOR FRT LH X	\$	758.10
1	DOOR REGULATOR MOTOR FRT LH X } NN	\$	501.40
1	DOOR REGULATOR GUIDE FRT LH X	\$	69.00
1	DOOR HANDLE OUTER FRONT LH X Repair	\$	169.50
1	DOOR HANDLE CAP FRONT LH X	\$	17.30
1	DOOR LOCK FRT LH X	\$	453.80
1	DOOR SEAL FRONT LH X	\$	69.60
1	DOOR SEAL LOWER FRONT LH X	\$	93.90
1	DOOR WHEATHESTRIP FRONT LH X } NN	\$	316.00
1	DOOR GLASS RUNNER SEAL FRONT LH X	\$	332.00
1	DOOR WAIST SEAL OUTER FRONT LH X	\$	92.20
1	DOOR MOULDING FRONT LH X	\$	100.50
1	DOOR MIRROR ASSY LH X	\$	727.90
1	DOOR HARNESS WIRE LH X	\$	2,670.00
1	ROCKER PANEL INNER GARNISH LH X	\$	466.51
1	ROCKER PANEL INNER LH X } Repair	\$	1,024.79
1	ROCKER PANEL OUTER LH X	\$	1,184.99

Trans-cab Auto Services Pte Ltd**AAD1912-033**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

1 ROCKER PANEL CENTER LH *x repair* \$ 990.25

TOTAL \$ 14,888.60

10% \$ 1,488.86

\$ 13,399.74

*3722.76**3350.48***Special Nett**

1 DOOR CHECK BOLT *X* \$ 22.69

1 DOOR GUIDE SCREW *X* \$ 10.85

1 DOOR HINGE BOLT *X* \$ 10.85

1 DOOR HINGE NUT LH *X* \$ 14.60

1 DOOR CHECK BOLT *X* \$ 22.69

1 DOOR CHECK NUT *X* \$ 3.75

1 DOOR LOCK SCREW L70Y *X* \$ 6.12

1 FRONT LEFT TYRE *X* \$ 300.00

1 FRONT LEFT TYRE RIM *X* \$ 380.00

1 FRONT DOOR STICKER "Trans-Cab" */* \$ 80.00 */*

1 FRONT DOOR STICKER "Classic" */* \$ 80.00 */*

1 REAR DOOR STICKER "6555-3333" */* \$ 80.00 */*

TOTAL \$ 1,011.57

TOTAL PARTS \$ 14,411.31

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00

500

Putty and spray painting of the affected portion.

\$ 6,000.00

600

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00

60

To check steering geometry and computer wheel alignment

\$ 220.00

X nn

Trans-cab Auto Services Pte Ltd**AAD1912-033**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00	

TOTAL \$ 13,830.00**Over All Total \$ 28,241.31****LUMP SUM (REPAIR DAY)****20 DAYS**

4 Days

lump sum repair.

After repair photos.

Guo Q: up - 82880282

06/12/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**