Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021651/UKA3Q2

Date: 12/08/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100397739-05 Claimant **SKR6636B** 

Insured Vehicle No: SKQ8497C Vehicle No:

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 9607679786SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKR6636B** Reg No:

Make & Model: FORD FOCUS RS, 2.3 (A) Engine No: GR75916

Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: WF05XXGCC5GR75916

Colour: Odometer: 36909 km Grey

**Engine Capacity:** 2261 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 235/35Z R19 Rear Tyre Size: 235/35Z R19 Michelin 6 mm Front Left Side: Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,821.00	6,901.20	5,919.80	46.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,000.00	660.00	39.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,481.00	7,901.20	6,579.80	45.44
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	14,481.00	6,300.00	8,181.00	56.49
+ GST 7.00/7.00% (S\$)	1,013.67	441.00	572.67	56.49
Nett Amount (S\$)	15,494.67	6,741.00	8,753.67	56.49
+ Loss of Use (2.0 x S\$6	60.00/day) (S\$)	120.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	6,863.00		

**INSPECTION** 

Date of Assignment: 09/12/2019

Date Inspected: 09/12/2019 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER SPORT	Dented /Torn	2,850.00 F	*2,820.00 FL	
2	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	210.00 F	*- FL	
3	1		*REAR BUMPER BEAM	Bent	699.00 F	*695.00 FL	
4	1		*REAR BUMPER TOP RETAINER	Not Necessary	265.00 F	*- FL	
5	1		*REAR END PANEL	Repair	1,018.00 F	*- FL	
6	1		*REAR EXHAUST HEAT SHIELD	Bent	299.00 F	*299.00 FL	
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS	
8	1		*REAR BUMPER LOWER CARBON FIBRE LIP (RS)	Cracked	3,800.00 FS	*2,800.00 FS	
9	1		*REAR EXHAUST END PIPE N/S	Serviceable	250.00 FS	*-FS	
10	1		*SET REAR BUMPER PLASTIC COATING	Necessary	800.00 FS	*800.00 FS	
11	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS	
12	1		*REAR EXHAUST MUFFLER	Serviceable	2,200.00 FS	*-FS	
F=Fra	ınchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	12,821.00	7,664.00	
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	762.80	
				Total Parts (S\$)	12,821.00	6,901.20	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACING REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
5	TO SPRAY RUST PROOFING	New	50.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	580.00	450.00
7	TO PUTTY & SPRAY PAINTING	New	680.00	420.00
	Gross Labou	r Cost (S\$)	1,660.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >