

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 10 Dec 2019

Preliminary Advice

Vehicle No	: SLX1805U	Accident Date	: 09/12/2019
Make	: AUDI R8	Policy No.	: 29076466MPQ
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: -
Inspection At	: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear engine compartment burnt from fire and parts claimed are consistent to the accident. Front left headlamp and bonnet damaged due to previous collision incident with another vehicle.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	37,389.00
Salvage Value	:S\$	
Margin for Repair	:S\$	137,611.00

Remarks

(X) The vehicle is not economical for repair. Vehicle recommended total loss.

() The above survey was conducted on a 'without prejudice' basis.