

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22112

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1449/2019/NS
Date : 7-Dec-19

Vehicle IN Workshop. Kindly Arrange For Survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Adrian Ling
09/12/19.
Not Authorised, 12 Days.

Owner's Name : Dr Cheong Hui Ting Elizabeth (Zhang Huiting)
Address : 260A Lorong Chuan
Singapore 556757
Telephone : HP +65 96881203
Type of Claim : Own Damage Claims
Policy No. : 1800086489-01
Vehicle No : **SME 130 C**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-18
Engine No : CHZ 468675
Chassis No : WAUZZZ8V8J1070243
Mileage : 13538
Date In : 7-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Dec-19
Place of Accident : PIE Towards Changi Airport

LKM Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To survey damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 130 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$ 600.00 ✓	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
5	To dismantle rear bumper and rear lid. Cut out and weld lhs rear fender and tail lamp panel. Renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 6,400.00 3000. ✓	
SUB TOTAL LABOUR CHARGES		: \$ 10,080.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 130 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To install rear windscreen solar film.	\$ 400.00	✓
7	To respray rear bumper, lhs rear fender, lhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,200.00	2200 ✓
8	To dismantle lhs rear suspension assy. Inspect for damages and renew accordingly.	S/N \$ 1,200.00	X X
9	To renew lhs rear rim and tyre. Carry out wheel alignment.	S/N \$ 280.00	✓ ✓
10	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 16,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
1	REAR BUMPER <i>incl</i>	\$	1,793.00	✓ 1434.40
2	REAR BUMPER GUIDE SECTION - LH <i>incl</i>	\$	15.00	✓ 11.44
3	REAR BUMPER LOCKING MECHANISM <i>Not Nec</i>	2 \$	53.00	X
4	REAR BUMPER SPOILER - LH <i>nt</i>	\$	216.00	✓ 172.80
5	REAR LIGHT REFLECTOR - RH <i>incl</i>	\$	38.00	✓ 29.68
6	REAR BUMPER GUIDE SECTION - LH <i>incl</i>	\$	60.00	✓ 47.84
7	REAR BUMPER SIDE REINFORCEMENT BEAM <i>Not Nec</i>	\$	522.00	X
8	REAR PARKING AID SENSOR - INNER / OUTER <i>Not Nec</i>	2 \$	462.00	X
9	SIDE PANEL - LH <i>Distorted.</i>	\$	2,110.00	✓ 1687
10	REAR CONNECTING PLATE - LH <i>Distorted.</i>	\$	89.00	✓ 70.82
11	VENT TRIM <i>incl</i>	\$	64.00	✓ 50.64
12	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Nec</i>	\$	81.00	X
13	REAR BUMPER ADAPTER - LH <i>Not Nec</i>	\$	34.00	X
14	LED TAIL LIGHT - LH <i>Not Nec</i>	\$	800.00	X
15	SIDE WINDOW - LH <i>Not Nec</i>	\$	520.00	✓ 415.60
16	REAR WINDSCREEN <i>Not Nec</i>	\$	742.00	✓ 593.20
17	PRIMER <i>Not Nec</i>	2 \$	38.00	✓ 14.88
18	REAR ALUMINIUM RIM - LH <i>nt</i>	\$	666.00	✓ 532.40
19	WHEEL BEARING <i>Not Nec</i>	\$	452.00	X
20	TYRE <i>Not Nec</i>		TBC	X

SUB TOTAL SPARE PARTS

: \$ 8,755.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	STUB AXLE <i>ne ne</i>	\$ 262.00	✓ X
22	ACRYLIC SEALANT ?	S/N \$ 180.00	✓ ✓ 180
23	CAVITY WAX <i>ne</i>	S/N \$ 140.00	✓ 140
24	STONE CHIP	S/N \$ 180.00	✓ 180
25	REAR WINDSCREEN SEALANT ?	S/N \$ 200.00	✓ 200
26	1/4 GLASS SEALANT <i>ne</i>	S/N \$ 100.00	✓ 100
27	METAL FILLER POWDER	S/N \$ 280.00	✓ 280
28	SUNDRIES <i>Nec.</i>	\$ 600.00	? ✓ 1296

TOTAL SPARE PARTS	:	\$ 10,697.00
TOTAL LABOUR CHARGES	:	\$ 16,352.00
GRAND TOTAL	:	\$ 27,049.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.