

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22015

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1445/2019/NS
Date : 6-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lincoln Peh Zhengliang (Bai Zhengliang)
Address : 2A Upper Boon Keng Road
#21-696
Singapore 381002
Telephone : (HP) +65 98186528
Type of Claim : Own Damage Claims
Policy No. : 1800034659
Vehicle No : **SLX 9508 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 18/4/2018
Engine No : CHZ 905889
Chassis No : WAUZZZ8V7J1056589
Mileage : 25776
Date In : 6-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Dec-19
Place of Accident : Slip Road Leading Into PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 9508 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To renew and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
3	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	2750 2500
4	To respray front bumper, bonnet, hinges and both front fenders. ✓	\$ 4,000.00	1950 3x550 = 1650 Hinge x2: 150 x 2 = 300
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 12,052.00	1950.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>del</i>	\$	1,830.00	✓
2	FRONT BUMPER FIXING PARTS ?	\$	170.00	?
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>neu</i>	2 \$	70.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>del</i>	\$	146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$	488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2 \$	540.00	?
7	FRONT BUMPER COVER TRIM - LH / RH ?	2 \$	296.00	?
8	FRONT BUMPER ADAPTER - LH / RH ?	2 \$	68.00	?
9	RADIATOR GRILLE <i>del</i>	\$	1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$	174.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>del</i>	2 \$	342.00	171
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$	660.00	?
13	FRONT BUMPER FOAM FILLER PIECE ?	\$	172.00	?
14	FRONT BUMPER FOAM FILLER PIECE COVER ?	\$	111.00	?
15	SIGNAL HORN - LH HIGH TONE ?	\$	182.00	?
16	SIGNAL HORN - RH LOW TONE ?	\$	182.00	?
17	FRONT FENDER - LH / RH <i>By 5 RH</i>	2 \$	1,556.00	+
18	FRONT FENDER ATTACHMENT PARTS ?	\$	65.00	+
19	FRONT FENDER BRACKET - LH / RH <i>del</i>	2 \$	70.00	+
20	FRONT FENDER BRACE - LH / RH <i>del</i>	2 \$	176.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,599.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 316.00	✓
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 81.00	+
23	BONNET <i>Dented</i>		\$ 2,898.00	✓
24	BONNET ATTACHMENT PARTS		\$ 149.00	?
25	BONNET LID HINGE - LH / RH <i>Bent</i>	2	\$ 112.00	✓
26	BONNET GAS FILLED STRUT <i>new</i>		\$ 109.00	+
27	BONNET CATCH HOOK <i>new</i>		\$ 81.00	+
28	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 200.00	+
29	BONNET EDGE PROTECTION <i>new new</i>		\$ 25.00	✓
30	BONNET CATCH HOOK <i>new</i>		\$ 58.00	X
31	BONNET LID LOCK	2	\$ 367.00	?
32	BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$ 53.00	+
33	BONNET SOUND ABSORBER <i>new</i>		\$ 201.00	+
34	PLENUM CHAMBER COVER <i>new</i>		\$ 164.00	+
35	LED HEADLIGHT - LH / RH <i>RH covered</i>	2	\$ 10,058.00	5029.
36	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 256.00	+
37	HEADLIGHT HOSE <i>new</i>		\$ 61.00	+
38	LOCK CARRIER <i>covered</i>		\$ 663.00	✓
39	READY MIX COOLANT <i>new</i>	4	\$ 84.00	✓
40	RADIATOR AIR GUIDE - LH / RH	2	\$ 44.00	?
SUB TOTAL SPARE PARTS		:	<u>\$ 15,980.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	RADIATOR AIR GUIDE - UPPER CENTRE <i>Me n</i>	\$ 11.00	+
42	AIR INTAKE AIR GUIDE <i>Me n</i>	\$ 53.00	+
43	AIR INTAKE WATER DRAINAGE HOSE <i>Me n</i>	\$ 31.00	+
44	AIR INTAKE AIR GUIDE	\$ 62.00	+
45	AIR INTAKE SEAL	\$ 13.00	+
46	AIR INTAKE AIR FILTER <i>Me n</i>	\$ 252.00	+
47	AIR INTAKE MANIFOLD	\$ 129.00	+
48	AIRCON STICKER <i>Me</i>	NEC \$ 7.00	—
49	CAUTION SIGN STICKER	NEC \$ 13.00	—
50	FRONT NO PLATE <i>Bert</i>	S/N \$ 40.00	✓
51	SUNDRIES ?	\$ 400.00	?

TOTAL SPARE PARTS : **\$ 25,590.00**

TOTAL LABOUR CHARGES : **\$ 12,052.00**

GRAND TOTAL : **\$ 37,642.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lj

Surveyed Date

:

09/12/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorized, 08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant