

CC3/A141A021688/Axd3n2

Merimen

ASSIGNMENT

Vehicle Type

① TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle for:

at Workshop only

if

Insured

Policy No

1800034659

Claims No.

Sum Insured

Excess

600

(Client's Record)

Make of Vehicle

(Policy Condition)

Remark: The veh has commenced its repair at the time of inspection.

Est. or Market Value

901K.

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

8/8

days

Fee

Yes or No

Use Surt

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Veh No

SLX9508A.

Date

2018 April

Type

① MCycl / Bus / Van / Lorry / Trail / Prime Mover /

Truck / Trailer or

Make

Audi A3

999

Colour

Blue.

At

Insured / Std / NI / NA

Sp. Reading

25776.

Traffic

Insured / Std / NI / NA

Eng No

Ch No

W4U222EV7J1056589.

Gen. Cond. Good / Fair / Poor / Burnt

Steering. Incl. Jer / Jammed / Leaked / Burnt

Brake. Incl. Jer / Jammed / Leaked / Burnt

Mod. Nil / ① Rim / STD A/Rim or

Tyre Size

F:

205/55R16.

R:

205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / ① MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A.

6/12/19

D.O.A.

06/12/19

Survey held at

Premium.

Des. of Damages ① Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ODAC.

SLX9508A-X

RECEIVED 12 MAR 2020

10/12/19

Revert via merimen

12/12/19

Rate approved \$22,036 from Andy by merimen

13/12/19

Inform Tony c/A ex 600 by email

21/12/20 final fig \$17,263.52 (Real 20,439.48, 5490) confirmed by email

Date/Time For Report

☐

: Prel. Report

Days Of Repair:

8

If

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time For Report

Survey Fee:

Transaction

200

11

12/3 - typist

Add'l Fee:

☐

Late typist

☐

Late typist

☐

Late typist

☐

Late typist

merimen

P/P \$17,263.52

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:		Date:	10 Dec 2019

Preliminary Advice

Vehicle No	: SLX9508A	Accident Date	: 06/12/2019
Make	: AUDI A3	Policy No.	: 1800034659
Assignment Date	: 10/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,642.00
Revised Amount	:S\$	18,771.00
Check Items (Estimated)	:S\$	3,515.00
Total	:S\$	22,286.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	50,852.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,148.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chan, Yoke Shi	Date: 12 Dec 2019

Preliminary Advice

Vehicle No	: SLX9508A	Accident Date	: 06/12/2019
Make	: AUDI A3	Policy No.	: 1800034659
Assignment Date	: 10/12/2019	Excess	: S\$600.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,642.00
Revised Amount	:S\$	18,521.00
Check Items (Estimated)	:S\$	3,515.00
Total	:S\$	22,036.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	50,852.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,148.00

Remarks

☒ (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ () Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 13 December 2019 8:23 AM
To: 'Claims Dept'; SUR; 'nora.khai@premiumauto.com.sg'
Cc: 'boojohnny@gmail.com'
Subject: RE: OD CLAIM FOR SLX 9508 A ON 6/12/2019
Attachments: MARK_ESTIMATE_(NEW).pdf

Dear Tony,

As instructed by our client , please proceed to repair the **insured vehicle SLX 9508A, (Excess S600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

NOTE: All awarded parts and labour to be justified with clear photos.

AIG OIC- yokeshi.chan@aig.com

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 December 2019 3:09 PM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; nora.khai@premiumauto.com.sg
Cc: boojohnny@gmail.com
Subject: RE: OD CLAIM FOR SLX 9508 A ON 6/12/2019

Dear Tony,

Still pending AIG approval.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 12 December 2019 2:19 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; nora.khai@premiumauto.com.sg
Cc: boojohnny@gmail.com; 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SLX 9508 A ON 6/12/2019

Dear Veron,

Kindly assist follow up on repair approval. This vehicle at our workshop since last week Friday.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Singapore 408699
p. +65 6366 2323, d. +65 67689911
e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 12 December 2019 9:24 AM
To: Claims; SUR; (nora.khai@premiumauto.com.sg)
Cc: (boojohnny@gmail.com)
Subject: RE: OD CLAIM FOR SLX 9508 A ON 6/12/2019

Dear Nora,

As spoken.

AIG Maintained:Main Labour NOT APPROVE.

Attach surveyor's marking, kindly advised.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 6 December 2019 2:31 PM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SLX 9508 A ON 6/12/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Vehicle is in our compound.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SLX9508A (9916563613SG)**

OD

Dec 6 2019 12:30PM

[LINCOLN PEH ZHENGLIANG(BAI ZHENGLIANG)]
Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/12/2019 20:28 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$22036.00) - SLX9508A - Claim Handler: Chan, Yoke Shi

Approved:22036.00:Please commence repairs. All awarded parts and labour to be justified with clear photos.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Sent: Thursday, 12 December 2019 8:31 PM
To: Chang, Lois-KL; Veron Chen (LKKAUTO)
Cc: Lim, Kok-Chong; Koh, Victor-CK
Subject: RE: SLX 9508A-DOA: 6/12/2019 (AIG REF: 9916563613SG)

Veron, Mandate set to commence repairs in Merimen.

Please inform surveyor that this claim will be marked in our performance tracking record and will be raised for clarification in the coming LKK-Premium Automobiles quarterly performance review.

Andy

From: Chang, Lois-KL
Sent: Thursday, December 12, 2019 3:43 PM
To: Veron Chen (LKKAUTO)
Cc: Fong, Andy-SY; Lim, Kok-Chong; Koh, Victor-CK
Subject: RE: SLX 9508A-DOA: 6/12/2019 (AIG REF: 9916563613SG)

Hi Veron,

Kindly refer the breakdown on below. Our acceptable range of labour time shall not exceed 24 working hour. Kindly proceed negotiate within the time range.

Meanwhile, kindly quantify your assessment time basis. IF repairer disagree, kindly request AUDI factory repair guide and repair time for us to review. Thanks

AUDI A3 (8VM)

AUDI AG time

MET/BODY = *8 hour job on non structural panel/parts replacement included on below.

- Renew front bumper cover
- Renew headlight
- Renew hood
- Renew lock carrier

NOTE: REPAIRER Separate labour time on below

1. Remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer.
2. Renew and reinstall aircon condenser, radiator, and additional radiator, check electrical fans and control unit. Pressurize cooling system. Carry out vacuum and regas.
3. Carry out diagnosis check/test.

Regards,
Lois Chang
AIG

Motor Surveyor
Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, December 12, 2019 3:08 PM
To: Chang, Lois-KL <Lois-KL.Chang@aig.com>
Subject: [EXTERNAL] SLX 9508A-DOA: 6/12/2019 (AIG REF: 9916563613SG)

Dear Mr Chang,

We refer to the above mentioned.

Maintained: Main Labour NOT APPROVE, Kindly negotiate and re-seek mandate.

Please advised your suggested repair labour.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Chang, Lois-KL <Lois-KL.Chang@aig.com>
Sent: Thursday, 12 December 2019 3:43 PM
To: Veron Chen (LKKAUTO)
Cc: Fong, Andy-SY; Lim, Kok-Chong; Koh, Victor-CK
Subject: RE: SLX 9508A-DOA: 6/12/2019 (AIG REF: 9916563613SG)

Hi Veron,

Kindly refer the breakdown on below. Our acceptable range of labour time shall not exceed 24 working hour. Kindly proceed negotiate within the time range.

Meanwhile, kindly quantify your assessment time basis. IF repairer disagree, kindly request AUDI factory repair guide and repair time for us to review. Thanks

AUDI A3 (8VM)

AUDI AG time

MET/BODY = *8 hour job on non structural panel/parts replacement included on below.

- Renew front bumper cover
- Renew headlight
- Renew hood
- Renew lock carrier

NOTE: REPAIRER Separate labour time on below

1. Remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer.
2. Renew and reinstall aircon condenser, radiator, and additional radiator, check electrical fans and control unit. Pressurize cooling system. Carry out vacuum and regas.
3. Carry out diagnosis check/test.

Regards,
Lois Chang
AIG
Motor Surveyor
Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 3000|Fax +(65) 6835 7416
lois-kl.chang@aig.com|www.AIG.com.sg

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, December 12, 2019 3:08 PM
To: Chang, Lois-KL <Lois-KL.Chang@aig.com>
Subject: [EXTERNAL] SLX 9508A-DOA: 6/12/2019 (AIG REF: 9916563613SG)

Dear Mr Chang,

We refer to the above mentioned.

Maintained:Main Labour NOT APPROVE, Kindly negotiate and re-seek mandate.

Please advised your suggested repair labour.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Dec 2019 14:28	Clim Veh Model Changed		[] Merimen Administrator
2	06 Dec 2019 14:28	Clim Created	Reg No: SLX9508A, Policy No: 1800034659, Acct Date: 2019/12/06, Claim Type: 5 C, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119160974	[I] Merimen Administrator
3	10 Dec 2019 10:21	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] Nivitha Govindasamy
4	10 Dec 2019 10:21	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasamy
5	10 Dec 2019 10:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	10 Dec 2019 10:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/19	[A] Nivitha Govindasamy
7	10 Dec 2019 10:21	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	10 Dec 2019 10:21	Clim Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	10 Dec 2019 10:21	Clim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] Nivitha Govindasamy
10	10 Dec 2019 10:21	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
11	10 Dec 2019 10:51	Adj Rpt Initiated		[A] VERON CHEN
12	10 Dec 2019 10:51	Clim Dtl Modified	JPJ Reg. Date: -> 2018/04/18.	[A] VERON CHEN
13	10 Dec 2019 10:51	Clim Details Notified		[A] VERON CHEN
14	10 Dec 2019 11:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/19	[A] VERON CHEN
15	10 Dec 2019 11:09	Adj Mandate Request	Cur.Req:22286.00:Damages Consistent Repair Cost Economical	[A] VERON CHEN
16	10 Dec 2019 15:12	Clim Registration Modified	Init.Est.->5,000 - 6,000, Excess: -> 600.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Chan, Yoke Shi
17	10 Dec 2019 15:12	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	11 Dec 2019 12:08	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/19. Mandate Remarks: KINDLY stage how many day labour award in main labour??	[I] Chang, Lois-KL
19	11 Dec 2019 12:08	Adj Mandate Set	Maintained:KINDLY stage how many day labour award in main labour??Reinsp:Yes.	[I] Chang, Lois-KL
20	11 Dec 2019 14:58	Adj Mandate Request	Cur.Req:22286.00:Damages Consistent Repair Cost Economical 5.5 days award in main labour.	[A] VERON CHEN
21	11 Dec 2019 15:06	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/12/19. Mandate Remarks: Main Labour NOT APPROVE, Kindly negotiate and re-seek mandate.	[I] Chang, Lois-KL
22	11 Dec 2019 15:06	Adj Mandate Set	Maintained:Main Labour NOT APPROVE, Kindly negotiate and re-seek mandate.	[I] Chang, Lois-KL

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2372199	10 Dec 2019 10:51:41	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLX9508A		11.77

Front Bumper 2 Days
 Bonnet 0.5 Day
 Handup
 Lock Carrier 2.5 Days
5 Days

We have been using this rate to calculate the appropriate labour charges for quite some time already.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 21 February 2020 3:31 PM
To: Carrine Leong; SUR
Cc: 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'; (nora.khai@premiumauto.com.sg)
Subject: RE: FINAL REVISION - SLX9508A - OD AIG - SURVEYED 9 DEC 19

Dear Carrine,

Confirm repair cost of \$17,263.52 before excess \$600 and GST @ 8 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 21 February 2020 2:23 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLX9508A - OD AIG - SURVEYED 9 DEC 19

Dear Adrian / Veron,

Please find attachment reinforcement beam photo for your attention.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak (<mailto:boojohnny@gmail.com>)

Sent: Monday, 3 February, 2020 6:19 PM

To: Adrian Ling <adrianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>;
Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLX9508A - OD AIG - SURVEYED 9 DEC 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$17,263.52 @ 8 days exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	937A
Vehicle Details	
Vehicle No.:	SLX9508A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CHZ905889
Chassis No.:	WAUZZZ8V7J1056589
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,712.00
Original Registration Date:	18 Apr 2018
First Registration Date:	18 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$26,597.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2028
PARF Rebate Amount:	\$19,947.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$30,905.00
Total Rebate Amount:	\$50,852.00

The information contained herein is correct as at 10 Dec 2019

OK

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LINCOLN PEH ZHENGLIANG (BAI ZHENGLIANG)
 Period of Insurance : 18 Apr 2018 To 17 Apr 2020
 Engine No. : CHZ 905889
 Chassis No. : WAUZZZ8V7J1056589

Vehicle No. : SLX9508A
 Policy No. : 1800034659
 Endorsement No. :
 Issued Date : 27 Apr 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 Use only for social, domestic and pleasure purposes and for the Policyholder's business.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LINCOLN PEH ZHENGLIANG (BAI ZHENGLIANG) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MALAYAN BANKING BERHAD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 180), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125256

PREMIUM LEASING -LSYA
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Steffany Lee

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22015

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1445/2019/NS
Date : 6-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lincoln Peh Zhengliang (Bai Zhengliang)
Address : 2A Upper Boon Keng Road
#21-696
Singapore 381002
Telephone : (HP) +65 98186528
Type of Claim : Own Damage Claims
Policy No. : 1800034659
Vehicle No : **SLX 9508 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 18/4/2018
Engine No : CHZ 905889
Chassis No : WAUZZZ8V7J1056589
Mileage : 25776
Date In : 6-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Dec-19
Place of Accident : Slip Road Leading Into PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 9508 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To renew and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	✓
3	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	2750 2500 ✓
4	To respray front bumper, bonnet, hinges and both front fenders.	\$ 4,000.00	1950 3x550 = 1650 Hinge x2: 150 x 2 = 300 1950 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 12,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
1	FRONT BUMPER <i>excl'd</i>		\$	1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>Not Nec</i>		\$	170.00	? X
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	70.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>excl'd</i>		\$	146.00	✓ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$	488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not Nec</i>	2	\$	540.00	? X
7	FRONT BUMPER COVER TRIM - LH / RH <i>excl'd RH</i>	2	\$	296.00	? 118.40
8	FRONT BUMPER ADAPTER - LH / RH <i>Not Nec</i>	2	\$	68.00	? X
9	RADIATOR GRILLE <i>excl'd</i>		\$	1,301.00	✓ 1040.80
10	RADIATOR GRILLE CLOSING ELEMENT <i>excl'd</i>		\$	174.00	? 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>excl'd</i>	2	\$	342.00	171 136.40
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Best</i>		\$	660.00	? 527.60
13	FRONT BUMPER FOAM FILLER PIECE <i>excl'd</i>		\$	172.00	? 137.60
14	FRONT BUMPER FOAM FILLER PIECE COVER <i>excl'd</i>		\$	111.00	? 88.80
15	SIGNAL HORN - LH HIGH TONE <i>Not Nec</i>		\$	182.00	? X
16	SIGNAL HORN - RH LOW TONE <i>Not Nec</i>		\$	182.00	? X
17	FRONT FENDER - LH / RH <i>excl'd RH</i>	2	\$	1,556.00	+
18	FRONT FENDER ATTACHMENT PARTS		\$	65.00	+
19	FRONT FENDER BRACKET - LH / RH <i>excl'd</i>	2	\$	70.00	+
20	FRONT FENDER BRACE - LH / RH <i>excl'd</i>	2	\$	176.00	+
SUB TOTAL SPARE PARTS			:	\$ 8,599.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
21	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	316.00	✓
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	81.00	+
23	BONNET <i>Dented</i>		\$	2,898.00	✓ 2316.40
24	BONNET ATTACHMENT PARTS <i>Not Nec</i>		\$	149.00	? X
25	BONNET LID HINGE - LH / RH <i>Bent</i>	2	\$	112.00	✓ 88.48
26	BONNET GAS FILLED STRUT <i>new</i>		\$	109.00	+
27	BONNET CATCH HOOK <i>new</i>		\$	81.00	+
28	BONNET STRIKER - LH / RH <i>new</i>	2	\$	200.00	+
29	BONNET EDGE PROTECTION <i>new</i>		\$	25.00	✓ 19.92
30	BONNET CATCH HOOK <i>new Bent</i>		\$	58.00	X 45.76
31	BONNET LID LOCK <i>Not Nec</i>	2	\$	367.00	? X
32	BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$	53.00	+
33	BONNET SOUND ABSORBER <i>new</i>		\$	201.00	+
34	PLENUM CHAMBER COVER <i>new</i>		\$	164.00	+
35	LED HEADLIGHT - LH / RH <i>RH cracked</i>	2	\$	10,058.00	5029.40 23-20
36	LIFT CYLINDER - LH / RH <i>new</i>	2	\$	256.00	+
37	HEADLIGHT HOSE <i>new</i>		\$	61.00	+
38	LOCK CARRIER <i>cracked</i>		\$	663.00	✓ 530.40
39	READY MIX COOLANT <i>new</i>	4	\$	84.00	✓ 67.20
40	RADIATOR AIR GUIDE - LH / RH <i>RH Deformed</i>	2	\$	44.00	? 17.12
SUB TOTAL SPARE PARTS			:	\$ 15,980.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	RADIATOR AIR GUIDE - UPPER CENTRE <i>Dem'd</i>	\$ 11.00 +	8.35
42	AIR INTAKE AIR GUIDE <i>OK</i>	\$ 53.00 +	
43	AIR INTAKE WATER DRAINAGE HOSE <i>OK</i>	\$ 31.00 +	
44	AIR INTAKE AIR GUIDE	\$ 62.00 +	
45	AIR INTAKE SEAL	\$ 13.00 +	
46	AIR INTAKE AIR FILTER <i>OK</i>	\$ 252.00 +	
47	AIR INTAKE MANIFOLD	\$ 129.00 +	
48	AIRCON STICKER <i>OK</i>	NEC \$ 7.00 -	5.12
49	CAUTION SIGN STICKER	NEC \$ 13.00 -	9.76
50	FRONT NO PLATE <i>Bert</i>	S/N \$ 40.00 -	40
51	SUNDRIES <i>Not nec.</i>	\$ 400.00 ?	X

TOTAL SPARE PARTS	:	\$ 25,590.00	
TOTAL LABOUR CHARGES	:	\$ 12,052.00	
GRAND TOTAL	:	\$ 37,642.00	37,703

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *09/12/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised , 08 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22015

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1445/2019/NS
Date : 6-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lincoln Peh Zhengliang (Bai Zhengliang)
Address : 2A Upper Boon Keng Road
#21-696
Singapore 381002
Telephone : (HP) +65 98186528
Type of Claim : Own Damage Claims
Policy No. : 1800034659
Vehicle No : **SLX 9508 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 18/4/2018
Engine No : CHZ 905889
Chassis No : WAUZZZ8V7J1056589
Mileage : 25776
Date In : 6-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Dec-19
Place of Accident : Slip Road Leading Into PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 9508 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To renew and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
3	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	2750 2500
4	To respray front bumper, bonnet, hinges and both front fenders.	\$ 4,000.00	1950 3x550 = 1650 Hinge x2: 150x2 = 300
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 12,052.00	1950.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
1	FRONT BUMPER <i>2nd</i>		\$	1,830.00	✓
2	FRONT BUMPER FIXING PARTS ?		\$	170.00	?
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	70.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>		\$	146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$	488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2	\$	540.00	?
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2	\$	296.00	?
8	FRONT BUMPER ADAPTER - LH / RH ?	2	\$	68.00	?
9	RADIATOR GRILLE <i>could</i>		\$	1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ? <i>new</i>		\$	174.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>		\$	342.00	1 TI
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ?		\$	660.00	?
13	FRONT BUMPER FOAM FILLER PIECE <i>new</i>		\$	172.00	?
14	FRONT BUMPER FOAM FILLER PIECE COVER ? <i>new</i>		\$	111.00	?
15	SIGNAL HORN - LH HIGH TONE ?		\$	182.00	?
16	SIGNAL HORN - RH LOW TONE ?		\$	182.00	?
17	FRONT FENDER - LH / RH <i>new</i> RH	2	\$	1,556.00	✓
18	FRONT FENDER ATTACHMENT PARTS ?		\$	65.00	✓
19	FRONT FENDER BRACKET - LH / RH <i>new</i>	2	\$	70.00	✓
20	FRONT FENDER BRACE - LH / RH <i>new</i>	2	\$	176.00	+
SUB TOTAL SPARE PARTS			:	\$ 8,599.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description				Damaged Parts & Prices	
					S/Nett	Remarks
21	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	316.00	✓	
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	81.00	+	
23	BONNET <i>dented</i>		\$	2,898.00	✓	
24	BONNET ATTACHMENT PARTS		\$	149.00	?	
25	BONNET LID HINGE - LH / RH <i>2</i>	2	\$	112.00	✓	
26	BONNET GAS FILLED STRUT <i>new</i>		\$	109.00	+	
27	BONNET CATCH HOOK <i>new</i>		\$	81.00	+	
28	BONNET STRIKER - LH / RH <i>new</i>	2	\$	200.00	+	
29	BONNET EDGE PROTECTION <i>new</i>		\$	25.00	✓	
30	BONNET CATCH HOOK <i>new</i>		\$	58.00	✓	
31	BONNET LID LOCK	2	\$	367.00	?	
32	BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$	53.00	+	
33	BONNET SOUND ABSORBER <i>new</i>		\$	201.00	+	
34	PLENUM CHAMBER COVER <i>new</i>		\$	164.00	+	
35	LED HEADLIGHT - LH / RH <i>2.11 canled</i>	2	\$	10,058.00	5029.	
36	LIFT CYLINDER - LH / RH <i>new</i>	2	\$	256.00	+	
37	HEADLIGHT HOSE <i>new</i>		\$	61.00	+	
38	LOCK CARRIER <i>canled</i>		\$	663.00	✓	
39	READY MIX COOLANT <i>new</i>	4	\$	84.00	✓	
40	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$	44.00	?	
SUB TOTAL SPARE PARTS			:	\$ 15,980.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	RADIATOR AIR GUIDE - UPPER CENTRE <i>ne n OK</i>	\$ 11.00	+
42	AIR INTAKE AIR GUIDE <i>ne n</i>	\$ 53.00	+
43	AIR INTAKE WATER DRAINAGE HOSE <i>ne n</i>	\$ 31.00	+
44	AIR INTAKE AIR GUIDE	\$ 62.00	+
45	AIR INTAKE SEAL	\$ 13.00	+
46	AIR INTAKE AIR FILTER <i>ne n</i>	\$ 252.00	+
47	AIR INTAKE MANIFOLD	\$ 129.00	+
48	AIRCON STICKER <i>ne</i>	NEC \$ 7.00	-
49	CAUTION SIGN STICKER	NEC \$ 13.00	-
50	FRONT NO PLATE <i>Bent</i>	S/N \$ 40.00	✓
51	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 25,590.00	
TOTAL LABOUR CHARGES		: \$ 12,052.00	
GRAND TOTAL		: \$ 37,642.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 09/12/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized , 08 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22015

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1445/2019/NS
Date	:	6-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian
8 days exclude 1 Sunday
jb 3 Feb 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lincoln Peh Zhengliang (Bai Zhengliang)
Address	:	2A Upper Boon Keng Road #21-696 Singapore 381002
Telephone	:	(HP) +65 98186528
Type of Claim	:	Own Damage Claims
Policy No.	:	1800034659
Vehicle No	:	SLX 9508 A
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	18/4/2018
Engine No	:	CHZ 905889
Chassis No	:	WAUZZZ8V7J1056589
Mileage	:	25776
Date In	:	6-Dec-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Dec-19
Place of Accident	:	Slip Road Leading Into PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 9508 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$	360.00	\$ 360.00
2	To renew and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
3	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	6,300.00	\$ 2,500.00
4	To respray front bumper, bonnet, hinges and both front fenders.	\$	4,000.00	\$ 1,950.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,052.00	\$ 6,202.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	\$ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 540.00	
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 296.00	\$ 118.40
8	FRONT BUMPER ADAPTER - LH / RH	2 \$ 68.00	
9	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	\$ 136.40
12	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 660.00	\$ 527.60
13	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	\$ 137.60
14	FRONT BUMPER FOAM FILLER PIECE COVER	\$ 111.00	\$ 88.80
15	SIGNAL HORN - LH HIGH TONE	\$ 182.00	
16	SIGNAL HORN - RH LOW TONE	\$ 182.00	
17	FRONT FENDER - LH / RH	2 \$ 1,556.00	
18	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
19	FRONT FENDER BRACKET - LH / RH	2 \$ 70.00	
20	FRONT FENDER BRACE - LH / RH	2 \$ 176.00	\$ 69.84
SUB TOTAL SPARE PARTS		\$ 8,599.00	\$ 3,838.64

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	c/f	Damaged Parts & Prices		Remarks
			S/Nett		
					\$ 3,838.64
21	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 316.00		
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 81.00		
23	BONNET		\$ 2,898.00	\$ 2,318.40	
24	BONNET ATTACHMENT PARTS		\$ 149.00		
25	BONNET LID HINGE - LH / RH	2	\$ 112.00	\$ 88.48	
26	BONNET GAS FILLED STRUT		\$ 109.00		
27	BONNET CATCH HOOK		\$ 81.00		
28	BONNET STRIKER - LH / RH	2	\$ 200.00		
29	BONNET EDGE PROTECTION		\$ 25.00	\$ 19.92	
30	BONNET CATCH HOOK		\$ 58.00	\$ 45.76	
31	BONNET LID LOCK	2	\$ 367.00		
32	BONNET BOWDEN CABLE - CENTRE		\$ 53.00		
33	BONNET SOUND ABSORBER		\$ 201.00		
34	PLENUM CHAMBER COVER		\$ 164.00		
35	LED HEADLIGHT - LH / RH	2	\$ 10,058.00	\$ 4,023.20	
36	LIFT CYLINDER - LH / RH	2	\$ 256.00		
37	HEADLIGHT HOSE		\$ 61.00		
38	LOCK CARRIER		\$ 663.00	\$ 530.40	
39	READY MIX COOLANT	4	\$ 84.00	\$ 67.20	
40	RADIATOR AIR GUIDE - LH / RH	2	\$ 44.00	\$ 17.12	
SUB TOTAL SPARE PARTS			\$ 15,980.00	\$ 10,949.12	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9508 A

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 10,949.12
41	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 11.00	\$ 8.32
42	AIR INTAKE AIR GUIDE		\$ 53.00	
43	AIR INTAKE WATER DRAINAGE HOSE		\$ 31.00	
44	AIR INTAKE AIR GUIDE		\$ 62.00	
45	AIR INTAKE SEAL		\$ 13.00	
46	AIR INTAKE AIR FILTER		\$ 252.00	
47	AIR INTAKE MANIFOLD		\$ 129.00	
48	AIRCON STICKER	NEC	\$ 7.00	\$ 5.12
49	CAUTION SIGN STICKER	NEC	\$ 13.00	\$ 9.76
50	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
51	Added parts -s ee attached		\$ 61.00	\$ 49.20
52	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 25,651.00	\$ 11,061.52
TOTAL LABOUR CHARGES			\$ 12,052.00	\$ 6,202.00
GRAND TOTAL			\$ 37,703.00	\$ 17,263.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1445/2019/NS 13-Dec-19 Glory Tan 1 of 1 SLX 9508 A Audi A3 Sedan 1.0 TFSI 8V
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight hose RHS	\$ 36.00	\$ 29.84
2	Radiator seal outer RHS	\$ 8.00	\$ 5.68
3	External temperature sensor bracket	\$ 17.00	\$ 13.68
TOTAL		\$ 61.00	\$ 49.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 9508 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1445/2019/NH

9th March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLX 9508 A, Audi A3 SEDAN 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLX 9508 A**, claimant, **Mr. Lincoln Peh Zhengliang**, please find the related document per attached.

1. A copy of the Original invoice no. 85014961 – S\$ 17,829.97.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLX 9508 A

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1445/2019/NS

Date

13-Dec-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLX 9508 A

Model No

Audi A3 Sedan 1.0 TFSI BV

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Headlight hose RHS <i>cut</i>	\$ 36.00	36.00
2	Radiator seal outer RHS <i>ca</i>	\$ 8.00	16.00
3	External temperature sensor bracket <i>ca</i>	\$ 17.00	51.00
TOTAL		\$	61.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:38

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014961	Account: A0006 (T 0)		
		Date : 06/03/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SLX9508A			
		Term : 30			
Regn No: SLX9508A (V 37459)		Regn Date: 18/04/2018	Mileage: 25776	WIP No.: 22015	
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V7J1056589	Engine: CH2 905889	Dept: U	
You have been assisted by :- UB-Tony Foong (33)					
		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	2500.00	1.00	2,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,HINGES AND FRONT FENDER	1950.00	1.00	1,950.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABV5807065R GRU	COVER	Less 020%	1.00	1830.00
X	ABV5807647B 9B9	(SK)GRILLE AP	Less 020%	1.00	145.50
X	ABV5807534A	COVERSTRIP AP	Less 020%	1.00	148.00
X	ABV3853651AA3FZ	GRILLE	Less 020%	1.00	1301.00
X	ABV3853949	PLATE AP	Less 020%	1.00	173.50
X	ABV5807682M 9B9	GRILL	Less 020%	1.00	170.50
X	ABV0807550A	FOAM INSER(LAST) (SH	Less 020%	1.00	172.00
X	ABV0807217A	COVER(LAST) (SHARE) A	Less 020%	1.00	111.00
X	ABV0821136A	SUPPORT(LAST) AP	Less 020%	1.00	87.30

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 6828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:38

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014961 Date: 06/03/2020 Order: SLX9508A Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLX9508A (V 37459)	Regn Date: 16/04/2018	Mileage: 25776	WIP No.: 22015
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7J1056589	Engine: CHE 905889	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A8V5823029A	HOOD Less 020%	1.00	2898.00	2,318.40
X	A8V0823301G	HINGE Less 020%	1.00	55.30	44.24
X	A8V0823302G	HINGE Less 020%	1.00	55.30	44.24
X	A8V0823126B	EDGING Less 020%	1.00	24.90	19.92
X	A8V4823485C	HOOK AP Less 020%	1.00	57.20	45.76
X	A8V0941774D	HEADLIGHT Less 020%	1.00	5029.00	4,023.20
X	A8V0805588A	CARRIER Less 020%	1.00	663.00	530.40
X	AG A13040M2	COOLANT Less 020%	4.00	21.00	67.20
X	A8V0121284K	AIR DUCT AP Less 020%	1.00	21.40	17.12
X	A8V0121230	SEAL AP Less 020%	1.00	7.10	5.68
X	A8V0121285A	AIR DUCT AP Less 020%	1.00	10.40	8.32
X	A8V0010515A	STICKER Less 020%	1.00	6.40	5.12
X	A8K0010520A	STICKER Less 020%	1.00	12.20	9.76
X	A8V4807109E	SEAM (SHARE) AP Less 020%	1.00	659.50	527.60
X	A8V0941718B	007575/(V) (SK) HOSE 1 Less 020%	1.00	37.30	29.84
X	A8V0820536	BRACKET (SHARE) AP Less 020%	1.00	17.10	13.68

Parts 11,021.52
Labour 0.00
Sublet 6,242.00
Menus 0.00
Lubricant 0.00

Sub-Total 16,663.52

7% GST 1,166.45

Grand Total 17,829.97



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX9508A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1445/2019/TF
23 Dec 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V7J1056589
Vehicle Regn No. : **SLX9508A**
Vehicle Mileage : 25776KM
Vehicle Owner : Mr. Lincoln Peh Zhengliang
Certificate No : 1800034659
Own Damage Excess : S 642.00 (Inclusive GST)
Accident Date : 06/12/2019
Place : Slip Road Leading into PIE Changi
Repair Cost : S\$ 17,829.97
WIP No. : 22015
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



26/12/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2019 10:51		10 Dec 2019 10:21 Edit Adj Rpt	S\$17,263.52 Edit Estimates	S\$17,263.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LINCOLN PEH ZHENGLIANG(BAI ZHENGLIANG), ID: S8925937A, Tel: +6598186528, Email: NOEMAIL								
Vehicle Reg. No.:	SLX9508A	Date of Loss:	06/12/2019 12:00 - :59 [19 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 9916563613SG	Policy/Cover Note No.:	1800034659 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/12/2019]								
Driver/Custodian:	LINCOLN PEH ZHENGLIANG(BAI ZHENGLIANG) (30 / Male), NRIC: S8925937A, Tel: +6598186528 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (12/12/2019): Alert - Adj Mandate Approved (S\$22036.00) - SLX9508A - Claim Handler: Chan, Yoke... - AIG_SG (12/12/2019): Alert - Adj Mandate Maintained - SLX9508A - Claim Handler: Chan, Yoke Shi - AIG_SG (11/12/2019): Alert - Adj Mandate Maintained - SLX9508A - Claim Handler: Chan, Yoke Shi - AIG_SG (11/12/2019): Alert - Adj Mandate Maintained - SLX9508A - Claim Handler: Chan, Yoke Shi - AIG_SG (11/12/2019): Alert - Adj Mandate Maintained - SLX9508A - Claim Handler: Chan, Yoke Shi - AIG_SG (10/12/2019): SLX9508A / OD / 06/12/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX9508A (9916563613SG)

OD

Dec 6 2019 12:30PM

[LINCOLN PEH ZHENGLIANG(BAI ZHENGLIANG)]

Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/19 11:06	Adjuster Immediate Advice	 Load HTM	☒
2	12/12/19 09:49	Adjuster Immediate Advice	 Load HTM	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/19 10:52	General View	 Load JPG	☒
2	10/12/19 10:52	General View	 Load JPG	☒
3	10/12/19 10:52	General View	 Load JPG	☒
4	10/12/19 10:52	General View	 Load JPG	☒
5	10/12/19 10:52	General View	 Load JPG	☒
6	10/12/19 10:52	General View	 Load JPG	☒
7	10/12/19 10:52	General View	 Load JPG	☒
8	10/12/19 10:52	General View	 Load JPG	☒
9	10/12/19 10:52	General View	 Load JPG	☒
10	10/12/19 10:52	General View	 Load JPG	☒
11	10/12/19 10:52	General View	 Load JPG	☒
12	10/12/19 10:52	General View	 Load JPG	☒
13	10/12/19 10:52	General View	 Load JPG	☒
14	10/12/19 10:52	General View	 Load JPG	☒
15	10/12/19 10:52	General View	 Load JPG	☒
16	10/12/19 10:52	General View	 Load JPG	☒
17	10/12/19 10:52	General View	 Load JPG	☒
18	10/12/19 10:52	General View	 Load JPG	☒
19	10/12/19 10:52	General View	 Load JPG	☒
20	10/12/19 10:52	General View	 Load JPG	☒
21	10/12/19 10:52	General View	 Load JPG	☒
22	10/12/19 10:52	General View	 Load JPG	☒
23	10/12/19 10:52	General View	 Load JPG	☒
24	10/12/19 10:52	General View	 Load JPG	☒
25	10/12/19 10:52	General View	 Load JPG	☒
26	10/12/19 10:52	General View	 Load JPG	☒
27	10/12/19 10:52	General View	 Load JPG	☒
28	10/12/19 10:52	General View	 Load JPG	☒
29	10/12/19 10:52	General View	 Load JPG	☒
30	10/12/19 10:52	General View	 Load JPG	☒
31	10/12/19 10:52	General View	 Load JPG	☒
32	10/12/19 10:52	General View	 Load JPG	☒
33	10/12/19 10:52	General View	 Load JPG	☒
34	21/02/20 15:21	Reinspection Photo	 Load JPG	☒
35	21/02/20 15:21	Reinspection Photo	 Load JPG	☒
36	21/02/20 15:21	Reinspection Photo	 Load JPG	☒
37	21/02/20 15:21	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/02/20 15:21	Reinspection Photo		
39	21/02/20 15:21	Reinspection Photo		
40	21/02/20 15:21	Reinspection Photo		
41	21/02/20 15:21	Reinspection Photo		
42	21/02/20 15:21	Reinspection Photo		
43	21/02/20 15:21	Reinspection Photo		
44	21/02/20 15:21	Reinspection Photo		
45	21/02/20 15:21	Reinspection Photo		
46	21/02/20 15:21	Reinspection Photo		
47	21/02/20 15:21	Reinspection Photo		
48	21/02/20 15:21	Reinspection Photo		
49	21/02/20 15:21	Reinspection Photo		
50	21/02/20 15:21	Reinspection Photo		
51	21/02/20 15:21	Reinspection Photo		
52	21/02/20 15:21	Reinspection Photo		
53	21/02/20 15:21	Reinspection Photo		
54	21/02/20 15:21	Reinspection Photo		
55	21/02/20 15:21	Reinspection Photo		
56	21/02/20 15:21	Reinspection Photo		
57	21/02/20 15:21	Reinspection Photo		
58	21/02/20 15:21	Reinspection Photo		
59	21/02/20 15:22	Reinspection Photo		

Documentation			1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/19 11:07	Singapore Accident Statement		
2	10/12/19 11:07	Certificate of Insurance		
3	10/12/19 11:07	Insured's Driving License		
4	10/12/19 11:07	LTA		
5	10/12/19 11:07	MARK ESTIMATE		
6	12/12/19 09:51	SURVEYOR'S MARKING		
7	13/03/20 09:48	Supplementary		
8	13/03/20 09:48	WORKSHOP INVOICE		
9	13/03/20 09:48	DISCHARGE VOUCHER		

Linked Accident Report Documents

Assessment Reports			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 19:33	Accident Statement		
2	06/12/19 19:35	Accident Statement		
3	06/12/19 19:36	Accident Statement		
4	06/12/19 19:37	Accident Statement		

Photos/Images			3 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 14:24	Accident Photo		
2	06/12/19 14:24	Accident Photo		
3	06/12/19 14:24	Accident Photo		
4	06/12/19 14:24	Accident Photo		
5	06/12/19 14:24	Accident Photo		
6	06/12/19 14:24	Accident Photo		
7	06/12/19 14:24	Accident Photo		
8	06/12/19 14:24	Accident Photo		
9	06/12/19 14:24	Accident Photo		

Assessment Reports			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
10	06/12/19 14:24	Accident Photo	Load JPG	
11	06/12/19 14:24	Accident Photo	Load JPG	
12	06/12/19 14:24	Accident Photo	Load JPG	
13	06/12/19 14:24	Accident Photo	Load JPG	
14	06/12/19 14:24	Accident Photo	Load JPG	
15	06/12/19 14:24	Accident Photo	Load JPG	
16	06/12/19 14:24	Accident Photo	Load JPG	
Documentation			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 14:26	Sketch Plan	Load JPG	
2	06/12/19 14:26	Sketch Plan #2	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19021688/AVD3N2

Date: 13/03/2020

REFERENCE

Insured/Claimant: LINCOLN PEH ZHENGLIANG(BAI ZHENGLIANG)

Policy No: 1800034659

Date of Loss: 06/12/2019

Nature of Claim: OD

Claim No: 9916563613SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX9508A	Engine No:	CHZ905889
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V7J1056589
Reg. Date:	18/04/2018 (Man. Year: 2018)	Odometer:	25776 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,639.20	11,061.52	14,577.68	56.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,052.00	6,202.00	5,850.00	48.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,691.20	17,263.52	20,427.68	54.20
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	37,091.20	16,663.52	20,427.68	55.07
+ GST 7.00/7.00% (S\$)	2,596.38	1,166.45	1,429.93	55.07
Nett Amount (S\$)	39,687.58	17,829.97	21,857.61	55.07

INSPECTION

Date of Assignment: 10/12/2019

Date Inspected: 09/12/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Cracked	146.00 FS	*116.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	540.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM-LH/RH	O/s Damaged	296.00 FS	*118.40 FS
8	2		*FRONT BUMPER ADAPTER-LH/RH	Not Necessary	68.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	O/s Deformed	342.00 FS	*136.40 FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	660.00 FS	*527.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	172.00 FS	*137.60 FS
14	1		*FRONT BUMPER FOAM FILLER PIECE COVER	Deformed	111.00 FS	*88.80 FS
15	1		*SIGNAL HORN-LH HIGH TONE	Not Necessary	182.00 FS	*- FS
16	1		*SIGNAL HORN-RH LOW TONE	Not Necessary	182.00 FS	*- FS
17	2		*FRONT FENDER-LH/RH	Repair	1,556.00 FS	*- FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
19	2		*FRONT FENDER BRACKET-LH/RH	Not Necessary	70.00 FS	*- FS
20	1		*FRONT FENDER BRACE-LH/RH	O/s Bent	176.00 FS	*69.84 FS
21	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	316.00 FS	*- FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
23	1		*BONNET	Dented	2,898.00 FS	*2,318.40 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
25	2		*BONNET LID HINGE-LH/RH	Bent	112.00 FS	*88.48 FS
26	1		*BONNET GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
28	2		*BONNET STRIKER-LH/RH	Not Necessary	200.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION	Necessary	25.00 FS	*19.92 FS
30	1		*BONNET CATCH HOOK	Bent	58.00 FS	*45.76 FS
31	2		*BONNET LID LOCK	Not Necessary	367.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	53.00 FS	*- FS
33	1		*BONNET SOUND ABSORBER	Not Necessary	201.00 FS	*- FS
34	1		*PLENUM CHAMBER COVER	Not Necessary	164.00 FS	*- FS
35	1		*LED HEADLIGHT-LH/RH	O/s Cracked	10,058.00 FS	*4,023.20 FS
36	2		*LIFT CYLINER-LH/RH	Not Necessary	256.00 FS	*- FS
37	1		*HEADLIGHT HOSE	Not Necessary	61.00 FS	*- FS
38	1		*LOCK CARRIER	Cracked	663.00 FS	*530.40 FS
39	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
40	1		*RADIATOR AIR GUIDE-LH/RH	O/s Deformed	44.00 FS	*17.12 FS
41	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Damaged	11.00 FS	*8.32 FS
42	1		*AIR INTAKE AIR GUIDE	Not Necessary	53.00 FS	*- FS
43	1		*AIR INTAKE WATER DRAINAGE HOSE	Not Necessary	31.00 FS	*- FS
44	1		*AIR INTAKE AIR GUIDE	Not Necessary	62.00 FS	*- FS
45	1		*AIR INTAKE SEAL	Not Necessary	13.00 FS	*- FS
46	1		*AIR INTAKE AIR FILTER	Not Necessary	252.00 FS	*- FS
47	1		*AIR INTAKE MANIFOLD	Not Necessary	129.00 FS	*- FS
48	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
49	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
50	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
51	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
52	1		*HEADLIGHT HOSE RHS	Cut	29.84 FS	*29.84 FS
53	1		*RADIATOR SEAL OUTER RHS	Cracked	5.68 FS	*5.68 FS
54	1		*EXTERNAL TEMPERATURE SENSOR BRACKET	Cracked	13.68 FS	*13.68 FS

F=Franchise part. S=SpcNetL.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	25,639.20
						11,061.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO RENEW AND REINSTALL AIRCOND CONDENSER,RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND BOTH HEADLIGHTS.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	2,500.00
4	TO RESPRAY FRONT BUMPER,BONNET,HINGES AND BOTH FRONT FENDERS	New	4,000.00	1,950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			12,052.00	6,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >