

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921

Email : jmartauto@gmail.com

Registration No: 201400246D

GST Reg. No: 201400246D

CC6/ALG19621719/UKB3

9-Dec-19

Our ref : TP/4783/19

Chan Jiaen

TP ALG.

1chanchna.

GB71097837

RE : estimate cost for vehicle no : SMN 1869B

1 pc	tailgate <i>Dented</i>	\$	1,409.10	<i>1193.70</i>
1 pc	Freed meblem <i>3 Me</i>		68.30	✓
1 pc	Hybrid emblem <i>Me</i>		81.90	✓
1 pc	H emblem <i>Me</i>		48.80	✓
1 pc	tailgate w/strip <i>new</i>		146.30	✓
1 pc	rear bumper <i>Dented</i>		977.50	✓
2 pcs	rear bumper retainers <i>new</i>	<i>2426.80</i>	41.00	✓
4 pcs	rear bumper clips <i>new</i>	<i>1841.44</i>	15.60	✓
2 pcs	rear bumper beam <i>new</i>		100.40	✓
1 pc	end panel <i>new</i>		880.50	✓
			3,769.40	
		less 20%	753.88	
			3,015.52	
1 pc	rear w/screen gum <i>new</i>		50.00	✓
1 pc	reverse sensor <i>Damaged</i>		250.00	✓
	Panel beating.		800.00	✓
	spray painting.		800.00	✓
	Wiring.	<i>1280</i>	30.00	✓
	Trnasfer tailgate fitting.		80.00	✓
	Remove & refit rear w/screen.		120.00	✓
	Rust proofing.		80.00	✓
	Upholstery.		80.00	✓
			5305.52	
		Plus 7% GST	371.39	
			5676.91	

SD : five thousand six hundred seventy-six & cents ninety-one only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 3221.44

h/s: 2.5K

Admin Lj
h/s 09/12/19

04 Dyp