

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 11 Dec 2019

Preliminary Advice

Vehicle No	: SJN6508X	Accident Date	: 25/11/2019
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1506281904
Assignment Date	: 10/12/2019	Excess	: S\$500.00
Date of Inspection	: 10/12/2019	Est. Duration of Repair	: 5
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,495.77
Revised Amount	:S\$	3,647.56
Check Items (Estimated)	:S\$	2,584.00
Total	:S\$	6,231.56
Lump Sum Repair (estimated)	:S\$	5,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	29,395.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,605.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :