

25/03/2019

ASS. REC. BY:

REF: CS/CTI 1904720/fuf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 10.12.19 14.00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 6508X

Insured:

at Workshop m/s S & H Motor

Tel: 64534730

of 160 San Ming Drive #0702

Policy No: BMPCSN 1506281904

Claim No: SNM 190205609

Sum Insured:

Excess: \$500

Make of Veh:

(Client's Record)

D.O.A. 25.11.2019

CA / REV 1 REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.12.19 2.10pm

Person Contacted:

ms Wong

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJN 6508X - NBA / CTI 1902043419

D.O.A. - 25/11/2019

11/12/19

Revert via merimen

16/12/19

Rece approved \$5000 from Irene by merimen

16/12/19

Informed Doris c/A ex \$500 by email

ASS. REC. BY:

REF: C 72 /

CS/CTI 19021720/Kvf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to
Bonnet Tamm

11/1/20

LS \$4750 confirmed by email (Recd 1745.TI, 27/0)

RECEIVED 1 JAN 2020

Veh No:

STN 6508X

Yr Regn:

02, CP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c.

2354

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

37.9175

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J14MRB38309520003P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

25/11/19

D.O.I.

10/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

13/1 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

220

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Meimen

Lump Sum / I.B.I. (\$

4750/-

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth'd	Status
Main	09 Dec 2019 Sendback Est	09 Dec 2019 16:45 S\$6,495.77	10 Dec 2019 14:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WEE OOH HUAT, SUNNY, ID: S1750867I								
Vehicle Reg. No.:	SJN6508X	Date of Loss:	25/11/2019 00:00 - :59 [129 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205609/SJN6508X/C BS	Policy/Cover Note No.:	DMPCSN1506281904 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/12/2019]								
Driver/Custodian:	WEE OOH HUAT, SUNNY (/ Male) , NRIC: S1750867I Email:								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 16 December 2019 9:40 AM
To: SUR; Doris
Subject: SJN 6508X-DOA: 25/11/2019 (CHINA TAIPING OD)

Dear Doris,

As instructed by our client , please proceed to repair the **insured vehicle SJN 6508X on Lump Sum Repair, (Excess S500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SJN6508X (SNM19D205609/SJN6508X/CBS)

OD

Nov 25 2019 12:00AM

[WEE OOH HUAT, SUNNY]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 16/12/2019 09:26 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5000.00) - SJN6508X - Claim Handler: Chong Boon Sen

Approved:5000.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Chong Boon Sen	Date:	11 Dec 2019

Preliminary Advice

Vehicle No	: SJN6508X	Accident Date	: 25/11/2019
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1506281904
Assignment Date	: 10/12/2019	Excess	: S\$500.00
Date of Inspection	: 10/12/2019	Est. Duration of Repair	: 5
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,495.77
Revised Amount	:S\$	3,647.56
Check Items (Estimated)	:S\$	2,584.00
Total	:S\$	6,231.56
Lump Sum Repair (estimated)	:S\$	5,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	29,395.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,605.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8671
Vehicle Details	
Vehicle No.:	SJN6508X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	K24Z21300042
Chassis No.:	JHMRB38309C200039
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$33,248.00
Original Registration Date:	24 Feb 2009
First Registration Date:	24 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$33,248.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,933.00
COE Rebate Amount:	\$29,395.00
Total Rebate Amount:	\$29,395.00

The information contained herein is correct as at 10 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	867I
Vehicle Details	
Vehicle No.:	SJN6508X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	K24Z213D0042
Chassis No.:	JHMRB38309C200039
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$33,248.00
Original Registration Date:	24 Feb 2009
First Registration Date:	24 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$33,248.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,933.00
COE Rebate Amount:	\$29,423.00
Total Rebate Amount:	\$29,423.00

The information contained herein is correct as at 07 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2019 17:22
Date Of Accident	25/11/2019 12:15
Exact Location Of Accident	COMMONWEALTH AVE WEST TOWARDS CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN6508X
Insured/Policyholder	
Name Of Registered Owner	WEE POH HUAT, SUNNY
NRIC No	S1750867I
Email Address	SALES@MIA.COM.SG
Mobile Phone No	(LOCAL) +65-97576634
Alternative Phone No	OTHERS-97576634

Vehicle Particulars

Manufacturer	HONDA
Model	ODESSEY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1506281904
Cover Note Number	

Driver

Name of Driver	WEE POH HUAT, SUNNY
NRIC No	S1750867I
Date Of Birth	25/04/1966
Occupation	OUTDOOR
Date Of Driving Pass	05/05/2004
Driving Experience	15 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97576634
Fax Number	
Contact Number	OTHERS-97576634
Email Address	SALES@MIA.COM.SG

Address	BLK 449B BUKIT BATOK WEST AVENUE 9 #15-96
Postcode	652449
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
as any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF5195A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow our legal advisors to **rescind policy liability**.
4. The issuer and acceptance of this claim by insurance company is not an admission of policy liability on the part of the insurer or customer.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the UKA Accounts Management Centre established by the General Insurance Association of Singapore (GIAS) to insurance and third claims of this report will for a fee be made available upon request to interested parties.
7. At the judgment of this report to UKA insurers and insurers concerned by the serious nature of the report, at the discretion and to papers of the report being made available elsewhere.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my working with the General Insurance Association of Singapore ("GIAS") may wish to collect, use, disclose and/or process my personal data/personal information as set out in this Form and my other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to other person(s) who have insured vehicle(s) involved in this accident (if necessary) and those insured vehicle(s) involved in this accident shall be collectively referred to as the "Insureds". My insurer, GIAS and the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, fire, the emergency services, etc.)
- (b) processing, handling and/or dealing with my claim including the settlement of the claim and any necessary investigations relating to the claim;
- (c) investigating the accident and/or my claim;
- (d) carrying out and/or dealing with my instructions or responding to my insurers' queries;
- (e) administering my claim (including the making of correspondence, documents, materials, reports or notices in the which could involve disclosure of certain personal data about me or being about delivery of the same as well as all the external cover of envelope/mail packages, etc.);
- (f) complying with applicable laws, administrative, processing, handling and/or dealing with my claim collectively the "Purposes".
- (g) insurers(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, they are permitted to collect, use, disclose and/or process the Personal Information for one or more of the above Purposes; and
- (h) my Personal Information may/ can be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents/acting their insurers/law firms, which may be related outside of Singapore, for one or more of the above Purposes;
- (i) my Personal Information will also be collected and used to conduct claims related for the purpose of fraud prevention, investigation and management in present and all future claims;
- (j) the information as collected under this Form may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in processing, investigating, handling or settling fraud, regulatory, law enforcement and government agencies as necessary required for the purposes stated; or
- (ii) for complying with requirements under any regulations, laws or laws in force.

Policyholder's Signature
Date & Time


Driver's Signature
or Driver to carry a collection letter
Date & Time

Signature of Insurer
Date & Time

26/11/2019
Rashid Umar

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped my vehicle at Commonwealth Ave West Junction when the traffic is red. Vehicle B. When the traffic turn green we start to move suddenly the front car stopped for nothing so I can't stop in time and collided with his rear and I alighted to check vehicle B only slight damage on his rear.

DECLARATION

I/We declare the foregoing particulars are true to best of my/our knowledge.

Driver's Signature
Date & Time:

Driver's Signature
(If Driver is not present/available)
Date & Time:

26/01/2015
Rafiqi
Linda

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 023840
Date calculated: 09/12/2019 3:56 PM

Full Report
Registration: SJN6508X
Printed: 09/12/2019 3:56 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	25/11/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: HONDA
 Model: ODYSSEY (RC1)
 Sub Model: BASE MODEL
 Model Sheet Number: 35 CF 01
 Registration: SJN6508X

VIN number:

Odometer:

Model Specs

2356CCM 129KW TWO COAT METALLIC PREPARE OFF VEHICLE

Not Notified
11/12/19
1/2
After Rain
Ex 8500
5 day

Labour

Fix: 62564315

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
8101A2	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		13.0	54.60
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		9.0	37.80
8121B8)	R + R BOTH BONNET HINGES		6.0	25.20
812100	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		8.0	33.60
NO NUMBER	R + R LOWER ENGINE PROTECTION		3.0	12.60
NO NUMBER	RENEW FRONT PANEL CPL		25.0	105.00
NO NUMBER	R + R AIR CONDITIONING CONDENSER		6.0	25.20
NO NUMBER	DRAIN AND VENT AIR CONDITIONING		5.0	21.00
0340	FRT BUMPER SUPPORT REPAIR		20.0*	84.00
0741	L/F WING REPAIR		10 15.0*	63.00
0742	R/F WING REPAIR		10 15.0*	63.00

Labour Cost
Panel / Mechanical Labour

Hrs 12.50 WU 125.0 525.00

Total of Labour

525.00

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	21.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	
	L/F WING REPAIR PAINTING <50%	11.0	
	R/F WING REPAIR PAINTING <50%	11.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	RIGHT FRONT DOOR SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.02
1009	FRONT PANEL CPL SURFACE PAINT	11.21
0283	FRONT BUMPER NEW PART PAINT K1R	49.20
0741	L/F WING REPAIR PAINTING <50%	12.60
0742	R/F WING REPAIR PAINTING <50%	12.60
1481	LEFT FRONT DOOR SURFACE PAINT	21.17
1482	RIGHT FRONT DOOR SURFACE PAINT	21.17

Labour Cost - Paint

Factor

42.00 SGD/h

Hrs WU Price SGD

Time Paint

76.0

Preparation Main Work Metal

2.50

25.0

105.00

Preparation Comp. Work Plastic

0.50

5.0

21.00

Total

10 WU/h

10.60

106.0

445.20

Material Cost - Paint

New Part Painting

65.02

New Part Painting - Plastic K1R

49.20

Repair Painting

25.20

Surface-/Blend Paint

53.55

Material-constant Metal Preparation

28.60

Material-constant Plastic

9.00

Total

230.57

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	04711T6A000ZZ		Bu	480.00 ✓
0410	GRILLE	71121T6A003		CM	180.00 ✓
0431	MANUFACTURER BADGE	75700TA0A00		Ma	25.00 ✓
0435	GRILLE TRIM CHROMED	71122T6A003		De	180.00 ✓

Code	Description	Part Number	Supplier	Price SGD
0471	BONNET	60100SLE000ZZ	Bu	490.00 ✓
0475	L/BONNET HINGE	60170T6A000ZZ	R	55.00 ?
0476	R/BONNET HINGE	60120T6A000ZZ	R	55.00 ?
0481	BONNET INSULATION	74141T6A000	Bu	80.00 ?
0493	BONNET LOCK	74120T6A003	Tu	90.00 ✓
0561	L/F HEADLAMP	33150T6AQ01	CM	490.00 —
0562	R/F HEADLAMP	33100T6AQ01	CM	490.00 ✓
1009	FRONT PANEL CPL	60400T6A300ZZ	Bu	380.00 ?
4465	CONDENSER	80110T6A003	Pu	450.00 ?
7761	RADIATOR	190105X6J01	Pu	480.00 ?
7767	L/FAN SHROUD	190155X6J01	CM	110.00 ?
7768	R/FAN SHROUD	386155X6J01	CM	90.00 ?
7789	L/FAN MOTOR	190305X6J01	Tu	280.00 ?
7790	R/FAN MOTOR	386165X6J01	Tu	320.00 ?
7793	L/BLOWER FAN	190205A4H01	Di	65.00 ?
7794	R/BLOWER FAN	386115A4H01	Di	65.00 ?
1000	GRILLE TOP GANRISH	FRONT GRILLE	CM	70.00 ?

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	4,925.00
Fixed Sundry Parts Price	100.00
Total	5,025.00

Extras

Code	Description	Price SGD
1001	ECU diagnostic ECU diagnostic	n 120.00* X
1002	Electrical work Electrical work	2ol 35.00* ✓
1003	Engine coolant Engine coolant	n 30.00* ?
1004	Air con coolant Air con	n 50.00* ~
1005	Front number plate Number Plate	n 35.00* X
Total Extras		270.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To receive bodywork/spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party claims is on a "Without Prejudice" basis
- No Repayment/Insurance is allowed
- Supplementary work(s) must be received and
is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

Final Calculation

	SGD	SGD
Parts	4,925.00	
Fixed Sundry Parts Price	100.00	
Total Parts		5,025.00
Labour Time Base 10 WU/h		
Total 125.0 WU X 42.00 SGD/h	525.00	298.20 523.80
Total of Labour		525.00
Total Of Extras		270.00
Paint Work Time Base 10 WU/h		
Labour Cost 106.0 WU X 42.00 SGD/h	445.20	445.20
Material Cost	230.57	217.36 230.57
Total Paint Including Material		675.77
Repair Cost Excludes GST		6,495.77
GST (+7.0%)		454.70
Repair Cost Included GST		6,950.47

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Revert

Insurer Reference:
Repairer Reference: 023840
Date calculated: 11/12/2019 11:59 AM

Full Report
Registration: SJN6508X
Printed: 11/12/2019 12:00 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	25/11/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle		
Manufacturer:	HONDA	
Model:	ODYSSEY (RC1)	
Sub Model:	BASE MODEL	
Model Sheet Number:	35 CF 01	
Registration:	SJN6508X	
VIN number:		
Odometer:		
Model Specs		
2356CCM 129KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
8101A2	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		13.0	54.60
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		9.0	37.80
812100	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		8.0	33.60
NO NUMBER	R + R BONNET LOCK		1.0	4.20
0340	FRT BUMPER SUPPORT REPAIR		20.0*	84.00
0741	L/F WING REPAIR		10.0*	42.00
0742	R/F WING REPAIR		10.0*	42.00
0475	L/BONNET HINGE CHECK			
0476	R/BONNET HINGE CHECK			
0481	BONNET INSULATION CHECK			
1009	FRONT PANEL CPL CHECK			
4465	CONDENSER CHECK			
7761	RADIATOR CHECK			
7767	L/FAN SHROUD CHECK			
7768	R/FAN SHROUD CHECK			
7789	L/FAN MOTOR CHECK			
7790	R/FAN MOTOR CHECK			
7793	L/BLOWER FAN CHECK			
7794	R/BLOWER FAN CHECK			
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		7.10	71.0	298.20
Total of Labour				298.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		21.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	L/F WING REPAIR PAINTING <50%		11.0	
	R/F WING REPAIR PAINTING <50%		11.0	
	LEFT FRONT DOOR SURFACE PAINT		8.0	
	RIGHT FRONT DOOR SURFACE PAINT		8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.00
0283	FRONT BUMPER NEW PART PAINT K1R	49.20
0741	L/F WING REPAIR PAINTING <50%	12.60
0742	R/F WING REPAIR PAINTING <50%	12.60
1481	LEFT FRONT DOOR SURFACE PAINT	21.17
1482	RIGHT FRONT DOOR SURFACE PAINT	21.17

Paint Material Per Part

Paint Material Factor		Price SGD		
Code	Description			
	Labour Cost - Paint		Hrs	WU
	Factor	42.00 SGD/h		
	Time Paint			70.0
	Preparation Main Work Metal		2.50	25.0
	Preparation Comp. Work Plastic		0.50	5.0
	Total	10 WU/h	10.00	100.0
				Price SGD
	Material Cost - Paint			
	New Part Painting			65.02
	New Part Painting - Plastic K1R			49.20
	Repair Painting			25.20
	Surface-/Blend Paint			42.34
	Material-constant Metal Preparation			28.60
	Material-constant Plastic			9.00
	Total			219.36

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	04711T6A000ZZ		480.00
0410	GRILLE	71121T6A003		180.00
0431	MANUFACTURER BADGE	75700TA0A00		25.00
0435	GRILLE TRIM CHROMED	71122T6A003		180.00
0471	BONNET	60100SLE000ZZ		490.00
0493	BONNET LOCK	74120T6A003		90.00
0561	L/F HEADLAMP	33150T6AQ01		490.00
0562	R/F HEADLAMP	33100T6AQ01		490.00
1000	GRILLE TOP GANRISH	FRONT GRILLE		70.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,495.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,595.00

Extras

Code	Description	Price SGD
1002	Electrical work Electrical work	35.00*
1003	Engine coolant Engine coolant	30.00*
1004	Air con coolant Air con	50.00*
	Total Extras	115.00

Final Calculation

	SGD	SGD
Parts	2,495.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,595.00
Labour Time Base 10 WU/h		
Total 71.0 WU X 42.00 SGD/h	298.20	
Total of Labour		298.20
Total Of Extras		115.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 42.00 SGD/h	420.00	
Material Cost	219.36	
Total Paint Including Material		639.36
Repair Cost Excludes GST		3,647.56
GST (+7.0%)		255.33
Repair Cost Included GST		3,902.89

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SH Motor Pte Ltd
180 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 023840
Date calculated: 09/12/2019 3:56 PM

Full Report
Registration: SJN6508X
Printed: 09/12/2019 3:56 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	25/11/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	HONDA
Model:	ODYSSEY (RC1)
Sub Model:	BASE MODEL
Model Sheet Number:	35 CF 01
Registration:	SJN6508X
VIN number:	
Odometer:	
Model Specs	
2356CCM 129KW	TWO COAT METALLIC
	PREPARE OFF VEHICLE

Not Available
61 Day & ?
Preparing After Repair
Ex & Sed.
5 day

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
8101A2	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	13.0	54.60	
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	9.0	37.80	
8121B8)	R + R BOTH BONNET HINGES	6.0	25.20	
812100	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE	8.0	33.60	
NO NUMBER	R + R LOWER ENGINE PROTECTION	3.0	12.60	
NO NUMBER	RENEW FRONT PANEL CPL	25.0	105.00	
NO NUMBER	R + R AIR CONDITIONING CONDENSER	6.0	25.20	
NO NUMBER	DRAIN AND VENT AIR CONDITIONING	5.0	21.00	
0340	FRT BUMPER SUPPORT REPAIR	20.0*	84.00	
0741	L/F WING REPAIR	10 15.0*	63.00	
0742	R/F WING REPAIR	10 15.0*	63.00	

Labour Cost
Panel / Mechanical Labour

Hrs	WU	
12.50	125.0	525.00
Total of Labour		525.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	21.0
	FRONT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1R	11.0
	L/F WING REPAIR PAINTING <50%	11.0
	R/F WING REPAIR PAINTING <50%	11.0
	LEFT FRONT DOOR SURFACE PAINT	8.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.02
1009	FRONT PANEL CPL SURFACE PAINT	11.21
0283	FRONT BUMPER NEW PART PAINT K1R	49.20
0741	L/F WING REPAIR PAINTING <50%	12.60
0742	R/F WING REPAIR PAINTING <50%	12.60
1481	LEFT FRONT DOOR SURFACE PAINT	21.17
1482	RIGHT FRONT DOOR SURFACE PAINT	21.17

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		76.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	106.0	445.20

Material Cost - Paint

	Price SGD
New Part Painting	65.02
New Part Painting - Plastic K1R	49.20
Repair Painting	25.20
Surface-/Blend Paint	53.55
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	230.57

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	04711T6A000ZZ		Per	480.00 -
0410	GRILLE	71121T6A003		CMS	180.00 -
0431	MANUFACTURER BADGE	75700TA0A00		Per	25.00 -
0435	GRILLE TRIM CHROMED	71122T6A003		Per	180.00 -

Code	Description	Part Number	Supplier	Price SGD
71	BONNET	60100SLE000ZZ		<i>Per</i> 490.00 ✓
75	L/BONNET HINGE	60170T6A000ZZ		95.00 ?
76	R/BONNET HINGE	60120T6A000ZZ		58.00 4
81	BONNET INSULATION	74141T6A000		80.00 7
93	BONNET LOCK	74120T6A003		<i>In</i> 90.00 ✓
161	L/F HEADLAMP	33150T6AQ01		<i>CM</i> 490.00 ✓
162	R/F HEADLAMP	33100T6AQ01		<i>CM</i> 490.00 ✓
109	FRONT PANEL CPL	60400T6A300ZZ		380.00 2
165	CONDENSER	80110T6A003		450.00 2
161	RADIATOR	190105X6J01		480.00 2
167	L/FAN SHROUD	190155X6J01		110.00 2
168	R/FAN SHROUD	386155X6J01		90.00 2
189	L/FAN MOTOR	190305X6J01		280.00 2
190	R/FAN MOTOR	386165X6J01		320.00 2
193	L/BLOWER FAN	190205A4H01		65.00 2
194	R/BLOWER FAN	386115A4H01		65.00 ?
000	GRILLE TOP GANRISH	FRONT GRILLE		70.00 7
				0.00
OEM Parts				
Non-OEM Parts				4,925.00
Used parts				100.00
Savings				
Subtotal				
Fixed Sundry Parts Price				
Total				5,025.00

Code	Description	Price SGD
001	ECU diagnostic ECU diagnostic	<i>nn</i> 120.00* X
002	Electrical work Electrical work	<i>2d</i> 35.00* ✓
003	Engine coolant Engine coolant	30.00* 7
004	Air con coolant Air con	50.00* 7
005	Front number plate Number Plate	<i>In</i> 35.00* X
Total Extras		270.00

Final Calculation

	SGD	SGD
	4,925.00	
Parts	100.00	
Fixed Sundry Parts Price		5,025.00
Total Parts		
Labour Time Base 10 WU/h	525.00	
Total 125.0 WU X 42.00 SGD/h		525.00
Total of Labour		270.00
Total Of Extras		
Paint Work Time Base 10 WU/h	445.20	
Labour Cost 106.0 WU X 42.00 SGD/h	230.57	
Material Cost		675.77
Total Paint Including Material		6,495.77
Repair Cost Excludes GST		454.70
GST (+7.0%)		6,950.47
Repair Cost Included GST		

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- } - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park, 51

Ubi Avenue 1

408933

Insurer Reference:

Repairer Reference: 023840

Date calculated: 09/01/2020 3:03 PM

Finalise

Full Report

Registration: SJN6508X

Printed: 09/01/2020 3:03 PM

Summary Information**Claim**

Location: Singapore (SG)

Work Provider:

China Taiping Insurance
(Singapore) Pte Ltd

Printed by:

KK LAU

Currency:

SGD

Claim Reference:

Date of Incident:

25/11/19

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details**Vehicle**

Manufacturer:

HONDA

Model:

ODYSSEY (RC1)

Sub Model:

BASE MODEL

Model Sheet Number:

35 CF 01

Registration:

SJN6508X

VIN number:

Odometer:

Model Specs

2356CCM 129KW


TWO COAT METALLIC

PREPARE OFF VEHICLE

Vehicle Condition**Vehicle Status**

Pre-Accident Damage:

Date of Inspection:

Damage AreasAll ☐Underbody ☐

Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
8101A2	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		13.0	54.60
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		9.0	37.80
812100	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		8.0	33.60
NO NUMBER	R + R LOWER ENGINE PROTECTION		3.0	12.60
NO NUMBER	RENEW FRONT PANEL CPL		25.0	105.00
NO NUMBER	R + R AIR CONDITIONING CONDENSER		6.0	25.20
NO NUMBER	DRAIN AND VENT AIR CONDITIONING		5.0	21.00
0340	FRT BUMPER SUPPORT REPAIR			
0741	L/F WING REPAIR		10.0*	42.00
0742	R/F WING REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		8.90	89.0	373.80
Total of Labour				373.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		21.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	L/F WING REPAIR PAINTING <50%		11.0	
	R/F WING REPAIR PAINTING <50%		11.0	
	LEFT FRONT DOOR SURFACE PAINT		8.0	
	RIGHT FRONT DOOR SURFACE PAINT		8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.0
1009	FRONT PANEL CPL SURFACE PAINT	11.2
0283	FRONT BUMPER NEW PART PAINT K1R	49.2
0741	L/F WING REPAIR PAINTING <50%	12.6
0742	R/F WING REPAIR PAINTING <50%	12.6
1481	LEFT FRONT DOOR SURFACE PAINT	21.1
1482	RIGHT FRONT DOOR SURFACE PAINT	21.1

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		76.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	106.0	445.20

Material Cost - Paint

	Price SGD
New Part Painting	65.00
New Part Painting - Plastic K1R	49.20
Repair Painting	25.20
Surface-/Blend Paint	53.50
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	230.50

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	04711T6A000ZZ		480.00
0410	GRILLE	71121T6A003		180.00
0431	MANUFACTURER BADGE	75700TA0A00		25.00
0435	GRILLE TRIM CHROMED	71122T6A003		180.00
0471	BONNET	60100SLE000ZZ		490.00
0493	BONNET LOCK	74120T6A003		90.00
0561	L/F HEADLAMP	33150T6AQ01		490.00
0562	R/F HEADLAMP	33100T6AQ01		490.00
1009	FRONT PANEL CPL	60400T6A300ZZ		380.00
4465	CONDENSER	80110T6A003		450.00
7761	RADIATOR	190105X6J01		480.00
7767	L/FAN SHROUD	190155X6J01		110.00
7768	R/FAN SHROUD	386155X6J01		90.00
7789	L/FAN MOTOR	190305X6J01		280.00
7790	R/FAN MOTOR	386165X6J01		320.00
7793	L/BLOWER FAN	190205A4H01		65.00
7794	R/BLOWER FAN	386115A4H01		65.00
1000	GRILLE TOP GANRISH	FRONT GRILLE		70.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,735.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			4,835.00

Extras

Code	Description	Price SGD
1002	Electrical work Electrical work	20.00
1003	Engine coolant Engine coolant	30.00
1004	Air con coolant Air con	50.00
	Total Extras	100.00

Final Calculation

	SGD	SGD
Parts	4,735.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,835.00
Labour Time Base 10 WU/h		
Total 89.0 WU X 42.00 SGD/h	373.80	
Total of Labour		373.80
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 106.0 WU X 42.00 SGD/h	445.20	
Material Cost	230.57	
Total Paint Including Material		675.77
Repair Cost Excludes GST		5,984.57
GST (+7.0%)		418.92
Repair Cost Included GST		6,403.49

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 13 January 2020 10:34 AM
To: Doris; SUR
Cc: Kenneth Kong (LKKAUTO)
Subject: RE: vehicle no : SJN6508X-final

Dear Doris,

Noted with thanks.

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Doris <doris@sh-motor.com>
Sent: Saturday, 11 January 2020 4:31 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: RE: vehicle no : SJN6508X-final

Dear Veron

Noted...Thank...lump sum cost \$4,750.00 (Excess \$500)

Thank

Doris

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 9 January 2020 3:28 PM
To: Doris; Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: vehicle no : SJN6508X-final

Dear Doris,

Offer Lump Sum \$4750 before excess \$500 @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Doris <doris@sh-motor.com>

Sent: Wednesday, 8 January 2020 1:21 PM

To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: vehicle no : SJN6508X-final

Dear Kenneth

Forward vehicle no : SJN 6508 X for final lump sum repair

Thank

Doris

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Dec 2019 Sendback Est	09 Dec 2019 16:45 \$56,495.77	10 Dec 2019 14:02 Edit Adj Rpt	\$54,750.00 Edit Estimates	\$54,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WEE OOH HUAT, SUNNY, ID: S17508671								
Vehicle Reg. No.:	SJN6508X	Date of Loss:	25/11/2019 00:00 - :59 [129 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205609/SJN6508X/CBS	Policy/Cover Note No.:	DMPCSN1506281904 (Comprehensive)						
		Excess:	\$500.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/12/2019]								
Driver/Custodian:	WEE OOH HUAT, SUNNY (/ Male) , NRIC: S17508671 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (16/12/2019): Alert - Adj Mandate Approved (\$5000.00) - SJN6508X - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN6508X (SNM19D205609/SJN6508X/CBS)

OD

Nov 25 2019 12:00AM

[WEE OOH HUAT, SUNNY]

S & H Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Assessment Reports				1 per page
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	09/12/19 16:45	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/12/19 12:30	Adjuster Immediate Advice		Load HTM
Photos/Images				3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/12/19 12:30	General View		Load PDF
2	09/01/20 15:21	Reinspection Photo (1)		Load PDF
3	09/01/20 15:21	Reinspection Photo (2)		Load PDF
Documentation				1 per page
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	09/12/19 16:44	E-filed GIA report		Load PDF
2	09/12/19 16:45	Repair Estimates		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/12/19 12:31	MARK ESTIMATE		Load PDF
2	11/12/19 12:31	AUDATEX		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119021720/KVF3E2

Date: 14/01/2020

REFERENCE

Insured/Claimant: WEE OOH HUAT, SUNNY Policy No: DMPCSN1506281904
Date of Loss: 25/11/2019 Nature of Claim: OD Claim No: SNM19D205609/SJN6508X/CBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN6508X
Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24Z21300042
Reg. Date: 24/02/2009 (Man. Year: 2008) Chassis No: JHMRB38309C200039
Colour: Metallic Silver Odometer: 379175 km
Engine Capacity: 2354 cc
Market Value/New Car Price: S\$59,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,925.00	4,735.00	190.00	3.86
Miscellaneous Items	370.00	200.00	170.00	45.95
Paintwork Materials	230.57	230.57	0.00	0.00
Labour	525.00	373.80	151.20	28.80
Paintwork Labour	445.20	445.20	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,495.77	5,984.57	511.20	7.87
Approved Total (Overridden) (S\$)		4,750.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	6,495.77	4,250.00	2,245.77	34.57
+ GST 7.00/7.00% (S\$)	454.70	297.50	157.20	34.57
Nett Amount (S\$)	6,950.47	4,547.50	2,402.97	34.57

INSPECTION

Date of Assignment: 10/12/2019 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 10/12/2019 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN6508X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare parts		4,925.00 F	*4,735.00 F
					Total Parts (S\$)	4,925.00
						4,735.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork material	230.57	230.57
<u>Miscellaneous Items</u>				
2	1	Misc	370.00	200.00
Sub Total (S\$)			600.57	430.57

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	445.20	445.20
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	525.00	373.80
Gross Labour Cost (S\$)			970.20	819.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >