

輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

08/12/2019

Owner: AL'EMMA CORNER

ESTIMATE TO REPAIR TOYOTA HIACE - GBF1515U

1pc	front RH door	\$ 1,248.50
2pcs	front RH door hinge @\$90.70	\$ 181.40
1pc	front RH door inner rubber	\$ 268.70
1pc	front RH door inner lock	\$ 381.50
1pc	front RH wheel top panel	\$ 681.50
1pc	front RH door rear pillar	\$ 891.50
1pc	front RH door rear pillar inner panel	\$ 781.50
1pc	rear RH door	\$ 1,718.50
1pc	rear RH door lower hinge	\$ 281.50
1pc	rear RH door lower lock	\$ 395.20
1pc	rear RH door auto motor	\$ 1,258.50
1pc	rear RH door inner rubber	\$ 278.50
1pc	rear RH door inner sensor rubber	\$ 781.50
		\$ 9,148.30
less 25%		\$ 2,287.08
		\$ 6,861.23

remove sticker	s.nett	\$ 380.00
ROC sticker	s.nett	\$ 80.00

remove & refit front RH door glass	\$ 120.00
tuffkote	\$ 150.00
wiring	\$ 150.00
spray painting	\$ 1,200.00
labour charges	\$ 1,400.00
Total	
	\$ 10,341.23

