

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ6146Y
Accident Date : 06-Dec-2019

No. : 06109

Date : 09-Dec-2019

Our Ref : 219206 (AIG) / CHAN

PAGE : 1

HUI SHOON CAR RENTAL
BLK 1 SIN MING IND. ESTATE
#01-125
Singapore 575642

Not Notified
Call by 85700
Resurvey After Repair
6 days

ESTIMATED COST OF REPAIR FOR TOYOTA ESTIMA AREAS 2.4 SGP86K

1 pc Tail gate		Bu	1,590.10	✓
1 pc Tail gate glass moulding		mc	91.20	✓
2 pcs Tail gate lamp <i>also cm also</i>	@ S\$383.40		766.80	2x2 ✓
1 pc Tail gate lamp ctr reflector		cm	381.60	2 ✓
1 pc Tail gate logo		mc	66.80	✓
1 pc Tail gate outer chrome		mc	287.70	✓
1 pc Tail gate inner trim cover		mc	476.40	✓
2 pcs Taillamp	@ S\$442.80	mc	885.60	x
1 pc Rear end panel		Bu	625.50	✓
1 pc End panel top garnish		Bu	260.50	✓
6 pcs End panel top garnish clip	@ S\$ 7.40	mc	44.40	✓ missing
1 pc End panel lower garnish		mc	175.80	✓
2 pcs Rear fender inner trim <i>return</i>	@ S\$743.30		1,486.60	✓
1 pc Rear bumper fascia		Bu	541.70	✓
2 pcs Rear bumper side retainer <i>also</i>	@ S\$ 51.90		103.80	✓ 4's only
2 pcs Rear bumper side sponge	@ S\$ 65.70	cm	131.40	✓
2 pcs Rear bumper side retainer(S)	@ S\$ 36.40	Bu	72.80	✓
			7,988.70	
	Less 25% :		1,997.18	
			5,991.52	401.
1 pc Rear w/s glass sealant		mc	60.00	sn
1 pc Rear bumper reverse sensor(4pc		mc	400.00	sn ✓
To remove & refix rear windscreen glass and conduct water leak test.			150.00	1201

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ6146Y

Page : 2

To remove roof lining, front and rear seats, trim board and carpet

601
120.00

To remove air con condenser, pipes and drier, vacuum and to recharge gas

nn 120.00 X

To apply undersealing

60 100.00 ?

To putty and spray replaced parts

900.00 6601

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

600 / 1,000.00 ?

Total : S\$ 8,841.52

Singapore Dollars Eight Thousand Eight Hundred and Forty One and Cents Fifty Two Only

C/SUM
5700.00

P *5233.80*
SN *440.00*
L *1500.00*

7173.80
1434.76
5739.04

REPAIRER'S
CONFIRM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: