

Lion City Rental Pte Ltd  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 10/12/2019

Attn : MOTOR CLAIMS DEPT

**ESTIMATE**

VEHICLE NO. SLE2661K

CHASSIS NO : GK81005670

MAKE / MODEL : Honda Shuttle 1.5G

DATE OF ACCIDENT : 06/12/2019

YOUR INSURED VEHICLE NUMBER : SGG7902G

MILEAGE : 227819 Km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/L door ✓ <i>DN</i>	1 PC	\$1,575.00	\$1,575.00
2	R/L fender ✓ <i>DN</i>	1PC	\$2,000.00	\$2,000.00
LIST TOTAL S\$:				\$3,575.00
20.00% DISCOUNT S\$:				\$715.00
				<u>\$2,860.00</u>

**LABOUR CHARGES**

1	To labour charge for removing R/L door and include cutting out R/L fender out to facilitate repairs and replacement of damaged parts	\$1,200.00	<i>600</i>
2	To respray R/L door and R/L fender	\$1,000.00	<i>400 500</i>
3	Transfer door mechanism to facilitate repairs and replacement of parts	\$120.00	<i>100</i>
LABOUR TOTAL S\$:		\$2,320.00	
TOTAL S\$:		\$5,180.00	
7% GST		\$362.60	
GRAND TOTAL S\$:		<u>\$5,542.60</u>	

Sum Pin (Lkk)

10/12/2019.

TP without prejudice.

Repair day - 4 days.  
5

Lump sum

After paint photo.