

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ms. AIG Asia Pacific Insurance Pte Ltd

Date: 10/12/2019

Attn : MOTOR CLAIMS DEPT

Lion City Rental Pte Ltd

CARROS CENTER

ALAN LAM HUAT #04-01 5(737869)

Main +65 62524991

ESTIMATE

VEHICLE NO. SLE2661K

CHASSIS NO : GK81005670

MAKE / MODEL : Honda Shuttle 1.5G

DATE OF ACCIDENT : 06/12/2019

YOUR INSURED VEHICLE NUMBER : SGG7902G

MILEAGE : 227819 Km

PARTS DESCRIPTION

- 1 R/L door ✓ bh
- 2 R/L fender ✓ bn

QTY	UNIT PRICE	LIST PRICE
1 PC	\$1,575.00	\$1,575.00 1050
1PC	\$2,000.00	\$2,000.00 1385
LIST TOTAL S\$:		\$3,575.00 2,435
20.00% DISCOUNT S\$:		\$715.00 - 20%
		\$2,860.00 1,948

LABOUR CHARGES

- 1 To labour charge for removing R/L door and include cutting out R/L fender out to facilitate repairs and replacement of damaged parts
- 2 To respray R/L door and R/L fender
- 3 Transfer door mechanism to facilitate repairs and replacement of parts

	\$1,200.00 600
	\$1,000.00 - 400 500
	\$120.00 100
LABOUR TOTAL S\$:	\$2,320.00 1,200
TOTAL S\$:	\$5,180.00
7% GST	\$362.60
GRAND TOTAL S\$:	\$5,542.60

Sun Pin (Lkk)

10/12/2019.

TP without prejudice.

Repair day - 5 days.

Lump sum

After paint photo.

Lump sum \$3,200.00

5 days

$$\begin{array}{r}
 P = 1,948 \\
 L = 1,200 \\
 \hline
 3,148 \\
 - 20\% \\
 \hline
 2,518.40
 \end{array}$$

4/5

\$2,500

5 days.

2860.00

1220.00
4080.00