

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

16-03-20

Date Of Accident : 09-12-2019

Our Ref : SJD 2628L/T/18

**ANG PHOON YONG**  
637 East Coast Road  
Singapore 459023

Lkr. - Adrian

TPAIG.

Jia

508J

Date la/parts 09-12-19 to 14-12/19

Fax 68416315  
on 17/03/20

**ESTIMATE BILL ON VEH. NO. : SJD 2628L**

**MODEL : B.M.W 523i**

**CHASSIS NO. : WBAFP320X0C546742**

## LIST ITEM

Front Bumper Fascia	deform	✓	1,200.00
Front Bumper Sporge	cracked	✓	160.00
Front Bumper Reinforcement	not new	X	708.00
Front Bumper Side Retainer RH	new	✓	45.00
Front Bumper Nozzle Cover	cracked	✓	50.00
Front Bumper Clips	New	12pcs @ 6.00	30 72.00
Front Bumper Air Grille Garnish RH	not new	X	38.00
Front Bumper Air Duct RH	cracked	✓	39.00
Headlamp RH	cracked	✓	2,302.00
Fog Lamp RH	cracked	✓	295.00
			4,909.00
Less 5% Discount :			245.45
			4,663.55

## SPECIAL NETT ITEM

Front Bumper Parking Sensor RH (Outer)	not new	X	380.00
Front Grille (Acc) RH	not new	X	250.00
Head Lamp Black Sticker (Acc)	New	120	40 150.00
Head Lamp Eye Lip (Acc)	New	80	100.00

## LABOUR CHARGE

To check wiring system

30 ~~80.00~~

To reset electrical system

80 ~~280.00~~

To respray affected areas

660 250 ~~600.00~~

To renew damaged parts, straighten & repair front RH fender,  
front support panel & aligned all parts

300 ~~700.00~~

7,283.55

GST 7% :

509.85

**AMOUNT DUE :**

7,793.40

total : 4488.50

L/S: 3.5K ✓

04 Days ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: