

## Police Report



**SINGAPORE  
POLICE FORCE**



T201912092001

1 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 648818  
Tel No: 1800-2680099

Report No: T201912092001

## REPORT OF A TRAFFIC ACCIDENT

|                                            |            |                                                                           |                              |                            |  |
|--------------------------------------------|------------|---------------------------------------------------------------------------|------------------------------|----------------------------|--|
| Date/Time Report Made:<br>08/12/2019 00:18 |            | Vide Report No.:                                                          |                              | Station Diary No.:<br>1    |  |
| <b>Informant's Particulars</b>             |            |                                                                           |                              |                            |  |
| Name of Informant:<br>DAVID NG             |            | Address:<br>APT BLK 531 JURONG WEST STREET 52 #11-421<br>SINGAPORE 640531 |                              |                            |  |
| ID Type / ID No.<br>NRIC NO / S7835529H    |            | Contact No.:                                                              |                              | Mobile: 98372335           |  |
| Nationality:<br>SINGAPORE CITIZEN          |            | Email:                                                                    |                              |                            |  |
| Sex:<br>Male                               | Age:<br>41 | Date of Birth:<br>04/12/1978                                              | Type of Informant:<br>Driver |                            |  |
| Race:<br>Chinese                           |            | Language:<br>English                                                      |                              | Institution / School Name: |  |
| Occupation:<br>LORRY DRIVER                |            | Driving Licence Information:<br>Class: 3,4,5                              |                              | Date of Expiry:            |  |

## General Information of the Accident

|                                                               |                           |                                    |                                            |                                     |
|---------------------------------------------------------------|---------------------------|------------------------------------|--------------------------------------------|-------------------------------------|
| Type of Accident:                                             | Non-Injury<br>Hit and Run | Drink Drive:<br>No                 | Date/Time of Accident:<br>08/12/2019 22:30 | Type of Location:<br>Car Park       |
| Location:<br>Along Road 1<br>JURONG WEST STREET 52            |                           |                                    |                                            |                                     |
| BLK 531 JURONG WEST ST 52 OPEN CAR PARK LOT 303               |                           |                                    |                                            |                                     |
| Weather:<br>Clear                                             |                           | Road Surface:<br>Dry               |                                            | Road Speed Limit:                   |
| Traffic Flow:<br>Two Way                                      |                           | Traffic Control:<br>Not Controlled |                                            | Traffic Volume:<br>No Traffic       |
| Type of Collision:<br>Moving Vehicle Against - Parked Vehicle |                           |                                    |                                            | Anyone conveyed by ambulance:<br>No |

## Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition         | No of Passenger |
|-------------|------|------|-------|-------|-------------------|-----------------|
| SMP424BM    | Car  |      |       |       | Seriously Damaged | 0               |

## Police Report

SINGAPORE  
POLICE FORCE

T201912292001

Police Station Of Origin:  
Jurong West N.P.C.  
700 Corporation Road SINGAPORE 642618  
Tel No: 1800-2689999

2 of 3  
Report No: T201912292001

## CONTINUATION OF REPORT

**Brief Details.**

On 08/12/2019 at about 10.00pm, I have parked and secured my vehicle (SMP4248M) at Blk 531 Jurong West St 52 open car park lot number 303. Everything intact.

On 08/12/2019 at about 10.45pm, my neighbor (staying at 7th floor) came over to my unit and showed a video which he had earlier taken from his handphone. The video had showed at about 10.38pm, that there is one black Merc had left the gantry of Blk 531 Jurong West St 52 car park. The video did not show that the said Merc had hit my vehicle. My said neighbor is Jimmy Teo and his contact number is 88235656. My neighbor informed me that earlier he had saw the said Merc had hit my vehicle and left the carpark. My neighbour had whatsapp the said video to me. My neighbor also informed me that there is one male Chinese uncle at the car park and he also had saw it. The said male Chinese uncle is also my neighbor staying at 9th floor. I am currently do not have the uncle's name but I have his contact number is 96371378.

I have installed in-car camera inside my vehicle. However, after I had viewed the footages from my handphone, it is too dark to see the Merc registration plate number. I will view the footages again from my computer to check whether am I able to see the said Merc registration plate number or not.

My vehicle's front bumper dented and crack and registration plate number dented. There is white cement mark on my right rear tyre. I believed that the mark was caused by the impact after the said Merc had hit my car which caused my vehicle to push backware causing the said white cement mark on my said tyre.

This is the first time such incident had happened to my vehicle. I am lodging the police report to claim insurance.

## Police Report

SINGAPORE  
POLICE FORCEPolice Station Of Origin:  
Jurong West N.P.C  
790 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

T201912012001

3 of 3

Report No. T201912012001

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

|                                                                                   |                                |
|-----------------------------------------------------------------------------------|--------------------------------|
| Signature Of Officer Recording This Report:<br>J /<br>Sr Staff Sgt ONG BOON TIONG | Signature Of Informant:<br>    |
| Signature Of Interpreter:<br>Not applicable                                       | Date/Time:<br>09/12/2019 00:15 |
| Officer In Charge Of Case:<br>TP / HRT /                                          | Classification Of Case:        |
| Contact No.:<br>Authentication Stamp<br>Signature:<br>Singapore Police Force      |                                |

## Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
 8 Raffles Quay #08-00 Singapore 048582  
 Tel: (65) 4224 0000 Fax: (65) 6724 0000  
 Operating Hours: Monday to Friday: 09:00 - 17:00  
 09:00 - 17:00 / 6:00 PM - 5:00 PM (7/7)

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report

### ADDENDUM

#### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 119162015 Vehicle Registration No: SMP 4246 M  
 Name (as shown on NRIC): Ms. Goh Ai Tee NRIC/FIN/Passport No: SXXXX573A  
 (\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
 Address: Blk 531 Jurong West St 52 #11-421 Singapore (640531)  
 Contact (Tel): \_\_\_\_\_ Mobile No: +65 97450889  
 Email Address: aittee78@gmail.com  
 Date of Accident: 08/12/2019 Time of Accident: 10.40am (10.40 PM)  
 Place of Accident: Blk 531 Jurong West Street 52 Carpark  
 Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

#### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO CONVERT FROM THIRD PARTY TO OWN DAMAGE CLAIM

Policyholder / Driver's Signature  
 Date: 20/12/2019

Reporting Centre Personnel's Signature  
 Name: Lish Shi Hao, Tracy  
 NRIC/FIN No: SXXXX792K  
 Date: 20/12/2019

# MOTOR CAR (Frt)

## Front Portion

| NAC  | INC    | Item                                   | CON | AC | Qty |
|------|--------|----------------------------------------|-----|----|-----|
| 1001 | 991886 | Frt Number Plate                       | BT  | ✓  |     |
| 1002 | 991887 | Frt Number Plate Base                  |     |    |     |
| 1003 | 991889 | Frt Number Plate Garnish               |     |    |     |
| 1004 | 991300 | Frt Bumper                             |     |    |     |
| 1005 | 992341 | Frt Bumper Clips                       |     |    |     |
| 1006 | 991325 | Frt Bumper Bracket                     |     |    |     |
| 1007 | 991462 | Frt Bumper Side Retainer               |     |    |     |
| 1008 | 991433 | Frt Bumper Reinforcement               |     |    |     |
| 1009 | 991318 | Frt Bumper Beam                        |     |    |     |
| 1010 | 991468 | Frt Bumper Sponge                      | 2   |    |     |
| 1011 | 991427 | Frt Bumper Protector                   |     |    |     |
| 1012 | 991420 | Frt Bumper Pad                         |     |    |     |
| 1013 | 991363 | Frt Bumper Grille                      |     |    |     |
| 1014 | 991301 | Frt Bumper Moulding                    |     |    |     |
| 1015 | 991407 | Frt Bumper Lower Spoiler               |     |    |     |
| 1016 | 991438 | Frt Bumper Sensor                      |     |    |     |
| 1017 | 995100 | Frt LH Bumper Fog Lamp Cover           |     |    |     |
| 1018 | 991355 | Frt RH Bumper Fog Lamp Cover           |     |    |     |
| 1019 | 995079 | Frt LH Bumper Fog Lamp                 |     |    |     |
| 1020 | 995080 | Frt RH Bumper Fog Lamp                 |     |    |     |
| 1021 | 991793 | Frt Grille                             | BR  | ✓  |     |
| 1022 | 991328 | Frt Grille Emblem                      |     |    |     |
| 1023 | 991799 | Frt Grille Chrome Moulding             |     |    |     |
| 1024 | 991222 | Frt Apron Panel                        |     |    |     |
| 1025 | 992013 | Frt Support Panel                      |     |    |     |
| 1026 | 992025 | Frt Support Panel Top Garnish Cover    |     |    |     |
| 1027 | 992416 | Horn                                   |     |    |     |
| 1028 | 991277 | Frt Brace Panel                        |     |    |     |
| 1029 | 995153 | Frt LH Headlamp Assy                   |     |    |     |
| 1030 | 991821 | Frt RH Headlamp Assy                   |     |    |     |
| 1031 | 995088 | Frt LH Side Lamp                       |     |    |     |
| 1032 | 995089 | Frt RH Side Lamp                       |     |    |     |
| 1033 | 990248 | Bonnet                                 |     |    |     |
| 1034 | 991328 | Bonnet Emblem                          |     |    |     |
| 1035 | 990287 | Bonnet Lock                            |     |    |     |
| 1036 | 990285 | Bonnet Insulator                       |     |    |     |
| 1037 | 990273 | Bonnet Hinge                           |     |    |     |
| 1038 | 990261 | Bonnet Damper                          |     |    |     |
| 1039 | 990305 | Bonnet Rubber                          |     |    |     |
| 1040 | 990252 | Bonnet Cable                           |     |    |     |
| 1041 | 990311 | Bonnet Stand                           |     |    |     |
| 1042 | 990119 | Air Con Condenser                      |     |    |     |
| 1043 | 990122 | Air Con Fan Assy                       |     |    |     |
| 1044 | 990134 | Air Con Suction Pipe (Low Pressure)    |     |    |     |
| 1045 | 990118 | Air Con Suction Hose                   |     |    |     |
| 1046 | 990133 | Air Con Discharge Pipe (High Pressure) |     |    |     |
| 1047 | 990114 | Air Con Discharge Hose                 |     |    |     |
| 1048 | 990149 | Air Con Liquid Pipe                    |     |    |     |
| 1049 | 995066 | Air Con Receiver Drier                 |     |    |     |
| 1050 | 990111 | Air Con Compressor Assy                |     |    |     |
| 1051 | 995294 | Air Con Belt                           |     |    |     |
| 1052 | 995074 | Radiator                               |     |    |     |
| 1053 | 992738 | Radiator Cowling                       |     |    |     |
| 1054 | 992742 | Radiator Fan Assy                      |     |    |     |
| 1055 | 992745 | Radiator Fan Clutch                    |     |    |     |
| 1056 | 992758 | Radiator Hose Top                      |     |    |     |
| 1057 | 992757 | Radiator Hose Bottom                   |     |    |     |
| 1058 | 992741 | Radiator Expansion Tank                |     |    |     |
| 1059 | 990151 | Air Duct                               |     |    |     |
| 1060 | 990070 | Air Cleaner Assy                       |     |    |     |
| 1061 | 990056 | Air Cleaner Hose                       |     |    |     |
| 1062 | 990089 | Air Cleaner Resonator                  |     |    |     |
| 1063 | 991712 | Frt Exhaust Manifold                   |     |    |     |
| 1064 | 991713 | Frt Exhaust Manifold Cover             |     |    |     |
| 1065 | 991054 | Frt Exhaust Manifold Sensor (Oxygen)   |     |    |     |
| 1066 | 991714 | Front Exhaust Pipe                     |     |    |     |
| 1067 | 990219 | Battery                                |     |    |     |
| 1068 | 990224 | Battery Cover                          |     |    |     |
| 1069 | 990223 | Battery Bracket                        |     |    |     |
| 1070 | 990229 | Battery Tray                           |     |    |     |

Vehicle No: 51P 4248M

| NAC  | INC    | Item                         | CON | AC | Qty |
|------|--------|------------------------------|-----|----|-----|
| 1071 | 992205 | Fuse Box                     |     |    |     |
| 1072 | 994011 | Relay Box                    |     |    |     |
| 1073 | 995053 | Wiper Washer Tank            |     |    |     |
| 1074 | 995052 | Wiper Washer Tank Motor      |     |    |     |
| 1075 | 990159 | Alternator Assy              |     |    |     |
| 1076 | 990160 | Alternator Belt              |     |    |     |
| 1077 | 992688 | Power Steering Pump          |     |    |     |
| 1078 | 992669 | Power Steering Belt          |     |    |     |
| 1079 | 994431 | Power Steering Cooler Pipe   |     |    |     |
| 1080 | 992692 | Power Steering Hose          |     |    |     |
| 1081 | 990010 | ABS Pump Control Unit        |     |    |     |
| 1082 | 990427 | Brake Master Pump Assy       |     |    |     |
| 1083 | 990403 | Brake Booster Pump Assy      |     |    |     |
| 1084 | 991005 | Engine Top Cover             |     |    |     |
| 1085 | 991011 | Engine Under Cover           |     |    |     |
| 1086 | 990946 | Engine Mounting              |     |    |     |
| 1087 | 990949 | Engine Mounting Frt          |     |    |     |
| 1088 | 990950 | Engine Mounting LH           |     |    |     |
| 1089 | 990952 | Engine Mounting RH           |     |    |     |
| 1090 | 990951 | Engine Mounting Rear         |     |    |     |
| 1091 | 992234 | Gear Box Mounting            |     |    |     |
| 1092 | 991520 | Frt LH Chassis Member        |     |    |     |
| 1093 | 991520 | Frt RH Chassis Member        |     |    |     |
| 1094 | 990728 | Frt Vertical Cross Member    |     |    |     |
| 1095 | 991863 | Frt Lower Cross Member       |     |    |     |
| 1096 | 995070 | Frt LH Fender                |     |    |     |
| 1097 | 995072 | Frt LH Fender Inner Panel    |     |    |     |
| 1098 | 995147 | Frt LH Fender Lamp           |     |    |     |
| 1099 | 995148 | Frt LH Fender Protector      |     |    |     |
| 1100 | 991740 | Frt LH Fender Inner Shield   |     |    |     |
| 1101 | 995179 | Frt LH Mudflap               |     |    |     |
| 1102 | 995170 | Frt LH Wheel Rim             |     |    |     |
| 1103 | 994025 | Frt LH Rim Cover             |     |    |     |
| 1104 | 995065 | Frt LH Tyre                  |     |    |     |
| 1105 | 995071 | Frt RH Fender                |     |    |     |
| 1106 | 991739 | Frt RH Fender Inner Panel    |     |    |     |
| 1107 | 991744 | Frt RH Fender Lamp           |     |    |     |
| 1108 | 991752 | Frt RH Fender Protector      |     |    |     |
| 1109 | 991740 | Frt RH Fender Inner Shield   |     |    |     |
| 1110 | 991884 | Frt RH Mudflap               |     |    |     |
| 1111 | 992087 | Frt RH Wheel Rim             |     |    |     |
| 1112 | 994025 | Frt RH Rim Cover             |     |    |     |
| 1113 | 995065 | Frt RH Tyre                  |     |    |     |
| 1114 | 992093 | Frt Windscreen Glass         |     |    |     |
| 1115 | 992117 | Frt Windscreen Rubber        |     |    |     |
| 1116 | 992108 | Frt Windscreen Moulding      |     |    |     |
| 1117 | 992098 | Frt Windscreen Sealant       |     |    |     |
| 1118 | 991019 | ERP Bracket                  |     |    |     |
| 1119 | 991020 | ERP Unit                     |     |    |     |
| 1120 | 992140 | Frt Wiper Arm                |     |    |     |
| 1121 | 992142 | Frt Wiper Blade              |     |    |     |
| 1122 | 995045 | Wiper Panel Garnish          |     |    |     |
| 1123 | 991126 | Firewall Panel               |     |    |     |
| 1124 | 990753 | Dashboard Assy               |     |    |     |
| 1125 | 992282 | Glove Box Cover              |     |    |     |
| 1126 | 992281 | Glove Box Compartment        |     |    |     |
| 1127 | 994483 | Steering Wheel Airbag        |     |    |     |
| 1128 | 994485 | Steering Wheel Airbag Sensor |     |    |     |
| 1129 | 990749 | Dashboard Airbag             |     |    |     |
| 1130 | 990750 | Dashboard Airbag Sensor      |     |    |     |
| 1131 | 990029 | Airbag Control Unit          |     |    |     |
| 1132 | 990864 | Frt Driver Seat              |     |    |     |
| 1133 | 991922 | Frt RH Seat Belt Assy        |     |    |     |
| 1134 | 991899 | Frt Passenger Seat           |     |    |     |
| 1135 | 995182 | Frt LH Seat Belt Assy        |     |    |     |
| 1136 | 990247 | Sticker                      |     |    |     |

No. of Items: 4

ADDRESS: TACAM

16/2/12

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22237

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1468/2019/NS  
Date : 12-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SJZ 91 G**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Goh Ai Tee  
Address : Blk 531 Jurong West Street 52  
#11-421  
Singapore 640531  
Telephone : (HP)+65 97450889  
Type of Claim : Third Party Claims  
Policy No. : 1900166952  
Vehicle No : **SMP 4248 M**  
Model Code : A4 Sedan 2.0 TFSI 8W  
Model / Year : Sep-19  
Engine No : CVK 082687  
Chassis No : WAUZZZF47KA077888  
Mileage : -  
Date In : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 8-Dec-19  
Place of Accident : Blk 531 Jurong West Street 52 Carpark

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMP 4248 M

| S/n                         | Nature of Jobs                                                                                                                                    |        | Estimated Charges  | Surveyor's Recommendations |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|----------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N \$ | 480.00             | / NEC ✓                    |
| 2                           | To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.                                        | \$     | 1,400.00           | 500.00 ✓                   |
| 3                           | To respray front bumper.                                                                                                                          | \$     | 900.00             | 550.00 ✓                   |
| 4                           | To carry out diagnostic checks.                                                                                                                   | S/N \$ | 192.00             | NEC ✓                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                   | :      | <b>\$ 2,972.00</b> |                            |



# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMP 4248 M

| S/N | Parts Description                           |        | Damaged Parts & Prices |             |
|-----|---------------------------------------------|--------|------------------------|-------------|
|     |                                             |        | S/Nett                 | Remarks     |
| 1   | FRONT BUMPER                                | \$     | 1,999.00               | ? X NDA     |
| 2   | FRONT BUMPER FIXING PARTS                   | \$     | 531.00                 | NNX         |
| 3   | FRONT BUMPER GRILLE - CENTRE                | \$     | 178.00                 | BR ✓ 143.40 |
| 4   | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | \$     | 191.00                 | ? X } NDA   |
| 5   | RADIATOR GRILLE                             | \$     | 1,227.00               | ? X }       |
| 6   | FRONT BUMPER AIR GUIDE GRILLE - LH / RH     | 2 \$   | 246.00                 | NNX         |
| 7   | FRONT BUMPER FOAM FILLER PIECE              | \$     | 113.00                 | ? X NDA     |
| 8   | FRONT BUMPER CARRIER                        | \$     | 733.00                 | NNX         |
| 9   | FRONT BUMPER COVER                          | \$     | 116.00                 | ? X }       |
| 10  | CAUTION SIGN STICKER                        | NEC \$ | 13.00                  | ? X } NDA   |
| 11  | AIRCOR STICKER                              | NEC \$ | 7.00                   | ? X }       |
| 12  | LOCK CARRIER BRACKET                        | \$     | 125.00                 | NNX         |
| 13  | FRONT BUMPER SUPPORT - LH / RH              | 2 \$   | 52.00                  | NNX         |
| 14  | FRONT PARKING AID SENSOR - INNER / OUTER    | 2 \$   | 462.00                 | } NNX       |
| 15  | FRONT PARKING AID SEAL RING                 | 4 \$   | 12.00                  |             |
| 16  | RADIATOR AIR GUIDE - L H / RH               | 2 \$   | 50.00                  |             |
| 17  | RADIATOR AIR GUIDE - LH / RH                | 2 \$   | 22.00                  |             |
| 18  | RADIATOR AIR GUIDE - UPPER                  | \$     | 15.00                  | NNX         |
| 19  | RADIATOR AIR GUIDE - LOWER                  | \$     | 19.00                  |             |
| 20  | FRONT NO PLATE                              | S/N \$ | 40.00                  | BT ✓ 40     |
| 21  | SUNDRIES                                    | \$     | 200.00                 | ? X NDA     |

**TOTAL SPARE PARTS CHARGES**

: \$ 6,351.00

**TOTAL LABOUR CHARGES**

\$ 2,972.00

**GRAND TOTAL**

\$ 9,323.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved



# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

*21/12/19*

Name : *TG Lim*  
Surveyed Date : *13/12/19*  
Authorised Date :  
Excess Cost : *TBA*  
Liability :  
Remarks : *NOT Authorised*

*Repair days 3*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22237

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1468/2019/NS  
Date : 12-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SJZ 91 G**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Mr.Lim,*

*4 days - ok - Jy - 12 Feb 2020*

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mdm Goh Ai Tee  
**Address** : Blk 531 Jurong West Street 52  
#11-421  
Singapore 640531  
**Telephone** : (HP)+65 97450889  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1900166952  
**Vehicle No** : **SMP 4248 M**  
**Model Code** : A4 Sedan 2.0 TFSI 8W  
**Model / Year** : Sep-19  
**Engine No** : CVK 082687  
**Chassis No** : WAUZZZF47KA077888  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 8-Dec-19  
**Place of Accident** : Blk 531 Jurong West Street 52 Carpark

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMP 4248 M

| S/n                         | Nature of Jobs                                                                                                                                    |          | Estimated<br>Charges | Surveyor's<br>Recommendations |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer Assy and front parking aid. | S/N \$   | 480.00               | \$ 480.00                     |
| 2                           | To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.                                        | \$       | 1,400.00             | \$ 500.00                     |
| 3                           | To respray front bumper.                                                                                                                          | \$       | 900.00               | \$ 550.00                     |
| 4                           | To carry out diagnostic checks.                                                                                                                   | S/N \$   | 192.00               | \$ 192.00                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                   | <b>:</b> | <b>\$ 2,972.00</b>   | <b>\$ 1,722.00</b>            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMP 4248 M

| S/N                              | Parts Description                           | Damaged Parts & Prices |                    |
|----------------------------------|---------------------------------------------|------------------------|--------------------|
|                                  |                                             | S/Nett                 | Remarks            |
| 1                                | FRONT BUMPER                                | \$ 1,999.00            |                    |
| 2                                | FRONT BUMPER FIXING PARTS                   | \$ 531.00              |                    |
| 3                                | FRONT BUMPER GRILLE - CENTRE                | \$ 178.00              | \$ 142.40          |
| 4                                | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | \$ 191.00              |                    |
| 5                                | RADIATOR GRILLE                             | \$ 1,227.00            |                    |
| 6                                | FRONT BUMPER AIR GUIDE GRILLE - LH / RH     | 2 \$ 246.00            |                    |
| 7                                | FRONT BUMPER FOAM FILLER PIECE              | \$ 113.00              |                    |
| 8                                | FRONT BUMPER CARRIER                        | \$ 733.00              |                    |
| 9                                | FRONT BUMPER COVER                          | \$ 116.00              |                    |
| 10                               | CAUTION SIGN STICKER                        | NEC \$ 13.00           |                    |
| 11                               | AIRCOR STICKER                              | NEC \$ 7.00            |                    |
| 12                               | LOCK CARRIER BRACKET                        | \$ 125.00              |                    |
| 13                               | FRONT BUMPER SUPPORT - LH / RH              | 2 \$ 52.00             |                    |
| 14                               | FRONT PARKING AID SENSOR - INNER / OUTER    | 2 \$ 462.00            |                    |
| 15                               | FRONT PARKING AID SEAL RING                 | 4 \$ 12.00             |                    |
| 16                               | RADIATOR AIR GUIDE - L H / RH               | 2 \$ 50.00             |                    |
| 17                               | RADIATOR AIR GUIDE - LH / RH                | 2 \$ 22.00             |                    |
| 18                               | RADIATOR AIR GUIDE - UPPER                  | \$ 15.00               |                    |
| 19                               | RADIATOR AIR GUIDE - LOWER                  | \$ 19.00               |                    |
| 20                               | FRONT NO PLATE                              | S/N \$ 40.00           | \$ 40.00           |
| 21                               | SUNDRIES                                    | \$ 200.00              |                    |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                             | <b>\$ 6,351.00</b>     | <b>\$ 182.40</b>   |
| <b>TOTAL LABOUR CHARGES</b>      |                                             | <b>\$ 2,972.00</b>     | <b>\$ 1,722.00</b> |
| <b>GRAND TOTAL</b>               |                                             | <b>\$ 9,323.00</b>     | <b>\$ 1,904.40</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Premium  
Automobiles  
Pte Ltd

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 12 February 2020 11:27 AM  
**To:** 'jiayee.yap@premiumauto.com.sg'; SUR; Admin A; CS A Team  
**Cc:** 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'  
**Subject:** RE: FINAL REVISION -SMP4248M - OD AIG - SURVEYED 13 DEC 19

Dear Jia Yee,

Confirm repair cost of \$1904.40 before GST @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>  
**Sent:** Wednesday, 12 February 2020 10:48 AM  
**To:** Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>  
**Subject:** FINAL REVISION -SMP4248M - OD AIG - SURVEYED 13 DEC 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$1904.40 @ 3 days of repairs.

Your early closure is well appreciated.

Thanks & Best Regard

JiaYee Yap

Claims Administrator

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SMP 4248 M**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/1468/2019/NH

9<sup>th</sup> March 2020

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

total pages

**RE: INSURANCE CLAIM FOR SMP 4248 M, Audi A4 SEDAN 2.0 TFSI.**

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SMP 4248 M**, claimant, **Ms. Goh Ai Tee**, please find the related document per attached.

1. A copy of the Original invoice no. 85014955 – S\$ 2,037.71.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encl  
AIG – SMP 4248 M



# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Main Telephone 6388 2323  
Main Telefax 6841 1183

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 1 16:01

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

|                                                                                                                               |                                                                            |                                                                                                                                                |
|-------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD<br>MOTOR CLAIM DEPT<br>AIG BUILDING<br>78 SHENTON WAY<br>#07-16<br>SINGAPORE 079120 079120 | Invoice No: 85014955<br>Date : 05/03/2020<br>Order : SMP4248M<br>Term : 30 | Account: A0006 (T 0)<br>AIG ASIA PACIFIC INSURANCE PTE LTD<br>MOTOR CLAIM DEPT<br>AIG BUILDING<br>78 SHENTON WAY<br>#07-16<br>SINGAPORE 079120 |
|-------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|

|                                             |                            |                    |                |
|---------------------------------------------|----------------------------|--------------------|----------------|
| Regn No: SMP4248M (V 42500)                 | Regn Date: 25/09/2019      | Mileage: 4636      | WIP No.: 22237 |
| Model: A4 SEDAN 2.0 TFSI 8W2ADG             | Chassis: WAU2ZZF47KA077888 | Engine: CVK 082687 | Dept: u        |
| You have been assisted by :- UB-Nora ( 11 ) |                            |                    |                |

|   |                | Details                                                                                                                                                     | Qty    | Unit Price | Amount |
|---|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|--------|
| S | SUBLET         | M:<br>TO SUPPLY VEHICLE NUMBER PLATE                                                                                                                        | 40.00  | 1.00       | 40.00  |
| S | BODYWORK       | M:<br>TO REMOVE,CHECK AND REINSTALL FRONT WIRE<br>HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE<br>TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY<br>AND FRONT PARKING AID | 480.00 | 1.00       | 480.00 |
| S | BODYWORK       | M:<br>TO DISMANTLE AND REPAIR FRONT BUMPER.<br>REORGANISE CRASH MANAGEMENT COMPONENTS.<br>REINSTALL ALL PARTS REMOVED                                       | 500.00 | 1.00       | 500.00 |
| S | BODYWORK       | M:<br>TO RESPRAY FRONT BUMPER                                                                                                                               | 550.00 | 1.00       | 550.00 |
| S | BODYWORK       | M:<br>TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                         | 192.00 | 1.00       | 192.00 |
| X | A8W0807683 9B9 | GRILLE Less 020%                                                                                                                                            | 1.00   | 178.00     | 142.40 |

Parts 142.40  
Labour 0.00  
Sublet 1,762.00  
Menus 0.00  
Lubricant 0.00



|                    |                 |
|--------------------|-----------------|
| Sub-Total          | 1,904.40        |
| 7% GST             | 133.31          |
| <b>Grand Total</b> | <b>2,037.71</b> |

Received by

For & on behalf of  
Premium Automobiles Pte Ltd

# Premium Automobiles

## Telefax

to AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Motor Claims Dept  
Yr Ref: SMP4248M

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/1468/2019/TG  
30 DEC 2019

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

total pages

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 2.0 TFSI 8W  
Vehicle Chassis No. : WAUZZZF47KA077888  
Vehicle Regn No. : SMP 4248 M  
Vehicle Mileage : 4638 KM  
Vehicle Owner : Ms. Goh Ai Tee (Wu Aidi)  
Certificate No : 1900166952  
Own Damage Excess : Waived  
Accident Date : 8/12/2019  
Place : Blk 531 Jurong West Street 52 Carpark  
Repair Cost : \$ 2037.71  
WIP No. : 22237  
Repairer's Name : Premium Automobiles Pte Ltd


Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733  
  
Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

  
bpm  
30 Dec 2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
|------|-------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 15 Dec 2019 |               | 23 Dec 2019<br>14:05<br><a href="#">Edit Adj Rpt</a> | <b>S\$1,904.40</b><br><a href="#">Edit Estimates</a> | <b>S\$1,904.40</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                   |                                                                                                                      |                        |                                                                             |
|-------------------|----------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|
| Insured:          | GOH AI TEE, ID: S7805573A, Tel: +6597450889, Email: AITEE78@GMAIL.COM                                                |                        |                                                                             |
| Vehicle Reg. No.: | SMP4248M                                                                                                             | Date of Loss:          | 08/12/2019 22:00 - :59<br>[2 Months and 13 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | OD / 9874529372SG                                                                                                    | Policy/Cover Note No.: | 1900166952 (Comprehensive)                                                  |
|                   |                                                                                                                      | Excess:                | S\$0.00                                                                     |
| Repairer:         | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911                                |                        |                                                                             |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Lim, Sheng Yang] ShengYang.Lim@aig.com |                        |                                                                             |
| Adjuster:         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 03/01/2020]     |                        |                                                                             |
| Driver/Custodian: | GOH AI TEE (41 / Female), NRIC: S7805573A, Tel: +6597450889 Email: AITEE78@GMAIL.COM                                 |                        |                                                                             |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (27/12/2019): Alert - Adj Mandate Approved (S\$1940.00) - SMP4248M - Claim Handler: Lim, Sheng ...
- AIG\_SG (26/12/2019): SMP4248M / OD / 08/12/2019 / Coverage & Excess update

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

\*SMP4248M (9874529372SG)  
 OD  
 Dec 8 2019 10:00PM  
 [GOH AI TEE]  
 Premium Automobiles Pte Ltd

|                    |                 |  |                                                        |  |  |                    |  |  |              |  |  |              |  |   |            |       |                                     |  |
|--------------------|-----------------|--|--------------------------------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|---|------------|-------|-------------------------------------|--|
| Upload Documents   |                 |  | Upload Photos                                          |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |   | View       |       | View in Browser                     |  |
| Video              |                 |  |                                                        |  |  |                    |  |  |              |  |  |              |  |   | 1 per page |       | <input checked="" type="checkbox"/> |  |
| No                 | Finalized On    |  | Premium Automobiles Pte Ltd (UBI)                      |  |  |                    |  |  |              |  |  |              |  |   | Thumbnail  | Print |                                     |  |
| 1                  | 09/12/19 16:26  |  | Video - Accident<br>[Linked Accident Report Documents] |  |  |                    |  |  |              |  |  |              |  | 1 | Load MP4   |       |                                     |  |
| Assessment Reports |                 |  |                                                        |  |  |                    |  |  |              |  |  |              |  |   | 1 per page |       | <input checked="" type="checkbox"/> |  |
| No                 | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)                      |  |  |                    |  |  |              |  |  |              |  |   | Thumbnail  | Print |                                     |  |
| 1                  | 23/12/19 15:48  |  | Adjuster Immediate Advice                              |  |  |                    |  |  |              |  |  |              |  | 1 | Load HTM   |       |                                     |  |
| Photos/Images      |                 |  |                                                        |  |  |                    |  |  |              |  |  |              |  |   | 3 per page |       | <input checked="" type="checkbox"/> |  |
| No                 | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ)                      |  |  |                    |  |  |              |  |  |              |  |   | Thumbnail  | Print |                                     |  |
| 1                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 2                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 3                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 4                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 5                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 6                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 7                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 8                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 9                  | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 10                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 11                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 12                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 13                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 14                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 15                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 16                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 17                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 18                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 19                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 20                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 21                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 22                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 23                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 24                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 25                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 26                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 27                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 28                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |
| 29                 | 23/12/19 15:36  |  | General View                                           |  |  |                    |  |  |              |  |  |              |  | 1 | Load JPG   |       | <input checked="" type="checkbox"/> |  |

| Video         |                 |                                   | 1 per page ▼                                                                                 | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Finalized On    | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                    | Print                               |
| 30            | 23/12/19 15:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31            | 23/12/19 15:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32            | 23/12/19 15:36  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |                                   | 1 per page ▼                                                                                 | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                    | Print                               |
| 1             | 23/12/19 15:49  | Singapore Accident Statement      |  Load PDF |                                     |
| 2             | 23/12/19 15:49  | Police Report                     |  Load PDF |                                     |
| 3             | 23/12/19 15:50  | Certificate of Insurance          |  Load PDF |                                     |
| 4             | 23/12/19 15:51  | Insured's Driving License         |  Load PDF |                                     |
| 5             | 23/12/19 15:52  | SG CAR MART                       |  Load PDF |                                     |
| 6             | 23/12/19 15:52  | MARK ESTIMATE                     |  Load PDF |                                     |
| 7             | 23/12/19 15:54  | LTA                               |  Load PDF |                                     |
| 8             | 12/03/20 16:43  | DISCHARGE VOUCHER                 |  Load PDF |                                     |
| 9             | 12/03/20 16:43  | WORKSHOP INVOICE                  |  Load PDF |                                     |

## Linked Accident Report Documents

| Video              |                |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                      | Print                               |
| 1                  | 09/12/19 16:26 | Video - Accident                  |  Load MP4   |                                     |
| Assessment Reports |                |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                      | Print                               |
| 1                  | 09/12/19 16:30 | Accident Statement                |  Load HTM |                                     |
| 2                  | 23/12/19 11:00 | Addendum Sheet                    |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 23/12/19 11:03 | Accident Statement Addm. #1       |  Load HTM |                                     |
| 4                  | 26/12/19 17:51 | Addendum Sheet                    |  Load JPG | <input checked="" type="checkbox"/> |
| 5                  | 26/12/19 17:52 | Accident Statement Addm. #2       |  Load HTM |                                     |
| Photos/Images      |                |                                   | 3 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                      | Print                               |
| 1                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 4                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 5                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 6                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 7                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 8                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 9                  | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 10                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 11                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 12                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 13                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 14                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 15                 | 09/12/19 16:24 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 16                 | 09/12/19 16:25 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 17                 | 09/12/19 16:25 | Accident Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 18                 | 09/12/19 16:25 | Police Report                     |  Load JPG | <input checked="" type="checkbox"/> |
| 19                 | 09/12/19 16:25 | Police Report                     |  Load JPG | <input checked="" type="checkbox"/> |



| Video         |                |                                   | 1 per page ▼                                                                                 | ✓     |
|---------------|----------------|-----------------------------------|----------------------------------------------------------------------------------------------|-------|
| No            | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                    | Print |
| 20            | 09/12/19 16:25 | Police Report                     |  Load JPG | ✓     |
| Documentation |                |                                   | 1 per page ▼                                                                                 | ✓     |
| No            | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail                                                                                    | Print |
| 1             | 09/12/19 16:28 | Sketch Plan                       |  Load JPG | ✓     |
| 2             | 09/12/19 16:28 | Sketch Plan #2                    |  Load JPG | ✓     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CC3/AIG19021735/BVD3S2  
Date: 12/03/2020

## REFERENCE

Insured/Claimant: GOH AI TEE Policy No: 1900166952  
Date of Loss: 08/12/2019 Nature of Claim: OD Claim No: 9874529372SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMP4248M  
Make & Model: AUDI A4, 2.0 (A)  
Reg. Date: 25/09/2019 (Man. Year: 2019)  
Colour: Red  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$140,000.00  
Sum Insured (S\$): Market Value/New Car Price

Engine No: CVK082687  
Chassis No: WAUZZZF47KA077888  
Odometer: 4085 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm  
Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 6,351.00        | 182.40          | 6,168.60        | 97.13        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 2,972.00        | 1,722.00        | 1,250.00        | 42.06        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>9,323.00</b> | <b>1,904.40</b> | <b>7,418.60</b> | <b>79.57</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>652.61</b>   | <b>133.31</b>   | <b>519.30</b>   | <b>79.57</b> |
| <b>Nett Amount (S\$)</b>      | <b>9,975.61</b> | <b>2,037.71</b> | <b>7,937.90</b> | <b>79.57</b> |

## INSPECTION

Date of Assignment: 23/12/2019  
Date Inspected: 13/12/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

| No.                          | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount     |
|------------------------------|-----|----------|----------------------------------------------|---------------|-------------|------------|
| 1                            | 1   |          | *FRONT BUMPER                                | Not Damaged   | 1,999.00 FS | *- FS      |
| 2                            | 1   |          | *FRONT BUMPER FIXING PARTS                   | Not Necessary | 531.00 FS   | *- FS      |
| 3                            | 1   |          | *FRONT BUMPER GRILLE - CENTRE                | Broken        | 178.00 FS   | *142.40 FS |
| 4                            | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Not Damaged   | 191.00 FS   | *- FS      |
| 5                            | 1   |          | *RADIATOR GRILLE                             | Not Damaged   | 1,227.00 FS | *- FS      |
| 6                            | 2   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH / RH     | Not Necessary | 246.00 FS   | *- FS      |
| 7                            | 1   |          | *FRONT BUMPER FOAM FILLER PIECE              | Not Damaged   | 113.00 FS   | *- FS      |
| 8                            | 1   |          | *FRONT BUMPER CARRIER                        | Not Necessary | 733.00 FS   | *- FS      |
| 9                            | 1   |          | *FRONT BUMPER COVER                          | Not Damaged   | 116.00 FS   | *- FS      |
| 10                           | 1   |          | *CAUTION SIGN STICKER                        | Not Damaged   | 13.00 FS    | *- FS      |
| 11                           | 1   |          | *AIRCOR STICKER                              | Not Damaged   | 7.00 FS     | *- FS      |
| 12                           | 1   |          | *LOCK CARRIER BRACKET                        | Not Necessary | 125.00 FS   | *- FS      |
| 13                           | 2   |          | *FRONT BUMPER SUPPORT - LH / RH              | Not Necessary | 52.00 FS    | *- FS      |
| 14                           | 2   |          | *FRONT PARKING AIR SENSOR - INNER / OUTER    | Not Necessary | 462.00 FS   | *- FS      |
| 15                           | 4   |          | *FRONT PARKING AID SEAL RING                 | Not Necessary | 12.00 FS    | *- FS      |
| 16                           | 2   |          | *RADIATOR AIR GUIDE - LH / RH                | Not Necessary | 50.00 FS    | *- FS      |
| 17                           | 2   |          | *RADIATOR AIR GUIDE - LH / RH                | Not Necessary | 22.00 FS    | *- FS      |
| 18                           | 1   |          | *RADIATOR AIR GUIDE - UPPER                  | Not Necessary | 15.00 FS    | *- FS      |
| 19                           | 1   |          | *RADIATOR AIR GUIDE - LOWER                  | Not Necessary | 19.00 FS    | *- FS      |
| 20                           | 1   |          | *FRONT NO PLATE                              | Bent          | 40.00 FS    | *40.00 FS  |
| 21                           | 1   |          | *SUNDRIES                                    | Not Damaged   | 200.00 FS   | *- FS      |
| F=Franchise part. S=SpcNett. |     |          |                                              |               |             |            |
| Total Parts (S\$)            |     |          |                                              |               | 6,351.00    | 182.40     |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                       | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                   |          |                 |                 |
| 1                              | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | New      | 480.00          | 480.00          |
| 2                              | TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                                        | New      | 1,400.00        | 500.00          |
| 3                              | TO RESPRAY FRONT BUMPER.                                                                                                                          | New      | 900.00          | 550.00          |
| 4                              | TO CARRY OUT DIAGNOSTIC CHECKS.                                                                                                                   | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                   |          | <b>2,972.00</b> | <b>1,722.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >