

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22237

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1468/2019/NS
Date : 12-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : SJZ 91 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Goh Ai Tee
Address : Blk 531 Jurong West Street 52
#11-421
Singapore 640531
Telephone : (HP)+65 97450889
Type of Claim : Third Party Claims
Policy No. : 1900166952
Vehicle No : **SMP 4248 M**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-19
Engine No : CVK 082687
Chassis No : WAUZZZF47KA077888
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Dec-19
Place of Accident : Blk 531 Jurong West Street 52 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMP 4248 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	/ NEC
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,400.00	500.00
3	To respray front bumper.	\$	900.00	550.00
4	To carry out diagnostic checks.	S/N \$	192.00	NEC
TOTAL LABOUR CHARGES		:	\$ 2,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4248 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER		\$ 1,999.00	?
2	FRONT BUMPER FIXING PARTS		\$ 531.00	NNX
3	FRONT BUMPER GRILLE - CENTRE		\$ 178.00	BR✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 191.00	?
5	RADIATOR GRILLE		\$ 1,227.00	?
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 246.00	NNX
7	FRONT BUMPER FOAM FILLER PIECE		\$ 113.00	?
8	FRONT BUMPER CARRIER		\$ 733.00	NNX
9	FRONT BUMPER COVER		\$ 116.00	?
10	CAUTION SIGN STICKER	NEC	\$ 13.00	?
11	AIRCOR STICKER	NEC	\$ 7.00	?
12	LOCK CARRIER BRACKET		\$ 125.00	NNX
13	FRONT BUMPER SUPPORT - LH / RH	2	\$ 52.00	NNX
14	FRONT PARKING AID SENSOR - INNER / CUTER	2	\$ 462.00	} NNX
15	FRONT PARKING AID SEAL RING	4	\$ 12.00	
16	RADIATOR AIR GUIDE - L H / RH	2	\$ 50.00	} NNX
17	RADIATOR AIR GUIDE - LH / RH	2	\$ 22.00	
18	RADIATOR AIR GUIDE - UPPER		\$ 15.00	
19	RADIATOR AIR GUIDE - LOWER		\$ 19.00	
20	FRONT NO PLATE	S/N	\$ 40.00	BT✓
21	SUNDRIES		\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ **6,351.00**

TOTAL LABOUR CHARGES

\$ **2,972.00**

GRAND TOTAL

\$ 9,323.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : TGuin
Surveyed Date : 13/12/19
Authorised Date :
Excess Cost : TBA
Liability :
Remarks : NOT Authorised

Repair days 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant