

15/5/2010

INS. CASE OWNER:

Jas

CC 4 / ASM190

1745, A

LKK:

IDAC:

Surveyor:

Adrian

DOI:


10/1/19

Date / Time:

10/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKS 424J

Name of Insured:

KOMUO CATE KENTON

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A:

8/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MUMUUED YABEN 2/0 BUKARI

Driver Tel No.:

(V/L: YES / NO)


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SMF 7/1/19



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fong
Motors


INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
12/1/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA/ GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

4,100.00

Loss of Rental (LOR):

\$S

—

(

— days)

Loss of Use (LOU):

\$S

360.00 (\$ 60.00 x 6 days)

Loss of Income (LOI):

\$S

—

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$S

7.45

Medical:

\$S

Disbursement:

\$S

—

(e.g. Tow/ Independent)

Legal Cost

\$S

—

Total:

\$S

4,467.45

Global Sum \$S:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

\$S

4,467.45

Name 1:

Fong Motors

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 350.00

AC-9K
01/04/2020

FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883

Tel: 6747 6388, Email: fongmotors@gmail.com

Company Reg No. 068972/00L

Terence Tan
Blk 119 Toa Payoh Lor 1
#09-449
Singapore 310119

TP AXA
Xiao Tong

Estimate

Code: FMSMF7317E
Date: 10/9/2019
Vehicle No.: SMF7317E
Model: HONDA JAZZ
CHASSIS/ENG#: JHMGK5850JX20955

PARTS

S/N Particular	Quantity	Unit Price	Amount
1 Rear Tail Gate <i>Dented</i>	1	\$799.60	\$799.60 ✓
2 Rear Tail Gate Hinge L/R <i>2 New</i>	2	\$35.50	\$71.00 ✓
3 Rear Tail Gate Damper L/R	2	\$146.20	\$292.40 +
4 Rear Tail Gate Rubber Weather Strip <i>ut</i>	2	\$105.30	\$210.60 10530
5 Rear Tail Gate Guide Stopper <i>New</i>	2	\$7.50	\$15.00 +
6 Rear Tail Gate Chrome Garnish <i>2 New</i>	1	\$351.30	\$351.30 +
7 Rear Tail Gate Chrome Garnish Clips	4	\$6.50	\$26.00 +
8 Rear Tail Gate Jazz Emblem <i>New</i>	1	\$45.40	\$45.40 ✓
9 Rear Tail Gate Mechanism Lock <i>Damaged</i>	1	\$209.20	\$209.20 ✓
10 Rear Tail Gate Inner Handle <i>Not new</i>	1	\$75.20	\$75.20 +
11 Rear Tail Gate Inner trimboard <i>Cracked</i>	1	\$168.30	\$168.30 ✓
12 Rear Tail Gate Windscreen Glass Moulding <i>New</i>	1	\$953.70	\$953.70 +
13 Rear Tail Gate Windscreen Glass Moulding <i>New</i>	1	\$45.00	\$45.00 ✓
14 Rear Tail Gate Wiper Motor <i>New</i>	1	\$238.20	\$238.20 +
15 Rear Tail Lamp L/R <i>Cracked</i>	2	\$252.30	\$504.60 ✓
16 Rear Tail Lamp Panel L/R <i>Reps</i>	2	\$603.60	\$1,207.20 +
17 Rear Tail Lamp Stay Clips <i>New</i>	4	\$6.50	\$26.00 +
18 Rear End Panel <i>Dented</i>	1	\$393.50	\$393.50 ✓
19 Rear End Panel Inner Top Garnish <i>Dented</i>	1	\$75.80	\$75.80 ✓
20 Rear End Panel Inner Top Garnish Clips	4	\$6.50	\$26.00 ✓
21 Rear End Panel Antenna Sensor <i>over</i>	1	\$78.80	\$78.80 ✓
22 Rear Trunk Panel <i>Reps</i>	1	\$534.60	\$534.60 +
23 Rear Trunk Panel Insulator Mat <i>New</i>	1	\$189.70	\$189.70 +
24 Rear Trunk Panel Compartement Sponge <i>Dented</i>	1	\$193.20	\$193.20 ✓
25 Rear Trunk Panel Buzzer Sensor <i>Cracked</i>	1	\$87.80	\$87.80 -
26 Rear Bumper <i>Dented</i>	1	\$615.50	\$615.50 492
27 Rear Bumper Side Retainer L/R <i>New</i>	2	\$19.50	\$39.00 ✓
28 Rear Bumper Side Retainer L/R <i>New</i>	1	\$312.50	\$312.50 +
29 Rear Bumper Reverse Sensor <i>Damaged 2 pieces</i>	1	\$1,021.99	\$1,021.99 400
30 Rear Bumper Lower Garnish <i>Deformed</i>	1	\$212.10	\$212.10 ✓

31 Rear End Sub Chasis Panel L/R

Rep 5

2 \$295.30

\$590.60 X

3875.60

3100.48

SUBTOTAL BEFORE DISCOUNT	\$9,609.79
	\$1,921.96

Sub-total 1 \$7,687.83

1 Rear Number Plate	1	\$25.00	\$25.00 X
2 Rear Number Plate Garnish	1	\$50.00	\$50.00 +
3 Rear Tail Gate Inner trimboard clips	1	\$30.00	\$30.00 ✓
4 Rear Tail Gate Windscreen Glass Sealant	1	\$80.00	\$80.00 60
5 Rear Bumper Clips	1	\$30.00	\$30.00 ✓

120

Sub-total 2 \$215.00

Labour

1 To provide towing charge	1	\$50.00	\$50.00 X
2 To remove, reinstall electrical wiring harness, check lighting	1	\$60.00	\$60.00 30
3 To remove & refix/renew reverse sensor assy and rectify for proper functioning	1	\$80.00	\$80.00 50
4 To remove reinstall rear tailgate windscreen	1	\$100.00	\$100.00 ✓
5 To remove, reinstall roof top trim upholstery cushion seat trim garnish trim liner carpet	1	\$140.00	\$140.00 60
6 To remove rear seat dismantle	1	\$80.00	\$80.00 X
7 To respray painting on the change bodyparts repair portion and where consistent to the accident	1	\$1,200.00	\$1,200.00 80
8 To provide Labour, workmanship to change the above damage bodyparts, repair, re-align body structure, body alignments damage consistent to the accident	1	\$1,250.00	\$1,250.00 80
9 To dismantle repair and realign rear wiper linkage and motor assy to proper functioning	1	\$100.00	\$100.00 X
10 To apply anti-rust chemical on repair and replaced panel	1	\$120.00	\$120.00 60
11 To set the chasis bench, adjust and align front chasis alignment back into its original specifications	1	\$250.00	\$250.00 X

900

Labour Total	\$3,430.00
Parts & Labour Total	\$11,332.83

Total: 5120.48

2/57 H.K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: