

FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883

Tel: 6747 6388, Email: fongmotors@gmail.com

Company Reg No. 068972/00L

Terence Tan
Blk 119 Toa Payoh Lor 1
#09-449
Singapore 310119

TP AXA
Xiao Tong

Estimate

Code: FMSMF7317E
Date: 10/9/2019
Vehicle No.: SMF7317E
Model: HONDA JAZZ
CHASSIS/ENG#: JHMGK5850JX20955

PARTS

S/N Particular	Quantity	Unit Price	Amount
1 Rear Tail Gate <i>Dented</i>	1	\$799.60	\$799.60 ✓
2 Rear Tail Gate Hinge L/R <i>2 new</i>	2	\$35.50	\$71.00 ✓
3 Rear Tail Gate Damper L/R	2	\$146.20	\$292.40 +
4 Rear Tail Gate Rubber Weather Strip <i>lit</i>	2	\$105.30	\$210.60 10530
5 Rear Tail Gate Guide Stopper <i>new</i>	2	\$7.50	\$15.00 +
6 Rear Tail Gate Chrome Garnish <i>3 new</i>	1	\$351.30	\$351.30 +
7 Rear Tail Gate Chrome Garnish Clips	4	\$6.50	\$26.00 +
8 Rear Tail Gate Jazz Emblem <i>new</i>	1	\$45.40	\$45.40 ✓
9 Rear Tail Gate Mechanism Lock <i>Damaged</i>	1	\$209.20	\$209.20 ✓
10 Rear Tail Gate Inner Handle <i>not new</i>	1	\$75.20	\$75.20 X
11 Rear Tail Gate Inner trimboard <i>cracked</i>	1	\$168.30	\$168.30 ✓
12 Rear Tail Gate Windscreen Glass Moulding <i>new</i>	1	\$953.70	\$953.70 +
13 Rear Tail Gate Windscreen Glass Moulding <i>new</i>	1	\$45.00	\$45.00 ✓
14 Rear Tail Gate Wiper Motor <i>not new</i>	1	\$238.20	\$238.20 X
15 Rear Tail Lamp L/R <i>cracked</i>	2	\$252.30	\$504.60 ✓
16 Rear Tail Lamp Panel L/R <i>Regr</i>	2	\$603.60	\$1,207.20 +
17 Rear Tail Lamp Stay Clips <i>new</i>	4	\$6.50	\$26.00 +
18 Rear End Panel <i>Dented</i>	1	\$393.50	\$393.50 ✓
19 Rear End Panel Inner Top Garnish <i>Deformed</i>	1	\$75.80	\$75.80 ✓
20 Rear End Panel Inner Top Garnish Clips <i>new</i>	4	\$6.50	\$26.00 ✓
21 Rear End Panel Antenna Sensor <i>cracked</i>	1	\$78.80	\$78.80 ✓
22 Rear Trunk Panel <i>Regr</i>	1	\$534.60	\$534.60 X
23 Rear Trunk Panel Insulator Mat <i>new</i>	1	\$189.70	\$189.70 +
24 Rear Trunk Panel Compartment Sponge <i>Deformed</i>	1	\$193.20	\$193.20 ✓
25 Rear Trunk Panel Buzzer Sensor <i>cracked</i>	1	\$87.80	\$87.80 -
26 Rear Bumper <i>Deformed</i>	1	\$615.50	\$615.50 492
27 Rear Bumper Side Retainer L/R <i>new</i>	2	\$19.50	\$39.00 ✓
28 Rear Bumper Side Retainer L/R <i>new</i>	1	\$312.50	\$312.50 +
29 Rear Bumper Reverse Sensor <i>Damaged 2 pieces</i>	1	\$1,021.99	\$1,021.99 400
30 Rear Bumper Lower Garnish <i>Deformed</i>	1	\$212.10	\$212.10 ✓

31 Rear End Sub Chasis Panel L/R

Repis

2 \$295.30

\$590.60 *X*

3875-60

3100-48

SUBTOTAL BEFORE DISCOUNT

\$9,609.79

\$1,921.96

Sub-total 1

\$7,687.83

1 Rear Number Plate

new

1 \$25.00

\$25.00 *X*

2 Rear Number Plate Garnish

new

1 \$50.00

\$50.00 *+*

3 Rear Tail Gate Inner trimboard clips

new

1 \$30.00

\$30.00 *✓*

4 Rear Tail Gate Windscreen Glass Sealant

new

1 \$80.00

\$80.00 *60*

5 Rear Bumper Clips

new

1 \$30.00

\$30.00 *✓*

120

Sub-total 2

\$215.00

Labour

1 To provide towing charge

1 \$50.00

\$50.00 *X*

2 To remove, reinstall electrical wiring harness, check lighting

1 \$60.00

\$60.00 *30*

3 To remove & refix/renew reverse sensor assy and rectify for proper functioning

1 \$80.00

\$80.00 *50*

4 To remove reinstall rear tailgate windscreen

1 \$100.00

\$100.00 *✓*

5 To remove, reinstall roof top trim upholstery cushion seat trim garnish trim liner carpet

1 \$140.00

\$140.00 *60*

6 To remove rear seat dismantle

1 \$80.00

\$80.00 *X*

7 To respray painting on the change bodyparts repair portion and where consistent to the accident

1 \$1,200.00

\$1,200.00 *800*

8 To provide Labour, workmanship to change the above damage bodyparts, repair, re-align body structure, body alignments damage consistent to the accident

1 \$1,250.00

\$1,250.00 *800*

9 To dismantle repair and realign rear wiper linkage and motor assy to proper functioning

1 \$100.00

\$100.00 *X*

900

10 To apply anti-rust chemical on repair and replaced panel

1 \$120.00

\$120.00 *60*

11 To set the chasis bench, adjust and align front chasis alignment back into its original specifications

1 \$250.00

\$250.00 *X*

Labour Total

\$3,430.00

Parts & Labour Total

\$11,332.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5120.48

L/S: H.K

06 Days