



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2918J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SAFESTOP 180 TMA ASSY }	CRUMPLED	52,000.00	38,900.00
1	TMA ALUMINIUM PANEL (BIG) }	CRUMPLED	550.00	-
1	TMA ALUMINIUM PANEL (SMALL) }	CRUMPLED	400.00	-
1	REFLECTIVE STICKER	NECESSARY	600.00	600.00
2	REAR NUMBER PLATE	CRUMPLED	40.00	40.00
2	"60 KM/H" STICKER	SCRATCHED	40.00	40.00
1	REAR LAMP LED LH	CRACKED	60.00	60.00
1	REVERSE LAMP LED LH	CRUMPLED	100.00	100.00
4	SIDE LAMP	CRUMPLED	120.00	120.00
3	BEACON LIGHT	CRUMPLED (1PC ONLY)	600.00	150.00
2	REAR NUMBER PLATE LAMP	CRUMPLED (1PC ONLY)	100.00	50.00
1	REAR BUCKET ALUMINIUM PANEL	CRUMPLED	650.00	650.00
1	REAR BUCKET ALUMINIUM PANEL FRAME	BENT	300.00	300.00
1	REAR METAL MUDGUARD LH	BENT	300.00	300.00
1	MUDFLAP LH	SERVICEABLE	30.00	-
1	MUDFLAP STRIP LH	BENT	100.00	100.00
2	TMA BRACKET LH / RH	BENT	600.00	600.00
1	ARROW LED SIGN BOARD	SERVICEABLE	2,500.00	-
1	ARROW LED SIGN BOARD FRAME	SERVICEABLE	700.00	-
			59,790.00	42,010.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NOT NECESSARY	150.00	-
			150.00	-
<b><u>LABOUR</u></b>				
TO TOW VEHICLE FROM ACCIDENT SCENE.		NOT NECESSARY	200.00	-
TO INSTALL WIRING ON TMA. TO REMOVE & INSTALL LIGHTING ON TMA. CHECK FOR & RECTIFY WIRING FAULTS, ETC.			680.00	500.00
TO PANEL BEAT / REPAIR / REALIGN / WELDING MAIN CHASSIS FRAME.			3,000.00	2,000.00

Report Ref No. CS/INC19021746/Qvd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & INSTALL ALUMINIUM PANELS & MUDGUARD.		1,000.00	700.00
	TO REMOVE & REFIX ARROW LED SIGN BOARD. CHECK FUNCTION.		700.00	350.00
	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.		2,000.00	1,750.00
			7,580.00	5,300.00
<b>GRAND TOTAL</b>			<b>67,520.00</b>	<b>47,310.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>47,310.00</b>
------------------------------------	--	--	--	------------------

Report Ref No. CS/INC19021746/Qvd3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.