

INS. CASE OWNER:

Jas

CC 4/ASM190

2748, 11

LKR:
IDAC:

Surveyor:

maxus

DOI:

10/12/19

Date / Time:

10/12/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 9196L

Claim No.:

SAM0805 / 150959

Name of Insured:

CHIN KOK YANN

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$5

D.O.A.:

24/12/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: HENG SENG KENG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

26/12/19

INSRS:
WSP:
Tel:
Liability:
RMKS:Asia
motorsportINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

26/12/19

SKH 9196L

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: maxus

Repair Cost:

46

SS 2500.00

1, 3

days) Reduction:

411903.25% R2

Email

Call

FINAL SETTLEMENT

Date/Time: 17/11/2020

Confirm with:

Asia

Email

Cal

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2500.00

Loss of Rental (LOR):

SS

800.00

1, 4

days) x

8200

Loss of Use (LOU):

SS

-

(\$ x

days)

Loss of Income (LOI):

SS

-

(\$ x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3309.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS

3309.45

Name 1:

Asia Motorsports Solution Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
20/11/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

5350.

X GIA.

S AFA-

Page No. 1

VEHICLE NO. PC 6221J

TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Tailgate 1978.50	20/Barf	2250.00	
1	Tailgate edge weatherstrip	11	375.20	X
1	Tailgate centre chrome garnish	11	289.50	X
1	Tailgate inner lock (top)	11	275.20	X
1	Tailgate inner lock (top) cover	11	122.00	X
1	Tailgate lock catch (lower)	11	142.60	X
2	Tailgate damper @322.70	11	645.40	X
2	Tailgate hinges @ 98.50	REUSE 11	0.00	X
1	Tailgate HIACE emblem 48.00	new	112.00	✓
1	Tailgate SUPER GL emblem 42.00	new	98.00	✓
1	Tailgate Inner trim board	11	250.00	X
1	Rear wiper washer nozzle	REFIX 11	0.00	X
1	Rear wiper arm	REFIX 11	0.00	X
1	Rear wiper blade	REFIX 11	0.00	X
1	Rear wiper motor	REFIX 11	0.00	X
1	Rear view mirror	REFIX 11	0.00	X
2	Rear number plate lamp @58.00	11	116.00	X
1	Rear bumper 657.00	new	1428.00	✓
1	Rear bumper beam	NS	232.00	X
2	Rear bumper side stopper @28.00	11	56.00	X
2	Rear bumper side retainer @98.40	11	196.80	X
1	Rear bumper step garnish	11	328.00	X
2	Rear RHS & LHS Corner panel @389.50	11	779.00	X
2	RHS & LHS Taillamp @695.80	11	1391.60	X
1	Rear floor panel	11	1295.80	X
1	Rear end panel (inner)	11	982.00	X
1	Rear end panel (outer)	11	965.20	X
1	Spare tyre holder	11	285.50	X
			12615.80	
			less 25%	25%
			3153.95	
			9461.85	
SPECIAL NETT ITEMS				
1	Toyota Badge	new	72.00	40
1	Hiace Sticker	Repud	40.00	X
1	Reverse camera	11	480.00	X
1	Reverse Parking Sensors	11	280.00	X
1	Rear Windscreen Sealant	100	100.00	40
1	Rear end panel sealant	11	100.00	X
1	Rear Licence Plate	11	50.00	X
TOTAL PARTS			10583.85	

 > **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 303C

Vehicle Details

Vehicle No.: PC6221J

Vehicle to be Exported: No

Intended Deregistration Date: 10 Dec 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE SUPER GL 3.0 DIESEL A/T 2WD
5DR

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2681294

Chassis No.: KDH2118007771

Maximum Power Output: -

Open Market Value: \$47,726.00

Original Registration Date: 30 Jun 2017

First Registration Date: 30 Jun 2017

Transfer Count: 1

Actual ARF Paid: \$2,387.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$36,879.00

COE Rebate Amount: \$27,853.00

Total Rebate Amount: \$27,853.00

The information contained herein is correct as at 10 Dec 2019

OK

500+ dealers competed to buy my car!

Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

sgCARMART

QUOTZ

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes-Benz C180K.



Genuine Low Mileage, Pristine Condition, Well Maintained By Merc Enthusiast.

Direct Owner - StarAd.

Free VICOM evaluation

Free grooming and 8 months maintenance

In-house workshop ensures quality service

Member of SVTA and hire purchase association

100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Toyota Hiace super

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace super		Any	Any	2017	Any	Any	Any	Available
	Toyota Hiace	3.0A Super GL Dark Prime	\$75,800	\$10,270 /yr	28-Apr-2017	2,982 cc	60,000 km	Bus	Available
Fuel Type: Diesel Enjoy Low Interest Bank Rate. Highest Specification Toyota Hiace. Comes With 5 Years Engine Warranty. Luxurious 8 Rear Seater Bus W... Euro Performance Asia Pte Ltd Posted: 01-Dec-2019 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0A Super GL Dark Prime	\$65,000	\$8,470 /yr	11-Aug-2017	2,982 cc	56,000 km	Van	Available
Fuel Type: Diesel Reliable 3.0L Turbo Diesel, 4 Cylinder Inline, 16 Valve, DOHC, Easy To Maintenance Engine. Problem-Free 4 Speed Auto Gearbox. No Ad... Posted: 18-Nov-2019 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page



Service Request Details

Claim

S9M02805

Reference

None

Loss Date

September 24, 2019

Report Date

Dec 9, 2019 12:14:00 PM

Request Date

December 10, 2019

Due Date

December 17, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

marcus

P. Loo

T: 10.08am 10.12.19

V: 14

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

PC6221J



Model

HIACE

Service Address

...

Primary Contact/Insured

CHIN KOK YANN

BLK 260A ANG MO KIO STREET 21, #08-149, 561260, Singapore

88919704

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

9

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Summer Lee (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Monday, 9 December, 2019 10:29 AM
To: customer.service@axa.com.sg; SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] NOTICE OF ACCIDENT: ACCIDENT INVOLVING PC 6221 J & SKH 9196 L ON 24 SEPTEMBER 2019

Categories: Shekhar

Your Ref:
Our Ref: PC 6221 J

9 December 2019

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING PC 6221 J & SKH 9196 L ON 24 SEPTEMBER 2019

We are instructed to notify you of a road traffic accident on **24 September 2019** at about **0145H** at **Syed Alwi Road towards Jalan Besar** involving our client's vehicle registration number **PC 6221 J** and vehicle registration number **SKH 9196 L** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **11 December 2019 (Wednesday), 1030H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563501 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/01/2020

Survey Details:

Date of loss	24-Sep-19
Date of appointment	10-Dec-19
Date of survey	10-Dec-19
Location of survey	ASIA MOTORSPORTS SOLUTION PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	PC 6221J
Make and Model	TOYOTA HIACE 2.0
Date of registration	30/6/2017
Excess	
Market Value	\$62,000
Parf Rebate	\$27,853
Nett Loss	\$34,147

Repair details:

Initial Estimate	\$ 14,003.85
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 1,436.25
Check items (estimate)	\$ -
Labour	\$ 1,070.00
Total	\$ 2,506.25
Lump Sum(if applicable)	\$ 2,500.00
Number of days for repair	3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

03 RECOMMENDED REPAIR DAYS + 1 PRS = 4DAYS

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	2,500.00	
Loss of use	\$	-	
Loss of rental	\$	1,000.00	4days x \$250
Loss of income	\$	-	
LTA search fees	\$	7.45	
Others	\$	-	
Proposed Total	\$	3,507.45	



<MANDATE IA> - S9M028O5 {ACCIDENT INVOLVING SKH 9196L (OI) & PC 6221 (TP) ON 24/09/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3507.45 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 16/01/2020

Reply



ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

FNA TRANSPORT SERVICES
53287303C

INVOICE NO: 2017/C208

DATE: 02/01/2020

VEHICLE NO: PC 6221 J

MAKE : TOYOTA ENGINE NO : 1KD2681294
MODEL : HIACE SUPER GL CHASSIS NO : KDH2118007771
3.0 DIESEL A/T
2WD 5DR

DESCRIPTION

AMOUNT

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$2,500.00

Total amount payable

S\$2,500.00



Asia Motorsports Solution Pte Ltd



Re:<MANDATE IA> - S9M028O5 {ACCIDENT INVOLVING SKH 9196L (OI) & PC 6221 (TP) ON 24/09/2019}

Type

🔗 Question

Message

hi, please offer \$200 for rental rate. thanks.

Reply

Cecilia Chong (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Thursday, 2 January 2020 2:28 PM
To: Cecilia Chong (LKK Auto); Admin A
Subject: Re: ACCIDENT INVOLVING PC 6221 J & SKH 9196 L ON 24 SEPTEMBER 2019 - CALL FOR DIRECT SETTLEMENT
Attachments: PC6221J_estimate_finalisation.pdf; PC6221J_invoice.pdf; PC6221J_report.pdf; PC6221J_rental_invoice.pdf; SKH9196L_ins_search.pdf

Your Ref:
Our Ref : PC 6221 J

2 January 2020

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1,
#02-25
Singapore 408933

Attn: Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING PC 6221 J & SKH 9196 L ON 24 SEPTEMBER 2019 - CALL FOR DIRECT SETTLEMENT

Kindly find attached the finalized report for PC 6221 J, as proposed by our Single Joint Expert. We are pleased to inform that we are agreeable to the amount proposed.

As such, we are writing to your kind office to call for a direct settlement, in relation to the accident involving PC 6221 J & SKH 9196 L on 24 September 2019. We will like to know if your company is prepared to settle for the amount as stated below:

Cost of Repair (amount as proposed by SJE)	: \$ 2,500.00
Cost of Rental	:\$ 1,040.00
LTA Search	:\$ 7.45

Total: : \$ 3,547.45

We seek your kindest assistance in letting us know whether your kind office is agreeable to the above within the next 7 days and we look forward to you forwarding us the DV (without prejudice to any personal injury claims), if required, so that we can expedite on its return for an amicable settlement to the matter.

We have also attached a copy of our company's invoice for PC 6221 J, the Singapore Accident Statement of PC 6221 J, rental invoice and LTA search for your easy reference.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021748/Ugb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:JAS

Date : 03-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 9196L	Veh. Inspected	PC 6221J
Policy No.	GA014096	Coverage (\$)	0.00
Claim No.	S9M02805	Excess (\$)	0.00
Assign From		Assign Date	10/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE SUPER GL (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2118007771	Colour	SILVER
Odometer	225285	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/09/2019	Inspection Date	10/12/2019
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6221J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	DENTED / BENT	2,250.00	1,971.50
1	TAILGATE EDGE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	375.20	-
1	TAILGATE CENTRE CHROME GARNISH (CONSISTENT)	NOT NECESSARY	289.50	-
1	TAILGATE INNER LOCK (TOP) (CONSISTENT)	NOT NECESSARY	275.20	-
1	TAILGATE INNER LOCK (TOP) COVER (CONSISTENT)	NOT NECESSARY	122.00	-
1	TAILGATE LOCK CATCH (LOWER) (CONSISTENT)	NOT NECESSARY	142.60	-
2	TAILGATE DAMPER @\$322.70 (CONSISTENT)	NOT NECESSARY	645.40	-
2	TAILGATE HINGES (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	TAILGATE HIACE EMBLEM (CONSISTENT)	NECESSARY	112.00	48.00
1	TAILGATE SUPER GL EMBLEM (CONSISTENT)	NECESSARY	98.00	42.00
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR WIPER WASHER NOZZLE (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR WIPER ARM (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR WIPER BLADE (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR WIPER MOTOR (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR VIEW MIRROR (CONSISTENT) (NPA)	NOT NECESSARY	-	-
2	REAR NUMBER PLATE LAMP @\$58.00 (CONSISTENT)	NOT NECESSARY	116.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,428.00	651.00
1	REAR BUMPER BEAM (CONSISTENT)	NO SUCH PARTS	232.00	-
2	REAR BUMPER SIDE STOPPER @\$28.00 (CONSISTENT)	NOT NECESSARY	56.00	-
2	REAR BUMPER SIDE RETAINER @\$98.40 (CONSISTENT)	NOT NECESSARY	196.80	-
1	REAR BUMPER STEP GARNISH (CONSISTENT)	NOT NECESSARY	328.00	-
2	REAR RHS & LHS CORNER PANEL @\$389.50 (CONSISTENT)	NOT NECESSARY	779.00	-
2	RHS & LHS TAILLAMP @\$695.80 (CONSISTENT)	NOT NECESSARY	1,391.60	-
1	REAR FLOOR PANEL (CONSISTENT)	NOT NECESSARY	1,295.80	-
1	REAR END PANEL (INNER) (CONSISTENT)	TO REPAIR SEE LABOUR	982.00	-
1	REAR END PANEL (OUTER) (CONSISTENT)	TO REPAIR SEE LABOUR	965.20	-
1	SPARE TYRE HOLDER (CONSISTENT)	NOT NECESSARY	285.50	-
	LESS 25% DISCOUNT		-3,153.95	-

Report Ref No. CC4/ASM19021748/Ugb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 50% DISCOUNT		-	-1,356.25
			9,461.85	1,356.25
	<u>SPECIAL NETT ITEMS</u>			
1	TOYOTA BADGE (CONSISTENT) (SN)	NECESSARY	72.00	40.00
1	HIACE STICKER (CONSISTENT) (SN)	REPEATED	40.00	-
1	REVERSE CAMERA (CONSISTENT) (SN)	NOT NECESSARY	480.00	-
1	REVERSE PARKING SENSOR (CONSISTENT) (SN)	NOT NECESSARY	280.00	-
1	REAR WINDSCREEN SEALANT (CONSISTENT) (SN)	NECESSARY	100.00	40.00
1	REAR END PANEL SEALANT (CONSISTENT) (SN)	NOT NECESSARY	100.00	-
1	REAR LICENCE PLATE (CONSISTENT) (SN)	NOT NECESSARY	50.00	-
			1,122.00	80.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER) AND REAR END PANEL (OUTER).		1,400.00	400.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PATT'S REPLACED.		1,000.00	500.00
	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION .		250.00	20.00
	TO REMOVE/REFIX INNER TRIMS ,FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN .		140.00	120.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION .	NOT NECESSARY	100.00	-
	TO REPLACE AND REPLACE REVERSE CAMERA AND TEST FOR PROPER FUNCTION .	NOT NECESSARY	100.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		180.00	30.00
			3,420.00	1,070.00
	GRAND TOTAL		14,003.85	2,506.25

Report Ref No. CC4/ASM19021748/Ugb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00
---	--	--	----------

Report Ref No. CC4/ASM19021748/Ugb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SYN02805

Reference

CCA/ASM19021748/Uga3a2

Loss Date

24 September 2019

Report Date

9 Dec 2019 12:14:00 PM

Request Date

10 December 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

PC6221J

Make

TRIVO TOYOTA

Model

HIACE

Service Address

...

Primary Contact/Insured

CHIN KOK YANN

BLK 260A ANG MO KIO STREET 21, #08-149,

561260, Singapore

88919704

Claim Handler

TAN Jis

6568804844

jis.tan@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Add Invoice to

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document Subtype

+ Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Meritmen

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKAAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 MANDATE IA DO 16012020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LTA SEARCH INV.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 TAX INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 TP-IA 6221.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
 Service appointment in Vendor Portal claim 599402805 for vehicle PC62213.html	[[getDocumentType_AsItem.documentType]]		VISHNU BATHAM Shekhar	10 December 2019
 SURVEYOR APPOINTED.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	10 December 2019
 LIST OF SURVEYOR SENT.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	9 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GA014096-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shekhar	9 December 2019
 GA014096-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shekhar	9 December 2019
 GIA PC6221J TP.PDF	Letters and Correspondence	Government Authorities / Police / Association / Regulator	VISHNU BATHAM Shekhar	9 December 2019
 TP ASIA MOTORSPORTS-EMAIL TP PRL.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	9 December 2019
 TP ASIA MOTORSPORTS-EMAIL TP PRL.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	9 December 2019