

J AYA.

1/5 # 2500?

10/12/19

Page No. 1

VEHICLE NO. PC 6221J

TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Tailgate 1971.50	20/321	2250.00	
1	Tailgate edge weatherstrip	11	375.20	X
1	Tailgate centre chrome garnish	11	289.50	X
1	Tailgate inner lock (top)	11	275.20	X
1	Tailgate inner lock (top) cover	11	122.00	X
1	Tailgate lock catch (lower)	11	142.60	X
2	Tailgate damper @322.70	11	645.40	X
2	Tailgate hinges @ 98.50	REUSE 11	0.00	X
1	Tailgate HIACE emblem 48.00	NEW	112.00	✓
1	Tailgate SUPER GL emblem 42.00	NEW	98.00	✓
1	Tailgate Inner trim board	11	250.00	X
1	Rear wiper washer nozzle	REFIX 11	0.00	X
1	Rear wiper arm	REFIX 11	0.00	X
1	Rear wiper blade	REFIX 11	0.00	X
1	Rear wiper motor	REFIX 11	0.00	X
1	Rear view mirror	REFIX 11	0.00	X
2	Rear number plate lamp @58.00	11	116.00	X
1	Rear bumper 657.00	NEW	1428.00	✓
1	Rear bumper beam	NS	232.00	X
2	Rear bumper side stopper @28.00	11	56.00	X
2	Rear bumper side retainer @98.40	11	196.80	X
1	Rear bumper step garnish	11	328.00	X
2	Rear RHS & LHS Corner panel @389.50	11	779.00	X
2	RHS & LHS Taillamp @695.80	11	1391.60	X
1	Rear floor panel	11	1295.80	X
1	Rear end panel (inner)	11	982.00	X
1	Rear end panel (outer)	11	965.20	X
1	Spare tyre holder	11	285.50	X
			12615.80	
		50% less 25%	3153.95	25%
			9461.85	
	SPECIAL NETT ITEMS			
1	Toyota Badge		NEW 72.00	40
1	Hiace Sticker		Repld 40.00	X
1	Reverse camera		11 480.00	X
1	Reverse Parking Sensors		11 280.00	X
1	Rear Windscreen Sealant		100 100.00	40
1	Rear end panel sealant		11 100.00	X
1	Rear Licence Plate		11 50.00	X
	TOTAL PARTS		10583.85	

