

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7602S

DATE 7/12/2019 12:01

MAKE :

Lee

CHINA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Wheel Hup-Cap (LH) SCV			\$ 107.10
	SUB TOTAL		107.10	\$ 107.10
	LESS 20%		-20%	\$ 21.42
	DISCOUNTED TOTAL		85.68	\$ 85.68
	Rear Door Comfortdelgro & Apps Sticker (LH) net		80	\$ 80.00
	Rear Tyre (LH) net XXXX			\$ 216.00
				\$ 296.00
	Labour Charge			
	Panel Beating-Repair Rear LH Fender & Rear LH Door, Rear Bumper			\$ 350.00
	Spray Painting Charge		880	\$ 750.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR		1,045.68	\$ 1,180.00
	ESTIMATE TOTAL		836.54	\$ 1,561.68

Nett

Nett

\$280

\$600

XXXX

850

Ram(LKIC)
 9/12/19 11/5hrs
 Para & Ram @ LKIC auto.c
 88622778
 (L/S) (3) repair
 \$850 as repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.