

REPAIR ESTIMATE*

VEHICLE NO : SH 8298M

DATE 9/12/2019 14:29

MAKE :

MODEL : HYUNDAI i40

Lke

CHINI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>Org</i>			\$ 1,110.10	
	Front Bumper Cover <i>x(r)</i>			\$ 1,052.20	
	Front Bumper Bracket Top (LH/RH) <i>xnn</i>		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) <i>xnn</i>		\$ 24.60	\$ 49.20	
	<i>S</i> Radiator Grille Emblem - #39.50 <i>Part taken rec.</i>				
	SUB TOTAL			\$ 2,256.30	
	LESS 20%			\$ 451.26	
	DISCOUNTED TOTAL			\$ 1,805.04	
	Front Number Plate <i>Org</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>scr</i>			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 350.00	\$280
	Spray Painting Charge			\$ 250.00	\$200
	Towing Fees			\$ 60.00	?
	TOTAL LABOUR			\$ 660.00	
	ESTIMATE TOTAL			\$ 2,520.04	
<i>Ram (Lke)</i> <i>9/12/19 1630hrs</i> <i>Parasuram@lkrauto.com</i> <i>88622728 hp</i> <i>(2) repairs</i> <i>AA repair photo</i> <i>(P/S)</i>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					