

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJT 4378 K**
 Model : TOYOTA AXIO
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BOOTLID	1	\$ 1,193.00	\$ ✓ 1,193.00 DDV ✓
2	BOOTLID LOGO	1	\$ 79.90	\$ 61.70 79.90 } NECV ✓
3	BOOTLID EMBLEM AXIO	1	\$ 86.50	\$ 59.80 86.50 } NECV ✓
4	BOOTLID EMBLEM X	1	\$ 58.80	\$ ✓ 58.80 } NECV ✓
5	BOOTLID OUTER MOULDING	1	\$ 195.20	\$ ✓ 195.20 BRV ✓
6	BOOTLID INNER LOCK	1	\$ 185.60	\$ ✓ 185.60 JAM ✓
7	BOOTLID LOCK STRIKER	1	\$ 48.00	\$ 48.00 HDX ✓
8	BOOTLID INNER TRIM	1	\$ 298.60	\$ ✓ 298.60 DIS ✓
9	BOOTLID WEATHERSTRIP	1	\$ 211.60	\$ ✓ 211.60 TN ✓
10	BOOTLID INNER TRIM	1	\$ 298.50	\$ 298.50 RPT ✓
11	REAR NUMBER PLATE LAMP	2	\$ 80.50	\$ 161.00 NDH ✓
12	REAR BUMPER	1	\$ 985.90	\$ 850.00 985.90 BRV ✓
13	REAR BUMPER SIDE RETAINER	2	\$ 105.80	\$ ✓ 211.60 NECV ✓
14	REAR BUMPER BRACKET	2	\$ 105.00	\$ ✓ 210.00 BRV ✓
15	REAR END PANEL	1	\$ 985.20	\$ 677.30 985.20 DDV ✓
16	REAR END PANEL TOP GARNISH	1	\$ 258.60	\$ ✓ 258.60 DLV ✓
17	REAR FENDER INNER TRIM	2	\$ 218.00	\$ ✓ 436.00 DIS ✓
18	TAILLAMP	2	\$ 786.20	\$ 970.20 1,247.00 BRV ✓
19	TAILLAMP LOWER BRACKET	2	\$ 82.60	\$ 165.20 NSPX ✓
20	TAILLAMP BASE PANEL	2	\$ 286.20	\$ ✓ 497.60 PDV ✓
21	EXHAUST MUFFLER	1	\$ 793.10	\$ 208.00 793.10 DDV ✓
22	EXHAUST MOUNTING	1	\$ 165.70	\$ 97.20 165.70 MIS ✓
23	SPARE TYRE PANEL	1	\$ 489.20	\$ ✓ 489.20 DDV ✓
24	SPARE TYRE PANEL TOP BOARD	1	\$ 265.90	\$ ✓ 265.90 DIS ✓
			Parts Sub Total :	\$ 7435.90 9,527.70
			Discount 25% :	\$ 1858.96 2,381.93
			PARTS TOTAL :	\$ 5576.93 7,145.78

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	BOOTLID SEALANT	1	\$ 100.00	\$ 50.00 100.00 NECV ✓
2	BOOTLID OUTER MOULDING CLIPS	1	\$ 50.00	\$ 30.00 50.00 NECV ✓
3	BOOTLID INNER TRIM CLIPS	1	\$ 50.00	\$ 30.00 50.00 } NECV ✓
4	REAR BUMPER CLIPS	1	\$ 80.00	\$ 30.00 80.00 } NECV ✓
5	TAILLAMP SEAL	2	\$ 50.00	\$ 40.00 100.00 } NSPX ✓
6	TAILLAMP CLIPS	2	\$ 40.00	\$ 80.00 80.00 } NSPX ✓
7	REAR FENDER INNER TRIM CLIPS	1	\$ 80.00	\$ 30.00 80.00 } NECV ✓
8	REAR END PANEL TOP GARNISH CLIPS	1	\$ 100.00	\$ 30.00 100.00 } NECV ✓
9	REAR END PANEL SEALANT	1	\$ 100.00	\$ 30.00 100.00 } NECV ✓
10	REAR NO PLATE WITH GARNISH	1	\$ 80.00	\$ 50.00 80.00 } NECV ✓
11	SPARE TYRE PANEL SEALANT	1	\$ 100.00	\$ 30.00 100.00 } NECV ✓
12	REAR REVERSE CAMERA	1	\$ 328.00	\$ 300.00 328.00 CRA ✓
13	REVERSE SENSOR WITH MODULE	1	\$ 300.00	\$ 200.00 300.00 CUT ✓
			SPECIAL NETT TOTAL :	\$ 850.00 1,548.00

Nos.	LABOUR	S\$		
1	R&R UPHOLSTERY	\$	200.00	NNX
2	CHECK WIRING	\$ 50.00	120.00	✓
3	PANEL BEATING	\$ 1200.00	1,600.00	✓
4	SPRAY PAINTING	\$ 1200.00	1,600.00	✓
5	R&R BOOTLID COMPONENT	\$ 80.00	150.00	✓
6	R&R REVERSE SENSOR	\$	100.00	NNX
7	R&R EXHAUST MUFFLER	\$ 80.00	150.00	✓
8	TO DRILL HOLES ON REAR BUMPER REVERSE SENSOR	\$ 60.00	80.00	✓
9	SPRAY REVERSE SENSOR	\$ 20.00	80.00	
10	RUST PROOFING	\$ 60.00	150.00	
LABOUR TOTAL :		\$2750.00	4,230.00	

PARTS TOTAL : \$5576.93 7,145.78
SPECIAL NETT TOTAL : \$ 850.00 1,548.00

LABOUR TOTAL : \$2750.00 4,230.00

GRAND TOTAL : \$8576.93 12,923.78

@ 20 % 1715.39
6861.54

4S 6850/2 with 11 days for repair

Resurvey 11/12/19

TGim Min

1620 hrs

Repair days 11

Survey 10/12/19

TGim Min

1530 hrs

Lump sum repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: