



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

After Repair photo

AKA ?

11 December 2019

REG NO.: SJK 3326 P
MAKE/MODEL: TOYOTA WISH

Not Authorized
16 dy. 10/12/19
1/5# 13,000/
to be the After Repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION LIST ITEMS	AMT(S\$)
1	Front bonnet	\$ Buc 733.80
1	Front bonnet chrome moulding	\$ body/cr 286.23
2	Front bonnet hinges	\$ su 97.10
1	Front bonnet insulator	\$ 11 298.50
1	Front bonnet lock	\$ twi 112.52
1	Front bonnet rubber	\$ rec 52.80
1	Front bonnet logo	\$ 11 68.50
2	Front headlamps 675x2=1350	\$ cr 1,607.50
1	Front grille	\$ body/fo 186.50
1	Front bumper 521.50	\$ 11 881.95
1	Front bumper centre grille	\$ 11 119.00
2	Front bumper fog lamp covers	\$ 11 173.00
1	Front bumper reinforcement 399.20	\$ 11 412.60
2	Front bumper side retainers 49.84	\$ n/s bent 99.68
1	Front fender 115	\$ Buc 786.90
2	Front fender inner shields	\$ 11 311.20
1	Front support panel	\$ body/tw 1,155.65
1	Front brace panel	\$ uni 110.50
2	Front support panel side garnishes	\$ 11 92.50
2	Horns	\$ 11 342.00
1	Air con condenser	\$ 11 1,428.97
1	Radiator	\$ 11 1,837.70
1	Radiator fan	\$ 11 890.68
1	Radiator fan blade	\$ 11 120.65
1	Radiator fan cowl	\$ cr 260.15
1	Radiator spare tank	\$ 11 142.60
2	Radiator top mountings	\$ 11 57.00
1	Air cleaner intake duct	\$ 11 126.20
1	Front wiper tank	\$ 11 182.50
1	Rear windscreen moulding	\$ 11 186.60
1	Rear tailgate 1298.10	\$ 11 1,466.80
1	Rear tailgate outer chrome moulding	\$ cr 383.90
2	Rear tailgate dampers	\$ 11 423.00
1	Rear tailgate lock	\$ shock 497.40
1	Rear taillamp 115	\$ smashed 481.60
1	Rear taillamp panel 115 399.50	\$ 11 594.00
1	Rear end panel 499.20	\$ body 606.90
1	Rear end panel inner garnish	\$ 11 296.50
		\$ 17,911.58

LIST ITEMS

1	Rear bumper	489.10	\$	705	895.65	✓
1	Rear bumper bracket	165	\$	set	65.50	✓
1	Rear bumper reflector	165	\$	320	85.50	✓
2	Rear bumper side retainers	48.50	\$	1/2 cone	128.86	✓
1	Rear fender -L/H		\$	705	1,013.50	✓
1	Rear fender air gate		\$	cne	125.45	✓
1	Rear fender inner top garnish		\$	17	150.55	X
1	Rear fender inner trim board	165	\$	705	692.40	✓
1	Rear fender quarter glass	165	\$	Shottub	628.55	✓
1	Rear fender quarter glass moulding		\$	NS	185.90	X
1	Rear fuel lid		\$	17	126.50	X
1	Rear wheel hub with bearing		\$	17	781.50	X
1	Rear shock absorber		\$	17	426.50	X
1	Rear axle		\$	17	2,017.60	X
1	Rear door -L/H		\$	2	1,265.50	X
1	Rear door rubber		\$	17	243.40	X
1	Rear door inner lock		\$	17	355.20	X
			\$		27,099.64	
			Less 25%	\$	6,774.91	
			\$		20,324.73	

502

16163.92
502
8081.98SPECIAL NETT ITEMS

1	Front bonnet insulator clip (1 set)		\$	17	35.00	X
1	Front bumper clip (1 set)		\$	rec	35.00	✓
1	Front number plate with holder		\$	set	50.00	40
2	Front fender inner shield clips (2 set)		\$	17	90.00	X
1	Rear windscreen sealant		\$	rec	80.00	40
1	Rear bumper clip (1 set)		\$	rec	45.00	✓
1	Rear reverse sensor (1 set)		\$	Shottub	350.00	200
1	Rear fender quarter glass sealant		\$	rec	80.00	40
1	Rear tyre		\$	SVC	400.00	X
1	Rear sport rim		\$	17	600.00	X
			\$		1,765.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	✓
3	To remove and refit inner garnishes.	\$	180.00	80
4	To remove and refit rear reverse sensor.	\$	120.00	50
5	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
6	To remove and refit fuel tank assembly with all attachments.	\$	150.00	60
7	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	100
8	To remove and refit rear windscreen glass.	\$	180.00	120
9	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	17	150.00 X
10	To apply undercoating.	\$	250.00	120
11	Panel beating.	\$	2,500.00	2200
12	To re-spray painting on the affected areas.	\$	2,400.00	1800
		\$	6,390.00	

GRAND TOTAL:

\$ 28,479.73

PAGE 2 OF 2

Acknowledged by Repairer

Signature:

Date:

P-8081.98
S.N-400
L-4622
13/01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company