

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

HEW KIM LOH

c/o 46 Lentor Plain
Singapore 786548

Not Authorized

Putty & paint

4 days

L/Lmp @ 2450/h

Date: 9/12/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: KIA CERATO / SMM 1497 X		
1 pc	rear bumper	Bumper 576.40
1 pc	rear bumper lower pad	CPA 315.10
1 pc	rear bumper sponge	WSP 365.60
1 pc	rear bumper reinforcement beam	CM 277.40
2 pcs	rear bumper reinforcement beam bracket	R 126.80
2 pcs	rear bumper lamp	231.90 @ 63.40
1 pc	rear bumper lower pad moulding	231.90 @ 419.30
24 pcs	rear bumper park sensor	361.40 @ 487.40
1 pc	rear end panel	1,949.60
1 pc	rear end panel garnish	R 498.40
1 pc	rear boot lid	Sm 217.50
1 pc	rear boot lock	R 776.30
1 pc	rear boot lock catch	R 197.40
1 pc	rear boot weatherstrip	R 76.60
1 pc	rear boot emblem logo	Sm 266.70
1 pc	rear boot emblem "CERATO"	Sm 72.10
1 pc	rear boot emblem "GT"	Sm 73.20
		Sm 81.40
	sub-total	6,978.80
	10 less 15%	1,046.82
	sub-total	5,931.98
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	400 1,000.00
	To check wiring system.	150 50.00
	To apply putty & spray painting on affected areas.	500 800.00
	To apply waterproof sealant on affected area.	nn 150.00
	To install reverse sensors and reverse camera.	50 80.00
	total	8,011.98