

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Authorized
Resurvey B4 paint
4 days

HEW KIM LOH
c/o 46 Lenton Plain
Singapore 786548

Date: 9/12/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: KIA CERATO / SMM 1497 X	
1 pc	rear bumper	Bumper 576.40
1 pc	rear bumper lower pad	CM 315.10
1 pc	rear bumper sponge	365.60
1 pc	rear bumper reinforcement beam	277.40
2 pcs	rear bumper reinforcement beam bracket @ 63.40	126.80
2 pcs	rear bumper lamp @ 419.30	838.60
1 pc	rear bumper lower pad moulding	269.70
1 pc	rear bumper park sensor	Scr @ 487.40 1,949.60
1 pc	rear end panel	R 498.40
1 pc	rear end panel garnish	Sm 217.50
1 pc	rear boot lid	R 776.30
1 pc	rear boot lock	R 197.40
1 pc	rear boot lock catch	R 76.60
1 pc	rear boot weatherstrip	Sm 266.70
1 pc	rear boot emblem logo	Sm 72.10
1 pc	rear boot emblem "CERATO"	Sm 73.20
1 pc	rear boot emblem "GT"	Sm 81.40
sub-total		6,978.80
less 15%		1,046.82
sub-total		5,931.98
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		4cd 1,000.00
To check wiring system.		15/ 50.00
To apply putty & spray painting on affected areas.		5cd 800.00
To apply waterproof sealant on affected area.		nn 150.00
To install reverse sensors and reverse camera.		5cd 80.00
total		8,011.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: