

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRST CAPITAL	DATE	: 10/12/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
Jia Le			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: PA8798J	JTFST22P800007047	
MODEL	: TOYOTA HIACE 3.0		
CHASSIS NO			
<u>ACCIDENT DETAILS</u> DATE : 1-Dec-19			
TIME : 20:30HRS			
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>replaced</i>	1	\$ 580.30	\$ 580.30
12	REAR BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 62.40	\$ 62.40
23	TAIL LAMP RH <i>replaced</i>	1	\$ 338.90	\$ 338.90
34	TAIL LAMP LOWER GARNISH RH <i>torn</i>	1	\$ 155.20	\$ 155.20
45	TAIL LAMP LOWER GARNISH RETAINER RH <i>new</i>	1	\$ 65.00	\$ 65.00
56	REAR FENDER <i>new</i>	1	\$ 2,388.50	\$ 2,388.50
67	REAR FENDER INNER COWLING <i>torn</i>	1	\$ 180.00	\$ 180.00
78	REAR FENDER AIR VENT <i>replaced</i>	1	\$ 80.00	\$ 80.00
89	REAR FENDER GLASS MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00

1396.80

TOTAL PRICE \$ 4,040.30

1047.60

LESS 25% \$ 1,010.08

SUB TOTAL PRICE \$ 3,030.23

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR FENDER INNER COWLING CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	REVERSE SENSOR <i>new</i>	1	\$ 200.00	\$ 200.00

5	WHEEL RIM COVER <i>ct</i>	1	\$ 280.00	\$ 280.00 <i>60.</i>
			TOTAL	\$ 540.00

120

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (SIDE)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,200.00 <i>600.</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00 <i>600.</i>	
3	TUFF COAT	\$ 250.00 <i>60.</i>	
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 150.00 <i>80.</i>	
5	TO REMOVE AND REFIX REVERSE SENSOR SETTING	\$ 80.00 <i>50</i>	
6	REMOVE AND REFIX FENDER WINDSCREEN	\$ 120.00	<i>X</i>

1380

TOTAL \$ 4,800.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,570.23
TOTAL LABOUR COS : \$ 4,800.00
TOTAL REPAIR COST : \$ 8,370.23

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :
NO OF DAYS :

FAX : total: 2557.60

4/s: 2K.

*Addan himy.
4/s 10/12/19.
050yr.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: