



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004469
INV Date 23/06/2020
Reference CC4/FCI19021776/R1ba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMH 8432M
Insured Veh. SHA 4120K
Claim No. D19007607MFSH
Policy No. D-19092580MFSH
Accident Date 30/11/2019
Inspection Date 13/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19021776/R1ba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-06-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4120K	Veh. Inspected	SMH 8432M
Policy No.	D-19092580MFSH	Coverage (\$)	0.00
Claim No.	D19007607MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	09/12/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI 1.2 DIG	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	SJNFEAJ11U2393827	Colour	BROWN
Odometer	50532	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	GOODYEAR	6 mm
L/H Front Tyre	215/60 R17	GOODYEAR	6 mm
R/H Rear Tyre	215/60 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/60 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/11/2019	Inspection Date	13/01/2020
Survey held at	TC AUTOCLINIC PTE LTD 1 SIXTH LOK YANG ROAD SINGAPORE 628099		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8432M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
30	CLIP -LH REAR OVER FENDER @\$2.7 (N)	NECESSARY	8.10	8.10
1	CLIP -RH REAR OVER FENDER @\$2.7 (N)	NECESSARY	8.10	8.10
1	OVER FENDER -REAR ,LH (N)	CUT	540.50	540.50
1	LH REAR DOOR LOWER PVC MOULDING (N)	SCRATCHED	280.40	280.40
1	REGULATOR ASSY -REAR DOOR WINDOW ,LH (N)	SERVICEABLE	455.90	-
1	LH REAR DOOR UPPER HINGE ASSY (N)	SERVICEABLE	58.90	-
1	LH REAR DOOR LOWER HINGE ASSY (N)	SERVICEABLE	58.90	-
1	TAPE -REAR DOOR OUTSIDE ,LH (N)	NECESSARY	32.40	32.40
1	TAPE-REAR DOOR OUTSIDE ,LH (N)	NECESSARY	32.40	32.40
1	DOOR -REAR LH (N)	BENT	1,166.20	1,166.20
1	LH FRONT DOOR LOWER PCV MOULDING (N)	SERVICEABLE	342.60	-
1	LOCK & REMOTE CONTROL ASSY -FRONT DOOR ,LH (N)	SERVICEABLE	172.30	-
1	WSTRIP ASSY -FRONT DOOR ,LH (N)	SERVICEABLE	139.20	-
1	TAPE -FRONT DOOR OUTSIDE ,LH (N)	NECESSARY	32.40	32.40
1	DOOR -FRONT LH (N)	BENT	1,166.20	1,166.20
	LESS 20% DISCOUNT		-898.90	-653.34
			3,595.60	2,613.36
<u>SPECIAL NETT ITEMS</u>				
1	ABSORBER -SHOCK ,REAR LH (SN)	SERVICEABLE	172.20	-
1	HUB-REAR WHEEL ,LH (SN)	SERVICEABLE	365.40	-
1	LH REAR SPORTS RIM (SN)	SCRATCHED	1,231.90	1,231.90
			1,769.50	1,231.90
<u>LABOUR</u>				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL .		240.00	240.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		200.00	200.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION -PASSENGER.		103.00	103.00
	REMOVE/INSTALL LH FRONT DOOR ,LH REAR DOOR AND AFFECTED PORTION ,REPAIR LH SIDE BODY PANEL.		1,170.00	975.00

Report Ref No. CC4/FCI19021776/R1ba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY PAINT LH FRONT DOOR ,LH REAR DOOR AND LH SIDE BODY PANEL.		1,000.00	750.00
	TRANSFER LH FRONT DOOR AND LH REAR DOOR MECHANISM TO NEW DOORS AND CHECK DOOR CENTRAL LOCKING SYSTEM.		160.00	160.00
	REMOVE/INSTALL LH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR.		20.00	20.00
			2,893.00	2,448.00
GRAND TOTAL			8,258.10	6,293.26

RECOMMENDED COST OF REPAIRS				6,293.26
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/FCI19021776/R1ba3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 8432M

INSPECTION



NISSAN
SJNFEAJ11U239327
1790 kg
2790 kg
1- 965 kg
2- 875 kg
Type FEAJ11 Colour, Trim CANG
Model FRLARDWJ11USA-A-B





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 8432M

RE-INSPECTION

