

VIC

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HO/2019
DATE : 06-DEC-2019

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MOHAMED KASSIM TAJUDEEN (ENH2-1014127)
ADDRESS : BLK 270 TOH GUAN RD
#11-101
S(600270)
TELEPHONE NO : 98578719/93862774

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SMH8432M 11/2/2019
MODEL CODE : FRLARDWJ11USA--A-B
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2018
ENGINE NO : HRA2693341A
CHASSIS NO : SJNFEAJ11U2393827
MILEAGE : 1 KM
DATE IN : 06/12/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 30/11/2019

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH8432M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 2 PANEL	240.00	/
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANEL	200.00	/
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	/
4 ZZ/001	REMOVE/INSTALL LH FRONT DOOR, LH REAR DOOR AND AFFECTED PORTION. REPAIR LH SIDE BODY PANEL	1170.00	975
5 ZZ/002	RESPRAY PAINT LH FRONT DOOR, LH REAR DOOR AND LH SIDE BODY PANEL	1000.00	500 750
6 ZZ/003	TRANSFER LH FRONT DOOR AND LH REAR DOOR MECHANISM TO NEW DOORS AND CHECK DOOR CENTRAL LOCKING SYSTEM	160.00	/
7 ZZ/004	REMOVE/INSTALL LH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	20.00	/
TOTAL LABOUR CHARGES		2893.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH8432M

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 ABSORBER-SHOCK, REAR LH ? <i>xsu</i>	E6210-HV02A			172.20
2 HUB-REAR WHEEL, LH ? <i>xsu</i>	43202-4EA0A			365.40
3 LH REAR SPORTS RIM <i>set</i> ✓	DOC00-HV01A			1231.90 ✓
4 CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS <i>ne</i> ✓	76847-JG00A	8.10 ✓		
5 CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS <i>ne</i> ✓	76847-4EA0A	8.10 ✓		
6 OVER FENDER-REAR, LH <i>cut</i> ✓	93829-4EA0A	540.50 ✓		
7 LH REAR DOOR LOWER PVC MOULDING <i>see</i> ✓	82871-4EA0A	280.40 ✓		
8 REGULATOR ASSY-REAR DOOR WINDOW, LH ? <i>xsu</i>	82701-HV00A	455.90		
9 LH REAR DOOR UPPER HINGE ASSY ? <i>xsu</i>	82401-4EA0A	58.90		
10 LH REAR DOOR LOWER HINGE ASSY ? <i>xsu</i>	82420-4EA0A	58.90		
11 TAPE-REAR DOOR OUTSIDE, LH <i>ne</i> ✓	82813-4EA0A	32.40 ✓		
12 TAPE-REAR DOOR OUTSIDE, LH <i>ne</i> ✓	82819-4EA0A	32.40 ✓		
13 DOOR-REAR LH <i>bt</i> ✓	H2101-HV0MB	1166.20 ✓		
14 LH FRONT DOOR LOWER PVC MOULDING ? <i>xsu</i>	80871-4EA0A	342.60		
15 LOCK & REMOTE CONTROL ASSY-FRONT DOOR, LH ? <i>xsu</i>	80501-HV00A	172.30		
16 WSTRIP ASSY-FRONT DOOR, LH <i>xsu</i>	80831-HV00A	139.20		
17 TAPE-FRONT DOOR OUTSIDE, LH <i>ne</i> ✓	80813-4EA0A	32.40 ✓		
18 DOOR-FRONT LH <i>bt</i> ✓	H0101-HV0MB	1166.20 ✓		
SUB TOTAL		4494.50	0.00	1769.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		898.90	0.00	0.00
GRAND TOTAL		3595.60	0.00	1769.50
OVERALL TOTAL		5365.10		

LEGEND: REMARKS(OX) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH8432M

TOTAL LABOUR CHARGES	2893.00
TOTAL SPARE PARTS CHARGES	5365.10
GRAND TOTAL	8258.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME
SURVEYED DATE
AUTHORIZED DATE
EXCESS CLAUSE
LIABILITY
REMARKS

NAME : Rame - Hp 90010068
SURVEYED DATE : 13/01/2020 @ 1010
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00

5 days
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HO/2019
DATE : 06-DEC-2019

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MOHAMED KASSIM TAJUDEEN (ENH2-1014127)
ADDRESS : BLK 270 TOH GUAN RD
#11-101
S(600270)
TELEPHONE NO : 98578719/93862774

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SMH8432M
MODEL CODE : FRLARDWJ11USA--A-B
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2018
ENGINE NO : HRA2693341A
CHASSIS NO : SJNFEAJ11U2393827
MILEAGE : 50532 KM
DATE IN : 06/12/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 30/11/2019

Finalized Bill

To: LK

Mr. Ar Rosul

5 days
over claim LK

Best regards
YM HS

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH8432M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01W	**COMPLETE WAXING OF VEHICLE		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 2 PANEL	240.00	240.00 /
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANEL	200.00	200.00 /
4	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	103.00 /
5	ZZ/001	REMOVE/INSTALL LH FRONT DOOR, LH REAR DOOR AND AFFECTED PORTION. REPAIR LH SIDE BODY PANEL	1170.00	975.00 /
6	ZZ/002	RESPRAY PAINT LH FRONT DOOR, LH REAR DOOR AND LH SIDE BODY PANEL	1000.00	750.00 /
7	ZZ/003	TRANSFER LH FRONT DOOR AND LH REAR DOOR MECHANISM TO NEW DOORS AND CHECK DOOR CENTRAL LOCKING SYSTEM	160.00	160.00 /
8	ZZ/004	REMOVE/INSTALL LH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	20.00	20.00 /
TOTAL LABOUR CHARGES			2893.00	2448.00

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH8432M

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 ABSORBER-SHOCK, REAR LH	E6210-HV02A			172.20 X
2 HUB-REAR WHEEL, LH	43202-4EA0A			365.40 X
3 LH REAR SPORTS RIM	D0C00-HV01A			1231.90 OK
4 CLIP-LH REAR OVER FENDER @ \$2.70 EACH X3PCS	76847-JG00A	8.10		OK
5 CLIP-LH REAR OVER FENDER @ \$2.70 EACH X3PCS	76847-4EA0A	8.10		OK
6 OVER FENDER-REAR, LH	93829-4EA0A	540.50		OK
7 LH REAR DOOR LOWER PVC MOULDING	82871-4EA0A	280.40		OK
8 REGULATOR ASSY-REAR DOOR WINDOW, LH	82701-HV00A	455.90		X
9 LH REAR DOOR UPPER HINGE ASSY	82401-4EA0A	58.90		X
10 LH REAR DOOR LOWER HINGE ASSY	82420-4EA0A	58.90		X
11 LH FRONT DOOR LOWER PVC MOULDING	80871-4EA0A	342.60		X
12 LOCK & REMOTE CONTROL ASSY-FRONT DOOR, LH	80501-HV00A	172.30		X
13 WSTRIP ASSY-FRONT DOOR, LH	80831-HV00A	139.20		X
14 TAPE-FRONT DOOR OUTSIDE, LH	80813-4EA0A	32.40		OK
15 DOOR-FRONT LH	H0101-HV0MB	1166.20		OK
16 TAPE-REAR DOOR OUTSIDE, LH	82813-4EA0A	32.40		OK
17 TAPE-REAR DOOR OUTSIDE, LH	82819-4EA0A	32.40		OK
18 DOOR-REAR LH	H2101-HV0MB	1166.20		OK
SUB TOTAL		3266.70	0.00	1231.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		653.34	0.00	0.00
GRAND TOTAL		2613.36	0.00	1231.90
OVERALL TOTAL		3845.26		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMH0432M

NETT ITEM 3266.70
LESS 20.00%) -653.34
NETT AMOUNT 2613.36

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 1231.90
LESS .00%) 0.00
SPECIAL NETT AMOUNT 1231.90

TOTAL LABOUR CHARGES 2448.00
TOTAL SPARE PARTS CHARGES 3845.26

TOTAL CHARGES 6293.26
ADD 7 % GST 440.53

GRAND TOTAL 6733.79

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HO/2019
DATE : 06-DEC-2019

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MOHAMED KASSIM TAJUDEEN (ENH2-1014127)
ADDRESS : BLK 270 TOH GUAN RD
#11-101
S(600270)
TELEPHONE NO : 98578719/93862774

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SMH8432M 1112/2019
MODEL CODE : FRLARDWJ11USA--A-B
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2018
ENGINE NO : HRA2693341A
CHASSIS NO : SJNFEAJ11U2393827
MILEAGE : 1 KM
DATE IN : 06/12/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 30/11/2019

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH8432M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 2 PANEL	240.00	/
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANEL	200.00	/
3	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	/
4	ZZ/001	REMOVE/INSTALL LH FRONT DOOR, LH REAR DOOR AND AFFECTED PORTION. REPAIR LH SIDE BODY PANEL	1170.00	975
5	ZZ/002	RESPRAY PAINT LH FRONT DOOR, LH REAR DOOR AND LH SIDE BODY PANEL	1000.00	500
6	ZZ/003	TRANSFER LH FRONT DOOR AND LH REAR DOOR MECHANISM TO NEW DOORS AND CHECK DOOR CENTRAL LOCKING SYSTEM	160.00	/
7	ZZ/004	REMOVE/INSTALL LH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	20.00	/
TOTAL LABOUR CHARGES			2893.00	

6043.26
7, 1361.36

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH8432M

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	ABSORBER-SHOCK, REAR LH ?	E6210-HV02A		172.20
2	HUB-REAR WHEEL, LH ?	43202-4EA0A		365.40
3	LH REAR SPORTS RIM set ✓	D0C00-HV01A		1231.90
4	CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS ✓	76847-JG00A	8.10	
5	CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS ✓	76847-4EA0A	8.10	
6	OVER FENDER-REAR, LH cut ✓	93829-4EA0A	540.50	
7	LH REAR DOOR LOWER PVC MOULDING ✓	82871-4EA0A	280.40	
8	REGULATOR ASSY-REAR DOOR WINDOW, LH ?	82701-HV00A	455.90	
9	LH REAR DOOR UPPER HINGE ASSY ? X	82401-4EA0A	58.90	
10	LH REAR DOOR LOWER HINGE ASSY ?	82420-4EA0A	58.90	
11	TAPE-REAR DOOR OUTSIDE, LH ✓	82813-4EA0A	32.40	
12	TAPE-REAR DOOR OUTSIDE, LH ✓	82819-4EA0A	32.40	
13	DOOR-REAR LH bt ✓	H2101-HV0MB	1166.20	
14	LH FRONT DOOR LOWER PVC MOULDING ?	80871-4EA0A	342.60	
15	LOCK & REMOTE CONTROL ASSY-FRONT DOOR, LH ?	80501-HV00A	172.30	
16	WSTRIP ASSY-FRONT DOOR, LH X	80831-HV00A	139.20	
17	TAPE-FRONT DOOR OUTSIDE, LH ✓	80813-4EA0A	32.40	
18	DOOR-FRONT LH bt ✓	H0101-HV0MB	1166.20	
SUB TOTAL			4494.50	0.00 1769.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			898.90	0.00 0.00
GRAND TOTAL			3595.60	0.00 1769.50
OVERALL TOTAL			5365.10	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH8432M

TOTAL LABOUR CHARGES	2893.00
TOTAL SPARE PARTS CHARGES	5365.10
GRAND TOTAL	8258.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Rashid - Hp 90010068

13/01/2020 @ 1010

5 days

0.00

0.00

Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.