

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 230/IC/TC/HO/2019
DATE : 06-DEC-2019

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MOHAMED KASSIM TAJUDEEN (ENH2-1014127)
ADDRESS : BLK 270 TOH GUAN RD
#11-101
S(600270)
TELEPHONE NO : 98578719/93862774

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SMH8432M 11/2/2019
MODEL CODE : FRLARDWJ11USA--A-B
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2018
ENGINE NO : HRA2693341A
CHASSIS NO : SJNFEAJ11U2393827
MILEAGE : 1 KM
DATE IN : 06/12/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 30/11/2019

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH8432M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 2 PANEL	240.00	/
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANEL	200.00	/
3	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	/
4	ZZ/001	REMOVE/INSTALL LH FRONT DOOR, LH REAR DOOR AND AFFECTED PORTION. REPAIR LH SIDE BODY PANEL	1170.00	975
5	ZZ/002	RESPRAY PAINT LH FRONT DOOR, LH REAR DOOR AND LH SIDE BODY PANEL	1000.00	500
6	ZZ/003	TRANSFER LH FRONT DOOR AND LH REAR DOOR MECHANISM TO NEW DOORS AND CHECK DOOR CENTRAL LOCKING SYSTEM	160.00	/
7	ZZ/004	REMOVE/INSTALL LH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	20.00	/
TOTAL LABOUR CHARGES			2893.00	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH8432M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	ABSORBER-SHOCK, REAR LH ?	E6210-HV02A			172.20
2	HUB-REAR WHEEL, LH ?	43202-4EA0A			365.40
3	LH REAR SPORTS RIM set ✓	D0C00-HV01A			1231.90
4	CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS ✓	76847-JG00A	8.10		
5	CLIP-LH REAR OVER FENDER @\$2.70EACH X3PCS ✓	76847-4EA0A	8.10		
6	OVER FENDER-REAR, LH cut ✓	93829-4EA0A	540.50		
7	LH REAR DOOR LOWER PVC MOULDING ✓	82871-4EA0A	280.40		
8	REGULATOR ASSY-REAR DOOR WINDOW, LH ?	82701-HV00A	455.90		
9	LH REAR DOOR UPPER HINGE ASSY ? X	82401-4EA0A	58.90		
10	LH REAR DOOR LOWER HINGE ASSY ?	82420-4EA0A	58.90		
11	TAPE-REAR DOOR OUTSIDE, LH ✓	82813-4EA0A	32.40		
12	TAPE-REAR DOOR OUTSIDE, LH ✓	82819-4EA0A	32.40		
13	DOOR-REAR LH bt ✓	H2101-HV0MB	1166.20		
14	LH FRONT DOOR LOWER PVC MOULDING ?	80871-4EA0A	342.60		
15	LOCK & REMOTE CONTROL ASSY-FRONT DOOR, LH ?	80501-HV00A	172.30		
16	WSTRIP ASSY-FRONT DOOR, LH X	80831-HV00A	139.20		
17	TAPE-FRONT DOOR OUTSIDE, LH ✓	80813-4EA0A	32.40		
18	DOOR-FRONT LH bt ✓	H0101-HV0MB	1166.20		
SUB TOTAL			4494.50	0.00	1769.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			898.90	0.00	0.00
GRAND TOTAL			3595.60	0.00	1769.50
OVERALL TOTAL			5365.10		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH8432M

TOTAL LABOUR CHARGES	2893.00
TOTAL SPARE PARTS CHARGES	5365.10
GRAND TOTAL	8258.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	:
LIABILITY	:
REMARKS	:

Ram - Hp 20010068

13/01/2020 @ 10.10

5 days

0.00

0.00

Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.