

INS. CASE OWNER:

Kachal m / CC4 / FC190 21778 / Kd 93

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

10/12/2019

Date / Time:

9/12/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 9520G

Claim No.:

019007704MFSH

Name of Insured:

City Cab Pte Ltd

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 04/12/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 438E



INSRS:

WSP: TRANS-CAB AUTO

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SHD438E - CC3/AIG101669E/K42432 DOA 15/08/11
 - CC3/AIG1022657/K4632 DOA 28/11/13
 - CC3/FC114032833/E4131 DOA 22/09/14
 SHA9520G - CS/FC114013345/M453 DOA 18/02/14
 TPA/EA115009286/12 DOA 28/05/15

70/2/2020 - FILE PAS To HmL To CLOK

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 13/2/2020

Confirm with: N2 W4 Y4

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/ LTR)

SS 2155.26

Loss of Rental (LOR):

SS 283.92

(

3 days) x \$94.64

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS 150.00

(\$

50 x

3 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$600

Total:

SS 2580.00

Global Sum SS: 2580.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 2580.00

Name 1:

Trans - Cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ISS. REC. BY:

REF: FCI

ASSIGNMENT

From: Date: 10.12.2014

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 438E

at Workshop m/s Trans cab

of NO 2 Amf Street 63

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.3.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 438E Yr Regn: 04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 349476 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1ABZ15AUC 283409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: ————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 4/12/19

D.O.I. 10/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5.2.2014.26

P/P - \$2014.26 (Red \$27712.13 / 93%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

E + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Form:

Lump Sum / T.B.:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19007704MFSH
Our ref: CC4/FCI19021778/Kda3

Date: 16/12/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 438E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10-12-2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	29,726.39
Revised Estimate Amount	: S\$	2,014.26
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,014.26
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 day

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E**AAD1912-028**

Not Authen
Resurvey B4 paint
82014.26

Vehicle No.:
 Chassis No.:
 Vehicle Make: **10 DEC 2019**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 438E

VF1ABL15AUC283409

RENAULT

LATITUDE

4.12.19

FCIL

27/4/2017

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Od/cm</i>	561.70 —
2	1	BUMPER LOWER REAR	\$	<i>nd</i>	411.90 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>sn</i>	98.10
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i>	82.10
5	1	BUMPER RETAINER RH REAR	\$	<i>sn</i>	59.80
6	1	BUMPER REFLECTOR RH	\$	<i>sn</i>	16.60
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>sn</i>	80.80
8	1	BUMPER RETAINER LH REAR	\$	<i>sn</i>	54.20
9	1	BUMPER REFLECTOR LH	\$	<i>sn</i>	16.60
10	1	BUMPER BEAM REAR	\$	<i>Bn</i>	547.80 —
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	114.50
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i>	100.90
13	1	OUTER PANEL REAR (End Panel)	\$	<i>n</i>	745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>sn</i>	404.56
15	1	TAILLAMP RH	\$	<i>sn</i>	313.10
16	1	TAILLAMP PANEL RH	\$	<i>n</i>	401.40
17	1	TAILLAMP LH	\$	<i>sn</i>	401.40
18	1	TAILLAMP PANEL LH	\$	<i>n</i>	401.40
19	1	BOOT REAR	\$	<i>n</i>	1,677.20
20	1	BOOT FINISHER	\$	<i>sn</i>	344.70
21	1	BOOT WHEATERSTRIP	\$	<i>sn</i>	178.20
22	1	BOOT REFLECTOR LAMP LH	\$	<i>sn</i>	277.70
23	1	BOOT REFLECTOR LAMP RH	\$	<i>sn</i>	277.70
24	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i>	82.40
25	1	BOOT BADGE	\$	<i>nn</i>	95.80
26	1	BOOT STRUT LH	\$	<i>sn</i>	145.10

Trans-cab Auto Services Pte Ltd

AAD1912-028

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

27	1	BOOT STRUT RH	\$	145.10	}
28	1	BOOT HINGE LH	\$	254.20	
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	2	BOOT BUFFER	\$	26.80	
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	}
38	1	EXHAUST CAP REAR	\$	125.40	
39	1	EXHAUST REAR	\$	5,263.60	
TOTAL			\$	15,232.66	
10%			\$	1,523.27	
			\$	13,709.39	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	X
11	1	BOOT STICKER "6555-3333"	\$	30.00	X
12	2	REAR WINDSCREEN SEALANT	\$	80.00	}
13	1	WINDSCREEN MOULDING	\$	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
15	1	BOOT INNER TRIM CLIP	\$	45.00	
16	1SET	BOOT FINISHER CLIP	\$	24.20	
17	1	TAILLAMP CLIP LH	\$	5.00	X

Trans-cab Auto Services Pte Ltd

AAD1912-028

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

18	1	TAILLAMP CLIP RH	\$	~ 5.00 X
19	1	Rear Bumper Protector	\$	~ 100.00 X
20	1	EXHAUST MOUNTING REAR	\$	~ 16.00 X
21	1	EXHAUST BRACKET REAR	\$	~ 24.80 X
TOTAL			\$	1,507.00
TOTAL PARTS			\$	15,216.39

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	~ 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X

Trans-cab Auto Services Pte Ltd**AAD1912-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

To repair and realign rear exhaust pipe.	\$	~ 170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 22cl

TOTAL \$ 14,510.00**Over All Total \$ 29,726.39****PART BY PART (REPAIR DAY)****20 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey (after spray painting)
- To resurvey damaged parts during resurvey
- Final claims are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implication is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Approved by Repairer

Signature

Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD438E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003338
Chassis No.:	VF1ABL15AUC283409
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Apr 2017
First Registration Date:	27 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$40,184.00
COE Rebate Amount:	\$27,096.00
Total Rebate Amount:	\$42,094.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Dec 2019

OK

MOTOR SURVEY ASSIGNMENT

Date	05-12-2019	Our Ref No. D19007704MFSH
Accident Date	04-12-2019	Claim Type. Third Party
Insured Vehicle	SHA9520G	Third Party Vehicle. SHD438E
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Kenneth

P: Zhe wei
 T: 5.27pm 9.12.19

V:lh

E:✓

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 18 December, 2019 6:03 PM
To: 'Rachel Wu'
Cc: 'CWS Motor Claims'; Jia Le (LKK Auto); Admin A
Subject: RE: SURVEY ASSESSMENT - D19007704MFSH/1
Attachments: TP ESTIMATE - MARKED.pdf; PRELIMINARY ADVICE.pdf

YOUR REF: D19007704MFSH
LKK REF: CC4/FC119021778/Kda3

Dear Sir / Madam,

We refer to the above matter.

We had inspected TP vehicle SHD 438E at M/s rans-cab Auto Services Pte Ltd - Ang Mo Kio on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

To check availability of the case handler, you may contact the undersigned.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 9 December, 2019 5:27 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Rachel Wu' <RachelWu@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007704MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI19021778/Kda3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-03-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9520G	Veh. Inspected	SHD 438E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D19007704MFSH	Excess (\$)	0.00	
Assign From	RachelWu	Assign Date	09/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283409	Colour	METALLIC WHITE / RED	
Odometer	349476	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	9 mm	
L/H Front Tyre	215/60 R16	SAILUN	9 mm	
R/H Rear Tyre	215/60 R16	SAILUN	9 mm	
L/H Rear Tyre	215/60 R16	SAILUN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2019	Inspection Date	10/12/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 438E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	DENTED / CRACKED	561.70	561.70
1	BUMPER LOWER REAR	DENTED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-
1	BOOT STRUT LH	SERVICEABLE	145.10	-

Report Ref No. CC4/FCI19021778/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
2	BOOT RUBBER PLUG	SERVICEABLE	139.90	-
2	BOOT BUFFER	SERVICEABLE	26.80	-
1	BOOT LOCK LINKAGE	SERVICEABLE	20.60	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	99.50	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	SERVICEABLE	246.60	-
1	BOOT LOCK CATCH	SERVICEABLE	41.70	-
1	EXHAUST CAP REAR	SERVICEABLE	125.40	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	5,263.60	-
	LESS 10% DISCOUNT		-1,523.27	-152.14
			13,709.39	1,369.26
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-

Report Ref No. CC4/FCI19021778/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	16.00	-
1	EXHAUST BRACKET REAR (SN)	NOT NECESSARY	24.80	-
			1,507.00	165.00
	LABOUR			
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH AND EXHAUST REAR.		6,000.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CC4/FCI19021778/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
			14,510.00	480.00
GRAND TOTAL			29,726.39	2,014.26
RECOMMENDED COST OF REPAIRS				2,014.26

Report Ref No. CC4/FCI19021778/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.