

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E**AAD1912-028***Not Notified
Resurvey B4 paint**82014.26*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 DEC 2019**SHD 438E**

VF1ABL15AUC283409

RENAULT

LATITUDE

4.12.19

FCIL

27/4/2017

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>odd/cm</i>	561.70	<i>—</i>
2	1	BUMPER LOWER REAR	\$	<i>nd</i>	411.90	<i>—</i>
3	1	BUMPER BRACKET CTR REAR	\$	<i>sn</i>	98.10	<i>X</i>
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i>	82.10	
5	1	BUMPER RETAINER RH REAR	\$	<i>sn</i>	59.80	
6	1	BUMPER REFLECTOR RH	\$	<i>sn</i>	16.60	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>sn</i>	80.80	
8	1	BUMPER RETAINER LH REAR	\$	<i>sn</i>	54.20	<i>X</i>
9	1	BUMPER REFLECTOR LH	\$	<i>sn</i>	16.60	
10	1	BUMPER BEAM REAR	\$	<i>B</i>	547.80	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	114.50	<i>X</i>
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i>	100.90	
13	1	OUTER PANEL REAR (End Panel)	\$	<i>n</i>	745.80	
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>sn</i>	404.56	
15	1	TAILLAMP RH	\$	<i>sn</i>	313.10	
16	1	TAILLAMP PANEL RH	\$	<i>n</i>	401.40	
17	1	TAILLAMP LH	\$	<i>sn</i>	401.40	
18	1	TAILLAMP PANEL LH	\$	<i>n</i>	401.40	
19	1	BOOT REAR	\$	<i>n</i>	1,677.20	
20	1	BOOT FINISHER	\$	<i>sn</i>	344.70	
21	1	BOOT WHEATERSTRIP	\$	<i>sn</i>	178.20	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>sn</i>	277.70	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>sn</i>	277.70	
24	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i>	82.40	
25	1	BOOT BADGE	\$	<i>nn</i>	95.80	
26	1	BOOT STRUT LH	\$	<i>sn</i>	145.10	

Trans-cab Auto Services Pte Ltd**AAD1912-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

27	1	BOOT STRUT RH	\$	145.10	}
28	1	BOOT HINGE LH	\$	254.20	
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	2	BOOT BUFFER	\$	26.80	
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	}
38	1	EXHAUST CAP REAR	\$	125.40	
39	1	EXHAUST REAR	\$	5,263.60	
TOTAL			\$	15,232.66	
10%			\$	1,523.27	
			\$	13,709.39	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	X
11	1	BOOT STICKER "6555-3333"	\$	30.00	X
12	2	REAR WINDSCREEN SEALANT	\$	80.00	}
13	1	WINDSCREEN MOULDING	\$	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
15	1	BOOT INNER TRIM CLIP	\$	45.00	
16	1SET	BOOT FINISHER CLIP	\$	24.20	
17	1	TAILLAMP CLIP LH	\$	5.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

18	1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 X
19	1	Rear Bumper Protector	\$	<i>nn</i> 100.00 X
20	1	EXHAUST MOUNTING REAR	\$	<i>nn</i> 16.00 X
21	1	EXHAUST BRACKET REAR	\$	<i>nn</i> 24.80 X
TOTAL			\$	1,507.00

TOTAL PARTS	\$	15,216.39
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 <i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

Trans-cab Auto Services Pte Ltd**AAD1912-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 438E

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>22cl</i>

TOTAL	\$	14,510.00
--------------	-----------	------------------

Over All Total	\$	29,726.39
-----------------------	-----------	------------------

PART BY PART (REPAIR DAY)~~20~~ DAYS*2 days*