

15/5/2016

INS. CASE OWNER:

CC 4/FCI190 2781, R1E1382

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

a/v/19

Date / Time:

6/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 1917M

Name of Insured:

CTDL

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

No/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

REVI S/O KWIMONY FERNANDEZ

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBK 71334



INSRS:

WSP:

Tel:

Liability:

RMKS:

HKL



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Of:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	1/5 S\$ 2,300	(4 days) Reduction: 65 %
FINAL SETTLEMENT	Date/Time: 17-02-20	Confirm with: JAMES
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 15
Repair Cost:	S\$ 2,300.00	LOD CHARGED JANE AND HAY TP
Loss of Rental (LOR):	S\$ -	(days)
Loss of Use (LOU):	S\$ 120.00	(\$ 30 x 4 days)
Loss of Income (LOI):	S\$ -	(\$ x days)
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LO ☐	[Tick only one]
GIA/LTA Search	S\$ -	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost	S\$ -	
Total:	S\$ 2,420.00	Global Sum S\$:
FINAL PAYMENT	Date/Time: 17-02-20	Confirm with: JAMES
Payee 1:	S\$ 2,420.00	Name 1: HKL WIM TEAM - MOTORSPORT.
Payee 2: (Strike if N.A.)	S\$ -	Name 2:
Payee 3: (Strike if N.A.)	S\$ -	Name 3:

COPY SENT
24/2/2020

ASS. REC. BY:

REF:

Special Instruction:

Surveyor

SEVL

ASSIGNMENT (Office)

From (Person):

Joanny

of

PCL

Date/Time:

6.12.19 6.30p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 71334

Insured:

SHC 1917m

at Workshop m/s

HK2 Kim Tam

Tel:

62756656

of

Bik 1008 # 01-24 Bukit Merah Lane 3

Policy No:

Claim No:

D19 007543mFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26.11.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

9.12.19 10.46a.m

Person Contacted:

James

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

/ASS. REC. BY: RomeREF: FC1

0756

COE EXPIRY: 2025/06

ASSIGNMENT

From:

Date:

9.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBK 71334

at Workshop m/s

HKL Lim

of

BIC 1008 #01-24 Bukit merah Lane 3

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

6.5K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBK 71334

Yr Regn:

2006 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA SPARK 135M

C.C.

135

Colour:

Mat White

A/C:

Insured / Std / NI / NA

Sp. Reading

49085

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SP710936

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

26/11/19

D.O.I.

09/12/19

Survey held at

HKL LIM

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ UIC / ☒ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	4s: 42,300 (3ED) 4,303 (65/-)
	M.V : +6,500
	N.A : +4,085
	N.V : +2,415

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Form:

Lump Sum / F.B.I. (\$

MOTOR SURVEY ASSIGNMENT

Date	28-11-2019	Our Ref No. D19007543MFSH
Accident Date	26-11-2019	Claim Type. Third Party
Insured Vehicle	SHC1917M	Third Party Vehicle. FBK7133Y
Survey Location	BLK 1008 #01-24 Bukit Merah Lane 3	
Contact Person.	JAMES LIM (KEONG)	
Contact No.	62756656/ 62756566	Fax No. 62729291
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HKL LIM TEAM MOTORSPORT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



HKL LIM
TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6666, 62727292 Fax: 6272 9291
Email: support@hklmotorsport.com.sg Website: www.hklmotorsport.com.sg

Steve 24/12/19

FBK7133Y

- 1 LAMP STAY ? / NT
- 2 METER ASSY ? / SHH
- 3 FRONT FORK ASSY LH/RH bt
- 4 FRONT FORK UNDER BRACKET bt
- 5 STEERING CONE BEARING neu
- 6 BODY FRAME ALIGNMENT repair
- 7 FRONT FENDER cra
- * 8 WHEEL RIM SET repair bt (FA 100) (SH)
- 9 FRONT WHEEL SHALE ? X su
- 10 FRONT WHEEL BEARING 2PCS ? / MC
- 11 FRONT WHEEL BEARING OIL SEAL neu
- 12 FRONT BRAKE DISC ? / NT
- 13 FRONT BRAKE CALIPER X su
- 14 HEAD COWLING sca
- 15 PILOT LIGHT X cra
- 16 SIGNALS SWITCH LH X su
- 17 IU UNIT cut
- 18 IU BRACKET X su
- 19 HANDLE BAR ? X su
- 20 HANDLE BAR BRACKET ? / NT
- 21 HANDLE BAR BALANCER sca
- 22 HANDLE BAR FRONT COVER cra
- 23 HANDLE BAR REAR COVER cra
- 24 FRONT NO PLATE neu
- 25 BRAKE LEVER X
- 26 CLUTCH LEVER X } su
- 27 SIDE MIRROR ? X }
- 28 HEAD LIGHT X
- 29 BRAKE PEDAL X
- 30 FRONT FOOT REST RUBBER cut
- 31 FRONT FOOT REST BRACKET bt
- 32 EXHAUST YOSHIMURA repair
- 33 EXHAUST GUARD R&B sca R&B
- 34 SIDE FAIRING LH/RH cra
- 35 TAIL BOARD LH/RH cra
- 36 CENTER COVER cra
- 37 CENTER PANEL X cra
- 38 SEAT PANEL X su
- 39 FAIRING STICKET SET neu
- 40 CDI UNIT ? / SHH
- 41 TOP BOX su
- 42 TOP BOX BRACKET BIG SET X su
- 43 BASKET cra
- 44 INSPECTION X su
- 45 TOWING -
- 46 LABOUR

3012
10%
2710.80

\$	60.00
\$	190.00
\$	240.00
\$	150.00
\$	70.00
\$	680.00 L - 300
\$	60.00
\$	250.00
\$	25.00 X
\$	40.00
\$	10.00
\$	120.00
\$	180.00 X
\$	90.00
\$	90.00
\$	95.00 X
\$	180.00
\$	25.00 X
\$	80.00 X
\$	60.00
\$	30.00
\$	55.00
\$	55.00
\$	12.00
\$	18.00 X
\$	18.00 X
\$	45.00 X
\$	90.00 X
\$	60.00 X
\$	20.00
\$	70.00
\$	1,200.00 XR
\$	120.00
\$	180.00
\$	180.00
\$	120.00
\$	45.00
\$	55.00 X
\$	80.00
\$	220.00
\$	180.00
\$	150.00 X
\$	35.00
\$	90.00 X
\$	30.00
\$	750.00

Rasul
Hp 90010068
4 days
L/S
09/12/19
@1740
Resy after
repair

TOTAL

Supplementary
Vol meter. \$90 /

90 x 10% = 81

/ SHH

\$ 6,603.00
6693

P - 2710.80

Suppl P - 81.00

L - 630.00

3,421.80

20%

2737.44

Repair limit
\$2,300



HKL LIM
TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6556, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklmotorsport.com.sg Website: www.hklmotorsport.com.sg

FBK7133Y

1 LAMP STAY ?	\$	60.00
2 METER ASSY ?	\$	190.00
3 FRONT FORK ASSY LH/RH <i>bt</i>	\$	240.00
4 FRONT FORK UNDER BRACKET <i>bt</i>	\$	150.00
5 STEERING CONE BEARING <i>re</i>	\$	70.00
6 BODY FRAME ALIGNMENT <i>repair</i>	\$	680.00 <i>L - 300</i>
7 FRONT FENDER <i>cr</i>	\$	60.00
8 WHEEL RIM SET <i>repair</i>	\$	250.00
9 FRONT WHEEL SHALF ?	\$	25.00
10 FRONT WHEEL BEARING 2PCS ?	\$	40.00
11 FRONT WHEEL BEARING OIL SEAL <i>re</i>	\$	10.00
12 FRONT BRAKE DISC ?	\$	120.00
13 FRONT BRAKE CALIPER <i>X</i>	\$	180.00
14 HEAD COWLING <i>scd</i>	\$	90.00
15 PILOT LIGHT <i>cr</i>	\$	90.00
16 SIGNALS SWITCH LH <i>X</i>	\$	95.00
17 IU UNIT <i>cut</i>	\$	180.00
18 IU BRACKET <i>X</i>	\$	25.00
19 HANDLE BAR ?	\$	80.00
20 HANDLE BAR BRACKET ?	\$	60.00
21 HANDLE BAR BALANCER <i>scd</i>	\$	30.00
22 HANDLE BAR FRONT COVER <i>cr</i>	\$	55.00
23 HANDLE BAR REAR COVER <i>cr</i>	\$	55.00
24 FRONT NO PLATE <i>re</i>	\$	12.00
25 BRAKE LEVER <i>X</i>	\$	18.00
26 CLUTCH LEVER <i>X</i>	\$	18.00
27 SIDE MIRROR <i>X</i>	\$	45.00
28 HEAD LIGHT	\$	90.00
29 BRAKE PEDAL <i>X</i>	\$	60.00
30 FRONT FOOT REST RUBBER <i>cut</i>	\$	20.00
31 FRONT FOOT REST BRACKET <i>bt</i>	\$	70.00
32 EXHAUST YOSHIMURA <i>repair</i>	\$	1,200.00
33 EXHAUST GUARD R&A <i>scd</i> <i>R&H</i>	\$	120.00
34 SIDE FAIRING LH/RH <i>cr</i>	\$	180.00
35 TAIL BOARD LH/RH <i>cr</i>	\$	180.00
36 CENTER COVER <i>cr</i>	\$	120.00
37 CENTER PANEL <i>cr</i>	\$	45.00
38 SEAT PANEL <i>X</i>	\$	55.00
39 FAIRING STICKET SET <i>re</i>	\$	80.00
40 CDI UNIT ?	\$	220.00
41 TOP BOX <i>scd</i>	\$	180.00
42 TOP BOX BRACKET BIG SET <i>X</i>	\$	150.00
43 BASKET <i>cr</i>	\$	35.00
44 INSPECTION <i>X</i>	\$	90.00
45 TOWING	\$	30.00
46 LABOUR	\$	750.00 <i>300</i>

TOTAL

Let A. T. Lim, hence notify
the Rep. of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
4p 90010068

4 days

L/S

09/12/19

@1740

Resy after repair

\$ 6,603.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	075E
Vehicle Details	
Vehicle No.:	FBK7133Y
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	YAMAHA
Vehicle Model:	SPARK 135 M
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	5YP710936
Chassis No.:	5YP710936
Maximum Power Output:	-
Open Market Value:	\$1,786.00
Original Registration Date:	03 Mar 2006
First Registration Date:	03 Mar 2006
Transfer Count:	8
Actual ARF Paid:	\$268.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,265.00
COE Rebate Amount:	\$4,085.00
Total Rebate Amount:	\$4,085.00

The information contained herein is correct as at 10 Dec 2019

OK

6500
4085

2415



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19021781/R1ea3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-02-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1917M	Veh. Inspected	FBK 7133Y
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D19007543MFSH	Excess (\$)	0.00
Assign From	JOANNEY	Assign Date	06/12/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA SPARK 135 M	c.c	135
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	5YP710936	Colour	WHITE
Odometer	49085	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/90-17	MAXXIS	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/11/2019	Inspection Date	09/12/2019
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7133Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LAMP STAY	BENT	60.00	60.00
1	METER STAY	SHORTED	190.00	190.00
2	FRONT FORK ASSY LH/RH	BENT	240.00	240.00
1	FRONT FORK UNDER BRACKET	BENT	150.00	150.00
1	STEERING CONE BEARING	NECESSARY	70.00	70.00
1	FRONT FENDER	CRACKED	60.00	60.00
1	SET WHEEL RIM (FRT & REAR)	BENT	250.00	250.00
1	FRONT WHEEL SHALF	SERVICEABLE	25.00	-
2	FRONT WHEEL BEARING	NECESSARY	40.00	40.00
1	FRONT WHEEL BEARING OIL SEAL	NECESSARY	10.00	10.00
1	FRONT BRAKE DISC	BENT	120.00	120.00
1	FRONT BRAKE CALIPER	SERVICEABLE	180.00	-
1	HEAD COWLING	SCRATCHED	90.00	90.00
1	PILOT LIGHT	CRACKED	90.00	90.00
1	SIGNALS SWITCH LH	SERVICEABLE	95.00	-
1	IU UNIT	CUT	180.00	180.00
1	IU BRACKET	SERVICEABLE	25.00	-
1	HANDLE BAR	SERVICEABLE	80.00	-
1	HANDLE BAR BRACKET	BENT	60.00	60.00
1	HANDLE BAR BALANCER	SCRATCHED	30.00	30.00
1	HANDLE BAR FRONT COVER	CRACKED	55.00	55.00
1	HANDLE BAR REAR COVER	CRACKED	55.00	55.00
1	FRONT NO PLATE	NECESSARY	12.00	12.00
1	BRAKE LEVER	SERVICEABLE	18.00	-
1	CLUTCH LEVER	SERVICEABLE	18.00	-
1	SIDE MIRROR	SERVICEABLE	45.00	-
1	HEAD LIGHT	SERVICEABLE	90.00	-
1	BRAKE PEDAL	SERVICEABLE	60.00	-
1	FRONT FOOT REST RUBBER	CUT	20.00	20.00
1	FRONT FOOT REST BRACKET	BENT	70.00	70.00

Report Ref No. CC4/FCI19021781/R1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST YOSHIMURA	TO REPAIR SEE LABOUR	1,200.00	-
1	EXHAUST GUARD R&G	SCRATCHED	120.00	120.00
2	SIDE FAIRING LH/RH	CRACKED	180.00	180.00
2	TAIL BOARD LH/RH	CRACKED	180.00	180.00
1	CENTER COVER	CRACKED	120.00	120.00
1	CENTER PANEL	CRACKED	45.00	45.00
1	SEAT PANEL	SERVICEABLE	55.00	-
1	SET FAIRING STICKER	NECESSARY	80.00	80.00
1	CDI UNIT	SHORTED	220.00	220.00
1	TOP BOX	SCRATCHED	180.00	180.00
1	SET TOP BOX BRACKET BIG	SERVICEABLE	150.00	-
1	BASKET	CRACKED	35.00	35.00
1	VOL METER (ADDITIONAL)	SHORTED	90.00	90.00
	LESS 10% DISCOUNT		-	-310.20
			5,143.00	2,791.80
	LABOUR			
	BODY FRAME ALGNMENT	NOT NECESSARY	680.00	300.00
	INSPECTION.		90.00	-
	TOWING.		30.00	30.00
	LABOUR.		750.00	300.00
			1,550.00	630.00
GRAND TOTAL			6,693.00	3,421.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/FCI19021781/R1ea3s2

MARKET VALUE: \$6,500.00 - LTA REIMBURSEMENT VALUE: \$4,085.00 = NETT VALUE: \$2,415.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.