

Ashen



Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6856, 6275 6566, 62727292 Fax: 6272 9291  
Email: support@hklmotorport.com.sg Website: www.hklmotorport.com.sg

Steve 24/12/19

FBK7133Y

|                                         |    |                |
|-----------------------------------------|----|----------------|
| 1 LAMP STAY ? / BT                      | \$ | 60.00          |
| 2 METER ASSY ? / SHM                    | \$ | 190.00         |
| 3 FRONT FORK ASSY LH/RH bt              | \$ | 240.00         |
| 4 FRONT FORK UNDER BRACKET bt           | \$ | 150.00         |
| 5 STEERING CONE BEARING neu             | \$ | 70.00          |
| 6 BODY FRAME ALIGNMENT repair           | \$ | 680.00 L - 300 |
| 7 FRONT FENDER cm                       | \$ | 60.00          |
| 8 WHEEL RIM SET repair bt (F1 100) (SH) | \$ | 250.00         |
| 9 FRONT WHEEL SHALF ? X su              | \$ | 25.00 X        |
| 10 FRONT WHEEL BEARING 2PCS ? / ML      | \$ | 40.00          |
| 11 FRONT WHEEL BEARING OIL SEAL neu     | \$ | 10.00          |
| 12 FRONT BRAKE DISC ? / BT              | \$ | 120.00         |
| 13 FRONT BRAKE CALIPER X su             | \$ | 180.00 X       |
| 14 HEAD COWLING scd                     | \$ | 90.00          |
| 15 PILOT LIGHT X cm                     | \$ | 90.00          |
| 16 SIGNALS SWITCH LH X su               | \$ | 95.00 X        |
| 17 IU UNIT cut                          | \$ | 180.00         |
| 18 IU BRACKET X su                      | \$ | 25.00 X        |
| 19 HANDLE BAR ? X su                    | \$ | 80.00 X        |
| 20 HANDLE BAR BRACKET ? / BT            | \$ | 60.00          |
| 21 HANDLE BAR BALANCER su               | \$ | 30.00          |
| 22 HANDLE BAR FRONT COVER cm            | \$ | 55.00          |
| 23 HANDLE BAR REAR COVER cm             | \$ | 55.00          |
| 24 FRONT NO PLATE neu                   | \$ | 12.00          |
| 25 BRAKE LEVER X                        | \$ | 18.00 X        |
| 26 CLUTCH LEVER X                       | \$ | 18.00 X        |
| 27 SIDE MIRROR X } su                   | \$ | 45.00 X        |
| 28 HEAD LIGHT X                         | \$ | 90.00 X        |
| 29 BRAKE PEDAL X                        | \$ | 60.00 X        |
| 30 FRONT FOOT REST RUBBER cut           | \$ | 20.00          |
| 31 FRONT FOOT REST BRACKET bt           | \$ | 70.00          |
| 32 EXHAUST YOSHIMURA repair             | \$ | 1,200.00 XR    |
| 33 EXHAUST GUARD R&L su                 | \$ | 120.00         |
| 34 SIDE FAIRING LH/RH cm                | \$ | 180.00         |
| 35 TAIL BOARD LH/RH cm                  | \$ | 180.00         |
| 36 CENTER COVER cm                      | \$ | 120.00         |
| 37 CENTER PANEL X cm                    | \$ | 45.00          |
| 38 SEAT PANEL X su                      | \$ | 55.00 X        |
| 39 FAIRING STICKET SET neu              | \$ | 80.00          |
| 40 CDI UNIT ? / Short                   | \$ | 220.00         |
| 41 TOP BOX su                           | \$ | 180.00         |
| 42 TOP BOX BRACKET BIG SET X su         | \$ | 150.00 X       |
| 43 BASKET cm                            | \$ | 35.00          |
| 44 INSPECTION X su                      | \$ | 90.00 X        |
| 45 TOWING                               | \$ | 30.00          |
| 46 LABOUR                               | \$ | 750.00         |
| TOTAL                                   |    | \$ 6,603.00    |

3012  
1090  
2710.80

Rasu  
Hp 90010068

4 days

L/S

09/12/19

@1740

Rasy after  
repair

300 330 + 300 = 630

Supplementary  
Vol meter. \$90 / Short

90 x 10% = 81

P - 2710.80  
Suppl P - 81.00  
L - 630.00  
T - 3,421.80  
20%  
2737.44

Repair limit  
\$2,300