

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22217

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1452/2019/NS
Date : 9-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Koh Hui Kuan @ Kho Hui Kuan
Address : 60 Havelock Road
#06-28
Singapore 169658
Telephone : HP +65 96572023
Type of Claim : Own Damage Claims
Policy No. : 1800118528-01
Vehicle No : **SME 6357 B**
Model Code : Audi Q2 TFSI S TRONIC
Model / Year : Oct-18
Engine No : CHZ A90356
Chassis No : WAUZZZGAXKA000419
Mileage : 10555
Date In : 9-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Dec-19
Place of Accident : IMM Carpak Level 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 6357 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	\$280-00
2	To dismantle and renew rear bumper. To repair rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 1,600.00 ✓	500 \$500-00
3	To respray rear bumper and rear lid. ✓	\$ 2,200.00 ✓	1100 \$1100-00
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	\$192-00
TOTAL LABOUR CHARGES		: \$ 4,272.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 6357 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>rehd</i>	\$ 1,074.00 ✓	\$859-20
2	REAR BUMPER FIXING PARTS <i>nee</i>	\$ 70.00 ✗	
3	REAR BUMPER SPOILER - LH <i>Del.</i>	\$ 259.00 ✓	\$207-20
4	REAR BUMPER TOWING EYE COVER <i>nee</i>	\$ 39.00 ✗	
5	REAR LIGHT REFLECTOR - LH <i>nee</i>	\$ 27.00 ?	
6	TAIL LIGHT - LH <i>could</i>	\$ 1,207.00 ✓	\$965-60
7	TAIL LIGHT TRIM - LH <i>nee</i>	\$ 27.00 ✗	
8	REAR BUMPER CARRIER <i>nee</i>	\$ 501.00 ?	
9	REAR BUMPER HOLDING STRAP - LH / RH <i>nee</i>	2 \$ 24.00 +	
10	REAR BUMPER GUIDE SECTION - LH <i>nee</i>	\$ 49.00 +	
11	REAR PARKLING AID SENSOR - INNER / OUTER <i>nee</i>	2 \$ 462.00 +	
12	REAR PARKING AID SEAL RING <i>nee</i>	4 \$ 12.00 +	
13	AUDI EMBLEM <i>nee</i>	\$ 113.00 -	\$90-60
14	Q2 INSCRIPTION <i>nee</i>	\$ 87.00 -	\$69-28
15	REAR WHEEL COVER - LH / RH <i>nee</i>	2 \$ 312.00 ✓	\$248-80
16	SUNDRIES <i>nee</i>	\$ 300.00 ?	
TOTAL SPARE PARTS		: \$ 4,563.00	
TOTAL LABOUR CHARGES		: \$ 4,272.00	
GRAND TOTAL		: \$ 8,835.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.