


.

1.0

-



.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	09/12/2019 11:01
Date Of Accident	08/12/2019 12:10
Exact Location Of Accident	ECP TO CHANGI AIRPORT
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SFA8798C
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.
Co Reg No	199400399N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67341222
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700006240-02
Cover Note Number	
Driver	
W (D)	CHIIA GEK LENG

CHUA GEK LENG Name of Driver S1697578H NRIC No 02/08/1965 Date Of Birth INDOOR Occupation 10/10/1985 Date Of Driving Pass 34 YEARS AND 1 MONTH **Driving Experience** MALE Gender (LOCAL) +65-96304537

Mobile Number Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 122 B SENG KANG EAST WAY

#15-21

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

PAID DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: CHUA LEE NGOH

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING FROM ECP TOWARDS CHANGI AIRPORT. THERE IS THREE LANE ON THE ROAD AND I WAS IN THE SECOND LANE. SUDDENLY THERE IS A CAR COMING FROM BEHIND (RIGHT HAND SIDE) COLLIDED WITH MY CAR. AFTER THE ACCIDENT, I CAME DOWN FROM THE CAR AND EXCHANGE PARTICULAR WITH THE GUY (DRIVER'S OF SKQ 2939 J) WHO COLLIDED WITH MY CAR.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKQ2939J

Vehicle Make/Model/Colour

TOYOTA/WHITE

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMED RAFIE BIN SYED IBRAHIM

NRIC/Passport Number

S1736588F

Contact Number

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers 'lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature
Steffie: WORL KAIDALL, SENG, GROOP

NRIC/FIN No.: G2987143X

CH PLAN		
	国家	A - SFA 8798C B - SKQ 2939J
scribe circumstances of	THE ACCIDENT	Air port. There is three
here is a cour	Ater the Accident 1 came articular bithe with the	second lane. Suddenly. right handside) costs collided down from the car guy (Driver's of SKQ 2939
DO COMPAS:	13	
DECLARATION		
VWe derive the ferracing conti	rufars are true in every respect.	TOWOLD STATE OF THE STATE OF TH
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder)	Name: WORK KHONG SENG, FOR NRIC/FIN No: G298-143X

Date & Time:

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Workshop : Accident Repairs : Ubi Road 1

Contact No

: 6366 2323

Fax No

: 6841 1183

Reference

: PA/OD/1453/2019/NS

WIP: 22310

Date

: 10-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Hitachi Capital Asia Pacific Pte Ltd

Address

Triple One Somerset

111 Somerset Road #11-05

Singapore 238164

Telephone Type of Claim (Office) +65 67341222 Own Damage Claims

Policy No.

1700006240-02

Vehicle No

: SFA 8798 C

Model Code

: Audi A4 SEDAN 1.4 TFSI

Model / Year

: 30/5/2017

Engine No

: CVN 033131

Charle No

: WAUZZZF47HA129710

Chassis No

:

Mileage Date In

: 8-Dec-19

Estimated By

: Johnny Boo / Allan Wu

Accident Date

: 8-Dec-19

Place of Accident

: Ecp To Changi Airport

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Reccomendations
1	To tow and recover vehicle from scene of sccident.	S/N	\$ 280.00	X
2	To carry out first measurement test on car oliner.	S/N	\$ 800.00	~
3	To remove, check and reinstall front wire harness for headlights, horns outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
4	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 7	✓
5	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 560.00	/ /
6	to dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N	\$ 300.00	X
	SUB TOTAL LABOUR CHARGES	:	\$ 2,660.00	

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

			Estimated	Surveyor's
S/n	Nature of Jobs		Charges	Reccomendations
7	To remove and renew rhs rear 1/4 glass and rear windscreen.	S/N	\$ 600.00	
8	To install rear windscreen solar film.	S/N	\$ 400.00 7	X
9	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, elecrtrical and audio equipment.	S/N	\$ 1,400.00 ?	pluh
10	To remove and reinstall front seat, rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,800.00	1400
11	To dismantle and reinstall centre console. Renew airbag control unit and both front seatbelt.	S/N	\$ 1,800.00	*
12	To remove and reinstall exhaust system and rear suspension assembly, including rear axle. Renew accordingly.	S/N	\$ 2,400.00	photo
	SUB TOTAL LABOUR CHARGES	:	\$ 8,400.00	

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

S/n	Nature of Jobs			Estimated Charges	Surveyor's Reccomendations
13	To remove and reinstall fuel tank assy.	S/N	\$	600.00	· /
14	To place car on car o-liner.	S/N	\$	2,400.00 Rasul	· 🗸
15	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door and rear bumper. To renew rhs front fender, rhs front door,rhs rear door and rear bumper. To cut out and reweld rhs rear fender, rhs rear fender outer wheel housing with connecting plate, rhs sill panel and rhs Bpillar. re-organise crash management components. reinstall all parts removed.		5	Rossul 13,306.00	Me Adria
16	To respray front bumper, rhs front fender, rhs front door, rhs wing mirror cover, door handle, rhs rear door, rhs sill panel, rhs B-pillar, rhs rear fender, rhs rear fender outer wheel housing with connecting plate, rear bumper, door entrances, roof channel, drain channel and end panelling.		\$	10,300.00	4650 ~
17	To renew rhs front rim, rhs rear rim and rhs rear tyre. To carry out wheel alignment.	S/N	\$	320.00	
18	To carry out diagnostic check.	S/N	\$	384.00	~
	SUB TOTAL LABOUR CHARGES	:	\$	38,364.00	

Telefax

		Damaged Pa		
S/N	Parts Description		S/Nett	Remarks
1	SIDE PANEL FRAME - RH		\$ 2,856.00	D284.80
2	FRONT BUMPER X		\$ 2,015.00	
3	FRONT BUMPER FIXING PARTS 🗡		\$ 66.00	
4	FRONT BUMPER SECURING STRIP 🗡		\$ 203.00	
5	FRONT BUMPER SPOILER - LH 🗡		\$ 227.00	
6	FRONT BUMPER GUIDE SECTION - RH		\$ 41.00	
7	WHEEL HOUSING - RH OUTER X		\$ 574.00	
8	REAR WINDOW ? 3 hat		\$ 1,049.00	839.20
9	PRIMER NA /		\$ 19.00	
10	SIDE WINDOW - RH		\$ 561.00	448.40
11	FRONT DOOR - RH St		\$ 2,152.00	1721.60
12	FRONT DOOR OUTER SEAL RE-	NEC	\$ 185.00	147.60
13	BONDING AGENT No.	NEC	\$ 45.00	35.92
14	CLEANING SOLUTION NEW	NEC	\$ 65.00	51.68
15	SEALING STRIP 7		\$ 15.00	
16	FRONT DOOR CATCH X		\$ 109.00	
17	DOOR HINGE - RH UPPER 7 X		\$ 41.00	
18	HING HALVES - RH UPPER / LOWER 7. X	2	\$ 84.00	
19	HINGE HALVES - RH LOWER -		\$ 42.00	
20	FRONT DOOR INNER SEAL 🔨 ⊀		\$ 201.00	
	SUB TOTAL SPARE PARTS CHARGES	:	\$ 10,550.00	

Telefax

S/N	Parts Description			Damaged Par S/Nett	ts <u>& Prices</u> Remarks
21	REAR DOOR ST		\$	2,152.00	1721-60
22	REAR DOOR OUTER SEAL - RH		\$	185.00	147.60
23	BONDING AGENT No.	NEC	5	45.00	35.92
	CLEANING SOLUTION ALL		\$	65.00	51.68
24	~ 4	NEC	\$	96.00	-, 00
25	REAR DOOR CATCH X		\$	185.00	
26	REAR DOOR SEAL - INNER - REAR DOOR ATTACHMENT PARTS		\$	488.00	
27	REAR DOOR ATTACHMENT PARTS				
28	TYRE PRESSURE DATA PLATE		\$	35.00	
29	DOOR HANDLE TRIM PLATE 7 ×		\$	80.00	
30	LOCK CYLINDER 7. X		\$	492.00	
31	DOOR HANDLE SENSOR - RH		\$	208.00	
32	EXTERIOR DOOR HANDLE - RH T. 4 m		\$	35.00	
33	FRONT PERIPHERAL LIGHT - RH		\$	66.00	
34	MOUNTING BAR ? X		\$	149.00	
35	EXTERIOR MIRROR MOUNTING - RH MARPOIS -		\$	824.00	658.80
36	MIRROR CAP - RH ML3		\$	220.00	175.60
37	MIRROR GLASS - RH 7.		\$	1,553.00	
38	WINDOW REGULATOR - RH		\$	250.00	
39	WINDOW REGULATOR MOTOR - RH 7 X		\$	278.00	
40	DOOR CONTROL UNIT		\$	685.00	
	SUB TOTAL SPARE PARTS CHARGES	:	\$	8,091.00	

Telefax

				Damaged Par	
S/N	Parts Description			S/Nett	Remarks
41	DOOR LOCK ? X		\$	487.00	
42	B PILLAR TRIM - RH 7 X		\$	212.00	
43	CORNER TRIM - RH 💆 🗡		\$	41.00	
44	WINDOW GUIDE - RH 🔀		\$	412.00	
45	CLIP Men / X	16	\$	12.00	
46	WINDOW SLOT SEAL - RH de		\$	280.00	400
47	WINDOW GUIDE TRIM STRIP - RH 7 X		\$	235.00	
48	SILL TRIM STRIP - RH 7		\$	109.00	87.70
49	DATA TAG 💥 🔨		\$	423.00	338
50	FRONT FENDER - RH repair		\$	700.00	
51	FRONT FENDER ATTACHMENT PARTS X		\$	183.00	
52	FRONT FENDER BRACKET X		\$	29.00	
53	FRONT FENDER BRAKCET 🗡		\$	31.00	
54	FRONT FENDER CLOSING ELEMENT - RH		\$	30.00	
55	FENDER LEDGE COVER 🗡		\$	28.00	
56	FENDER LEDGE TOP COVER - RH ★		\$	21.00	
57	FRONT WHEEL HOUSING LINER - RH		\$	220.00	
58	WHEEL HOUSING LINER ATTACHMENT PARTS X		\$	82.00	
59	REAR WHEEL HOUSING LINER - RH		\$	223.00	
60	STONE CHIP GUARD X		\$	46.00	
	SUB TOTAL SPARE PARTS CHARGES	:	\$	3,804.00	-

Telefax

S/N	Parts Description		Damaged Pa S/Nett	rts & Prices Remarks
61	THREE POINT AUTOMATIC SEATBELT - LH / RH	2	\$ 2,010.00	
62	SEAT BELT HEIGHT ADJUSTER X	2	\$ 322.00	
63	AIRBAG CONTROL UNIT X		\$ 1,927.00	
64	PRESSURE SENSOR		\$ 245.00	
65	AIRBAG CRASH SENSOR - REAR		\$ 412.00	
66	CENTRAL PROTECTION ? X		\$ 485.00	
67	SUPPORT FRAME 7		\$ 2,975.00	2380
68	WISHBONE - LOWER ?		\$ 785.00	68
69	WISHBONE - RH UPPER 7.		\$ 507.00	405.20
70	WISHBONE - RH FRONT 7		\$ 112.00	89.60
71	WISHBONE ?		\$ 407.00	325.60
72	REAR TRACK ROD - RH		\$ 155.00	124
73	WHEEL BEARING HOUSING - RH 7.		\$ 903.00	745.60
74	WHEEL BEARING HOUSING - RH		\$ 404.00	322.80
75	STONE CHIP GUARD 🔨 🗡		\$ 40.00	
76	GAS SHOCK ABSORBER 7		\$ 276.00	2201FD
77	ALUMINIUM RIM - RH FRONT / REAR		TBC	760
78	REAR TYRE-RH punctured -		TBC	780
79	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	200
80	1/4 GLASS SEALANT NEC	S/N	\$ 100.00	100
	SUB TOTAL SPARE PARTS CHARGES	:	\$ 12,265.00	- -

Telefax

			Damaged Par	rts & Prices
S/N	Parts Description		S/Nett	Remarks
81	ACRYLIC SEALANT NE	S/N	\$ 360.00	180
82	CAVITY WAX NL	S/N	\$ 280.00	140
83	STONE CHIP /	S/N	\$ 360.00	180
84	METAL FILLER POWDER	S/N	\$ 280.00	280
85	SUNDRIES 7		\$ 1,000.00	129.92
	TOTAL SPARE PARTS CHARGES	:	\$ 36,990.00	
	TOTAL LABOUR CHARGES	:	\$ 38,364.00	
	GRAND TOTAL	:	\$ 75,354.00	
	All charges are not inclusive of GST. Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.		79,594	

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date **Authorised Date**

Excess Cost

Liability Remarks RASUL - Hp 90010068

Resures before paint

LKK Auto Consultants hence notify

To display damaged part(s) during resurvey

Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

· Parts prices are subject to confirmation

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

the Repairer of the following: To resurvey before/after spray painting

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant