

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22310

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1453/2019/NS
Date : 10-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Hitachi Capital Asia Pacific Pte Ltd
Address : Triple One Somerset
111 Somerset Road #11-05
Singapore 238164
Telephone : (Office) +65 67341222
Type of Claim : Own Damage Claims
Policy No. : 1700006240-02
Vehicle No : **SFA 8798 C**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : 30/5/2017
Engine No : CVN 033131
Chassis No : WAUZZZF47HA129710
Mileage :
Date In : 8-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Dec-19
Place of Accident : Ecp To Changi Airport

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00 /	Xnn
2	To carry out first measurement test on car o-liner.	S/N \$	800.00 /	✓
3	To remove, check and reinstall front wire harness for headlights, horns outside temperature sensor and headlight washer assy.	S/N \$	360.00 X	nn
4	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00 ?	✓
5	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00 /	✓
6	to dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$	300.00 /	Xnn
SUB TOTAL LABOUR CHARGES		:	\$ 2,660.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Reccomendations
7	To remove and renew rhs rear 1/4 glass and rear windscreen.	S/N \$	600.00	✓
8	To install rear windscreen solar film.	S/N \$	400.00	? nn X
9	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, elecrtical and audio equipment.	S/N \$	1,400.00	? photo ✓
10	To remove and reinstall front seat, rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,800.00	✓ 1400
11	To dismantle and reinstall centre console. Renew airbag control unit and both front seatbelt.	S/N \$	1,800.00	? X nn
12	To remove and reinstall exhaust system and rear suspension assembly, including rear axle. Renew accordingly.	S/N \$	2,400.00	? photo ✓
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 8,400.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFA 8798 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
13	To remove and reinstall fuel tank assy.	S/N \$ 600.00 ✓	✓
14	To place car on car o-liner.	S/N \$ 2,400.00 ✓	✓
	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door and rear bumper. To renew rhs front fender, rhs front door, rhs rear door and rear bumper. To cut out and reweld rhs rear fender, rhs rear fender outer wheel housing with connecting plate, rhs sill panel and rhs B-pillar. re-organise crash management components. reinstall all parts removed.	<i>Result</i> <i>To review with Adrian.</i> \$ 13,300.00 ✓	6000 ✓
16	To respray front bumper, rhs front fender, rhs front door, rhs wing mirror cover, door handle, rhs rear door, rhs sill panel, rhs B-pillar, rhs rear fender, rhs rear fender outer wheel housing with connecting plate, rear bumper, door entrances, roof channel, drain channel and end panelling.	<i>8/5 review</i> \$ 10,300.00 ✓	4650 ✓
17	To renew rhs front rim, rhs rear rim and rhs rear tyre. To carry out wheel alignment.	S/N \$ 320.00 ✓	✓
18	To carry out diagnostic check.	S/N \$ 384.00 ✓	✓
SUB TOTAL LABOUR CHARGES		: \$ 38,364.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFA 8798 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	SIDE PANEL FRAME - RH <i>bt ✓</i>	\$ 2,856.00	<i>2284.80</i>
2	FRONT BUMPER <i>X</i>	\$ 2,015.00	
3	FRONT BUMPER FIXING PARTS <i>X</i>	\$ 66.00	
4	FRONT BUMPER SECURING STRIP <i>X</i>	\$ 203.00	
5	FRONT BUMPER SPOILER - LH <i>X</i>	\$ 227.00	
6	FRONT BUMPER GUIDE SECTION - RH <i>X</i>	\$ 41.00	
7	WHEEL HOUSING - RH OUTER <i>X</i>	\$ 574.00	
8	REAR WINDOW <i>? photo ✓ nec</i>	\$ 1,049.00	<i>839.20</i>
9	PRIMER <i>na / nn X</i>	\$ 19.00	
10	SIDE WINDOW - RH <i>na /</i>	\$ 561.00	<i>448.40</i>
11	FRONT DOOR - RH <i>bt ✓</i>	\$ 2,152.00	<i>1721.60</i>
12	FRONT DOOR OUTER SEAL <i>Rec /</i>	NEC \$ 185.00	<i>147.60</i>
13	BONDING AGENT <i>na /</i>	NEC \$ 45.00	<i>35.92</i>
14	CLEANING SOLUTION <i>na /</i>	NEC \$ 65.00	<i>51.68</i>
15	SEALING STRIP <i>? X</i>	\$ 15.00	
16	FRONT DOOR CATCH <i>X</i>	\$ 109.00	
17	DOOR HINGE - RH UPPER <i>? X</i>	\$ 41.00	
18	HINGE HALVES - RH UPPER / LOWER <i>? X</i>	2 \$ 84.00	
19	HINGE HALVES - RH LOWER <i>? X</i>	\$ 42.00	
20	FRONT DOOR INNER SEAL <i>? X</i>	\$ 201.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,550.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFA 8798 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR DOOR <i>bt ✓</i>	\$ 2,152.00	<i>1721.60</i>
22	REAR DOOR OUTER SEAL - RH <i>? ✓ nec</i>	\$ 185.00	<i>147.60</i>
23	BONDING AGENT <i>nec ✓</i>	NEC \$ 45.00	<i>35.92</i>
24	CLEANING SOLUTION <i>nec ✓</i>	NEC \$ 65.00	<i>51.68</i>
25	REAR DOOR CATCH <i>X</i>	\$ 96.00	
26	REAR DOOR SEAL - INNER <i>? X</i>	\$ 185.00	
27	REAR DOOR ATTACHMENT PARTS <i>? X</i>	\$ 488.00	
28	TYRE PRESSURE DATA PLATE <i>nec X</i>	\$ 35.00	
29	DOOR HANDLE TRIM PLATE <i>? X SVC</i>	\$ 80.00	
30	LOCK CYLINDER <i>? X</i>	\$ 492.00	
31	DOOR HANDLE SENSOR - RH <i>? X</i>	\$ 208.00	
32	EXTERIOR DOOR HANDLE - RH <i>Repair</i>	\$ 35.00	
33	FRONT PERIPHERAL LIGHT - RH <i>X</i>	\$ 66.00	
34	MOUNTING BAR <i>? X</i>	\$ 149.00	
35	EXTERIOR MIRROR MOUNTING - RH <i>MTBIS -</i>	\$ 824.00	<i>658.80</i>
36	MIRROR CAP - RH <i>mis ✓</i>	\$ 220.00	<i>175.60</i>
37	MIRROR GLASS - RH <i>? X</i>	\$ 1,553.00	
38	WINDOW REGULATOR - RH <i>? X</i>	\$ 250.00	
39	WINDOW REGULATOR MOTOR - RH <i>? X SVC</i>	\$ 278.00	
40	DOOR CONTROL UNIT <i>? X</i>	\$ 685.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,091.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFA 8798 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	DOOR LOCK ? X	\$	487.00
42	B PILLAR TRIM - RH ? X SVC	\$	212.00
43	CORNER TRIM - RH ? X	\$	41.00
44	WINDOW GUIDE - RH X	\$	412.00
45	CLIP <i>re</i> / <i>nn</i> X	16 \$	12.00
46	WINDOW SLOT SEAL - RH <i>de</i>	\$	280.00 224
47	WINDOW GUIDE TRIM STRIP - RH ? <i>nn</i> X	\$	235.00
48	SILL TRIM STRIP - RH ? ✓ nec	\$	109.00 87.20
49	DATA TAG ? ? ✓ nec	\$	423.00 338
50	FRONT FENDER - RH <i>repair</i>	\$	700.00
51	FRONT FENDER ATTACHMENT PARTS X	\$	183.00
52	FRONT FENDER BRACKET X SVC	\$	29.00
53	FRONT FENDER BRACKET X	\$	31.00
54	FRONT FENDER CLOSING ELEMENT - RH X	\$	30.00
55	FENDER LEDGE COVER X	\$	28.00
56	FENDER LEDGE TOP COVER - RH X	\$	21.00
57	FRONT WHEEL HOUSING LINER - RH X	\$	220.00
58	WHEEL HOUSING LINER ATTACHMENT PARTS X	\$	82.00
59	REAR WHEEL HOUSING LINER - RH X	\$	223.00
60	STONE CHIP GUARD X	\$	46.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 3,804.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFA 8798 C

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	THREE POINT AUTOMATIC SEATBELT - LH / RH X	2	\$ 2,010.00	
62	SEAT BELT HEIGHT ADJUSTER X	2	\$ 322.00	
63	AIRBAG CONTROL UNIT X SVC	\$	1,927.00	
64	PRESSURE SENSOR ? X	\$	245.00	
65	AIRBAG CRASH SENSOR - REAR ? X	\$	412.00	
66	CENTRAL PROTECTION ? X	\$	485.00	
67	SUPPORT FRAME ? bt ✓	\$	2,975.00	2380
68	WISHBONE - LOWER ? bt ✓	\$	785.00	628
69	WISHBONE - RH UPPER ? bt ✓	\$	507.00	405.20
70	WISHBONE - RH FRONT ? bt ✓	\$	112.00	89.60
71	WISHBONE ? bt ✓	\$	407.00	325.60
72	REAR TRACK ROD - RH ? bt ✓	\$	155.00	124
73	WHEEL BEARING HOUSING - RH ? bt ✓	\$	903.00	745.60
74	WHEEL BEARING HOUSING - RH ? bt ✓	\$	404.00	322.80
75	STONE CHIP GUARD ? nn X	\$	40.00	
76	GAS SHOCK ABSORBER ? bt ✓	\$	276.00	220.40
77	ALUMINIUM RIM - RH FRONT / REAR ? bt ✓		TBC	760
78	REAR TYRE - RH punctured —		TBC	280
79	REAR WINDSCREEN SEALANT ? —	S/N \$	200.00	200
80	1/4 GLASS SEALANT ? —	S/N \$	100.00	100
SUB TOTAL SPARE PARTS CHARGES		:	\$ 12,265.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFA 8798 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	ACRYLIC SEALANT <i>neu</i>	S/N \$ 360.00	180
82	CAVITY WAX <i>neu</i>	S/N \$ 280.00	140
83	STONE CHIP <i>neu</i>	S/N \$ 360.00	180
84	METAL FILLER POWDER <i>neu</i>	S/N \$ 280.00	280
85	SUNDRIES <i>? nec</i>	\$ 1,000.00	129.92
TOTAL SPARE PARTS CHARGES		: \$ 36,990.00	
TOTAL LABOUR CHARGES		: \$ 38,364.00	
GRAND TOTAL		: \$ 75,354.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

79,594

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

[Signature]
12/12/19
: Rasul - Hp 90010068
: 10/12/19 @ 1445
: 20 days
: EXCESS: TBA
: REVERT
: Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant