

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SGK5473U

Model: Mitsubishi Grandis

QTY	Description	Repairer's Estimate	
Spare Parts - List Items			
1	Rear Reverse Camera X <i>NN</i>	\$	180.00
1	Rear R/H Head light X <i>NN</i>	\$	880.00
1	Rear Bumper / <i>CUT</i>	\$	1,500.00
1	Rear Bumper Side Retainers / <i>OR</i>	\$	170.00
1	Bumper Sensor X	\$	120.00
1	Rear Bumper Reflectors / <i>OR</i>	\$	380.00
1	Rear Bumper Top Step Garnish X	\$	150.00
1	Rear End Panel X	\$	480.00
1	Rear End Panel Inner Garnish X	\$	120.00
1	Rear Boot Garnish X	\$	100.00
1	Hydraulic Hinge X	\$	200.00
2	Rubber Moulding X	\$	40.00

\$ 4,320.00

c/f: \$ 4,320.00

Special Nett Items

AMT S\$

1	Back bumper clip / M	\$	150.00	30
1	Rear Reverse Sensor (1 set) X	\$	620.00	
		\$	<u>770.00</u>	

S/N. Labour Charges

Remove and refit rear tailgate \$ 300.00 X

Remove and refit rear bumper \$ 300.00 200

Remove, refit and replaced damage lamps and check up rear electrical wiring \$ 150.00 30

Remove and refit inner garnishes trim to assist repair \$ 200.00 X

Remove and refit rear reverse sensor \$ 240.00 20

To apply undercoating on replaced panel \$ 120.00 30

To Respray Painting. \$ 1,000.00 400

\$ 2,310.00

GRAND TOTAL

\$ 7,400.00

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 832 8813
(Email) _____
(Signature) 
(Date/Time) 11/12/19, 4:40pm

2 days
w/ LKK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: