

ASS. REC. BY:

REF: CS/CTI 140485 / KVF302

Special Instruction:

SURVIVOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Tan Kah Leng

of

CTI

Date/Time:

11.12.19 12.43 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 7558 U

Insured:

G B J 716 S

at Workshop m/s

Esteem Performance

Tel:

65662112 / 65532112

of

385 Sin Ming Drive

Policy No:

DMCVS N18405718000

Claim No:

SNM191205888102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

11.12.19 1.32p.m

Person Contacted:

Jenny

H.O.P. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 7558 U - X
	G B J 716 S - X
6/1/2020	@ 312pm Carmen said claim withdrawn
7/1/2020	Submit preli report

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV

To Inspect Vehicle No: _____

at Workshop m/s _____ *Esturon*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *88dk*

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLP 7558 U* Regn: *10, 17*Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: *Toy Prius* c.c. *1798*Colour: *M. Silver* A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: *208011* T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: *JTDKB31F4 803571068*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim orTyre Size: F: *195/65R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ☒

Front _____ Rear _____

R/Bal. *9* mm R/Bal. *9* mmL/Bal. *9* mm L/Bal. *9* mmD.O.A. *10/12/19* D.O.I. *11/12/19*

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or*CLS Rear, & Rear, O/S Frt & N/S Frt*The U/C / Chassis frame / ☒ Body Structure affected due to collision.

RECEIVED 07 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

D. *7/1 - typist*

Report Format:

Lump Sum / I.B.I: IS

Days Of Repair: *14*

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation: _____ \$ - RS. SI

Fees:

Others:

TOTAL

*270**270*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2019		11 Dec 2019 12:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	SLS7558U	Date of Loss:	10/12/2019 14:00 - :59						
Vehicle Reg. No.:	TP / SNM19D205888C02	Policy/Cover Note No.:	DMCVSN18405718000						
Claim Type:	GBJ7165	Policy No. (Claimant):	A29114756MKF						
Vehicle Reg. No. (Insured):		Excess:	S\$350.00						
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel: 63896193								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2019]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLS755BU
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR50B9567
Chassis No.:	JTDKB3FU803571068
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	03 Oct 2017
First Registration Date:	03 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2027
PARF Rebate Amount:	\$4,059.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$41,923.00
Total Rebate Amount:	\$45,982.00

The information contained herein is correct as at 12 Dec 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal COE Toyota Wish 2.0A,



2.88% F/A, \$0 Admin, Monthly
From \$488, 2 Years Warranty
Engine And Gearbox...
GV Credit [Booked](#)



Browse by Category ▼








Sort by Date Posted ▼

20 results/page ▼

6 vehicles

Toyota Prius

Advanced Search ✕

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Prius	Any	Any	2017	Any	Any	Any	Available
	Toyota Prius C Hybrid 1.5A Fuel Type: Petrol-Electric The Toyota Prius C Is An Adequate Car. This Hybrid's Biggest Selling Points Are Its Outstanding Gas Mileage, Excellent Predicted Reliability Rating, And Large Cargo Area. 1 Owner, Local Agent Unit With Valid Warranty! High Trade-in, Minimum Down Payment And Attractive Fi... Pang's Motor Trading Pte Ltd Posted: 11-Dec-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$65,600	\$8,700 /yr	14-Mar-2017	1,497 cc	33,300 km	Hatchback	Available
	Toyota Prius C Hybrid 1.5A Fuel Type: Petrol-Electric As Good As New! Always Under Shade, Super Well Kept By Former Owner, 100% No Touch Up Done By Us! 100% Accident Free! Warranty And Fully By Agent Borneo Motors From Day 1! Underutilized Mileage Done At 29k Km! Flawless Inside Out! Nothing More To... Posted: 06-Dec-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$69,000	\$8,430 /yr	02-Nov-2017	1,497 cc	29,000 km	Hatchback	Available
	Toyota Prius C Hybrid 1.5A Fuel Type: Petrol-Electric Full Loan Available At \$1k Plus, We Can Help To Convert To Z10 Usage If Needed, In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Avail... 88 Motor Trading Posted: 05-Dec-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$66,800	\$8,520 /yr	28-Jun-2017	1,497 cc	-	Hatchback	Available
	Toyota Prius Alpha Hybrid 1.8A S Fuel Type: Petrol-Electric Full Loan Available, Secured And Well Maintained By Fussy Owner, Immaculate Condition Inside And Outside, Certified With Assurance And Quality From STA Evaluation, Give Yourself A Peace Of Mind! Buy It From Us! A Company With Professional Sales Serviced Assured.... 88 Motor Trading Posted: 29-Nov-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$95,800	\$11,670 /yr	08-Dec-2017	1,797 cc	-	MPV	Available
	BC Racing V1 Coilover BC (V1) Coilovers for Toyota. Part Number (V1) C-24-VM. More info about this product							
	Toyota Prius C Hybrid 1.5A Fuel Type: Petrol-Electric In House Finance Available! Most Ideal For Private And PHV Usage, Very Reliable And Fuel Efficient! New Arrival, 1 Owner Unit, Fully Maintained By Borneo Motors Since Day One! Comes With Agent 5 Years/ Unlimited Mileage Warranty! Full Service Records! 10 Years H... Speedo Motoring Posted: 14-Nov-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$66,800	\$8,610 /yr	30-May-2017	1,497 cc	40,000 km	Hatchback	Available
	Toyota Prius Hybrid 1.8A S Fuel Type: Petrol-Electric Cheapest, Lowest Depreciation, Low Mileage, Loan Package, Well Maintained By Previous Owner! High Trade In Are Welcome. Tip Top Condition! 100% Accident Free. View To Believe It, Call Now Before Sold! Posted: 08-Oct-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota	\$84,800	\$11,300 /yr	24-Mar-2017	1,797 cc	25,000 km	Hatchback	Available

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 15:20
Date Of Accident	10/12/2019 14:10
Exact Location Of Accident	JUNC OF PENJURU ROAD / PENJURU LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS7558U
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31388644

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	WOON JAN SIANG
NRIC No	S7864478H
Date Of Birth	06/04/1978
Occupation	OUTDOOR
Date Of Driving Pass	29/01/2002
Driving Experience	17 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81982972
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 466D SEMBAWANG DRIVE #08-347
Postcode	754466
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOT APPLICABLE
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMPAWANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 4 SEMPAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5549999 - FAX NO: 68522499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20191210/2186

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ716S
Vehicle Make/Model/Colour	TOYOTA / HIACE
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ABDUL RAHMAN BIN RAHIM
NRIC/Passport Number	S8920827J
Contact Number	98597360

Address
Postcode
Insurance Company Name
Nature Of Damage FRONT PORTION
No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties PROPERTY
Vehicle Category GOVERNMENT
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage COLLIDED INTO LAMP POST
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MALE PASSENGER
Approximate Age
Injuries Sustain NOSE PAIN
Injured person in which vehicle? SLS7558U
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10/12/2019
3.35 p.m.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT NO. T/ 20191210/2186

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

©JARMAC SketchPlanForm_V3

Police Report



**SINGAPORE
POLICE FORCE**



T/20191210/2186

1 of 3

Report No: T/20191210/2186

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5548999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/12/2019 21:41	Vide Report No.: D/20191210/0061	Station Diary No.: 110
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: WOON JAN SIANG		Address: APT BLK 456D SEMBAWANG DRIVE #08-347 SINGAPORE 754466	
ID Type / ID No.: NRIC NO / S7864478H		Contact No.: Home/Office: Mobile: 81984272	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 41	Date of Birth: 06/04/1978	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 2B.3 Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 10/12/2019 14:10	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 PENJURU ROAD PENJURU LANE			
Weather: Raining	Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBJ716S	Van	TOYOTA		Silver		0
SLS7558U	Car	TOYOTA	PRIUS	Silver	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999



T/20191210/2186

Report No. T/20191210/2186

CONTINUATION OF REPORT

Driver		ID No.	S8920827J
Name	ABDUL RAHMAN BIN RAHIM	Contact No.	98597360
Related Vehicle	GBJ716S (Van)	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Hospital/Clinic	NIL	Date Treatment	NIL
		Date Discharge	NIL
		No. of Days granted Medical Leave	NIL
		Degree of Injury	NIL
Driver		ID No.	S7864478H
Name	WOON JAN SIANG	Contact No.	81984272
Related Vehicle	SLS7558U (Car)	Class of Driving Licence & Expiry Date	Class: 2B.3 Date of Expiry: NIL
Hospital/Clinic	NIL	Date Treatment	NIL
		Date Discharge	NIL
		No. of Days granted Medical Leave	NIL
		Degree of Injury	NIL







Brief Details.

On 10/12/2019 at about 1410 hrs, I was driving my car along Penjuru Lane. As I was crossing the uncontrolled junction of Penjuru Lane and Penjuru Road, I spotted the van (GBJ 716S) already at my driver side, front door as such I speed up my car but the van still hit onto my car, driver side rear passenger door and rear tyre area.

Due to the impact my car spun 180 degree, went up the kerb and came to a stop after hitting a lamp post. The van was coming from Penjuru Road going towards Teban Garden. After the accident, I call my company followed by the insurance company then the Police as I was unsure of the procedure on traffic accident.

I had ask my passenger and he informed that he felt pain on his nose however he had left on another Grab car as he was in a hurry. He was informed to keep his receipt and contact Grab for any claim. The Ambulance arrived and they had examine me. Traffic Police attended to the accident reference D/20191210/0061 and my in-car camera micro SD card was taken by Traffic Police Officer.

Police Report

 SINGAPORE POLICE FORCE		 T/20191210/2186
Police Station Of Origin: Sembawang N.P.C 4 Sembawang Crescent SINGAPORE 757633 Tel No: 1800-5549999		3 of 3 Report No: T/20191210/2186
CONTINUATION OF REPORT		
Sketch Plan Informant is not able to provide sketch plan		
<p>IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.</p>		
Signature Of Officer Recording The Report: L / Staff Sgt LIM FEI YANG		Signature Of Informant: 
Signature Of Interpreter: Not applicable		Date/Time: 10/12/2019 21:41
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414		Classification Of Case:
Authentication Stamp NP158	 Signature  Singapore Police Force	



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLS 7558 U

Parts	(a) Cost / List Price Items	\$	34,486.80	33442.10
	Plus/Less 25%	\$	8,621.70	8360.525
	Total of Cost / List	\$	25,865.10	25081.575
	(b) Nett Price Items			
	Less			
	Total of Nett Item			
	(c) Special Nett Items	\$	865.00	
	Total Parts Cost	\$	26,730.10	
	Labour	\$	8,360.00	
	Total	\$	35,090.10	34306.525

Not Authorized

U/Lays 8?

Resurvey After Paint

LKIC Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To allow damaged panels during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "limited liability" basis
- No illegal modifications are allowed
- Supplementary items must be confirmed and accepted to have approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKIC

Survey conducted on

11/12/19

at

3.45pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 14 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 11/12/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLS 7558 U**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU803571068**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>R</i>	1	\$450.80		X
2	Front bumper clip <i>nn</i>	10	\$40.00		X
3	Front bumper side retainer RH <i>nn</i>	1	\$107.20		X
4	Front bumper emblem <i>nn</i>	1	\$87.10		X
5	Front bumper tow cover RH <i>nn</i>	1	\$25.70		X
6	Rear windscreen moulding <i>nn</i>	1	\$97.70		✓
7	Rear windscreen sealant <i>nn</i>	1	\$50.00	S.N	<i>For nn</i>
8	Rear windscreen top garnish <i>nn</i>	1	\$655.40		✓
9	Rear windscreen top quarter garnish LH	1	\$189.60		?
10	Rear windscreen top quarter garnish RH	1	\$189.60		?
11	PHV Sticker <i>nn</i>	1	\$20.00	S.N	✓
12	Rear number plate <i>nn</i>	1	\$45.00	S.N	✓
13	Reverse sensor <i>nn</i>	1	\$200.00	S.N	✓
14	Rear bumper <i>nn</i>	1	\$497.50		✓
15	Rear bumper clip <i>nn</i>	10	\$40.00		✓
16	Rear bumper side retainer LH <i>nn</i>	1	\$112.70		X
17	Rear bumper side retainer RH <i>nn</i>	1	\$112.70		✓
18	Rear bumper reinforcement <i>nn</i>	1	\$398.90		✓
19	Rear bumper lower garnish centre <i>nn</i>	1	\$582.60		✓
20	Rear bumper lower garnish LH <i>nn</i>	1	\$149.70		X
21	Rear bumper lower garnish RH <i>nn</i>	1	\$149.70		✓
22	Rear bumper tow cover <i>nn</i>	1	\$31.70		X
23	Rear bumper under cover <i>nn</i>	1	\$355.20		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLS 7558 U**

Make & Model : **TOYOTA PRIUS**

Chassis No. : **JTDKB3FU803571068**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Rear bumper under cover LH	1	\$187.60		?
25	Rear bumper under cover RH	1	\$187.60		?
26	Rear bumper under cover clip	4	\$14.00		?
27	Tail door <i>By</i>	1	\$1,122.50		—
28	Tail door lock <i>Im</i>	1	\$487.70		—
29	Tail door emblem <i>me</i>	1	\$61.70		—
30	Wording "PRIUS" <i>me</i>	1	\$51.90		—
31	Wording "HYBRID" <i>me</i>	1	\$55.47		—
32	Tail door hinge LH <i>R</i>	1	\$87.60		X
33	Tail door hinge RH <i>R</i>	1	\$87.60		X
34	Tail door plate garnish <i>CM</i>	1	\$782.50		—
35	Tail door inner trim <i>DIY</i>	1	\$278.90		—
36	Tail door inner trim clip <i>me</i>	10	\$28.00		—
37	Taildoor spoiler	1	\$1,567.83		?
38	Tail end panel <i>By</i>	1	\$596.60		✓
39	Tail end panel garnish	1	\$151.60		?
40	Tail end panel garnish clip	10	\$35.00		?
41	Boot weatherstrip	1	\$353.10		?
42	Spare tyre well panel	1	\$793.15		?
43	Spare tyre board	1	\$566.79		?
44	Spare tyre compartment sponge LH	1	\$297.67		?
45	Spare tyre compartment sponge RH	1	\$297.67		?
46	Tail lamp LH - UPPER	1	\$498.75		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

25/11/23

Spare Parts

Vehicle No. : **SLS 7558 U**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU803571068**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Tail lamp RH - UPPER <i>CRM</i>	1	\$498.75		✓
48	Tail lamp LH - LOWER	1	\$511.60		?
49	Tail lamp RH - LOWER	1	\$511.60		?
50	Taildoor glass <i>Shattered</i>	1	\$598.70		✓
51	Taildoor glass sealant <i>new</i>	1	\$50.00	S.N	<i>4050</i>
52	Third brake light <i>CRM</i>	1	\$359.64		✓
53	RH rear fender <i>R2</i>	1	\$883.60		✓
54	RH rear fender undershield <i>CRM</i>	1	\$92.30		✓
55	RH rear fender undershield clip <i>new</i>	10	\$30.00		✓
56	RH rear inner trim upper	1	\$386.75		?
57	RH rear lower arm <i>R2</i>	1	\$398.65		✓
58	RH rear knuckle arm	1	\$895.60		?
59	RH rear knuckle bearing	1	\$421.90		✓
60	RH rear wheel hub <i>But new</i>	1			
61	RH rear wheel hub lock nut	1	\$17.30		?
62	RH rear shock absorber	1	\$359.40		?
63	RH rear shock absorber top mounting	1	\$165.70		?
64	RH rear shock absorber stopper	1	\$85.70		?
65	RH rear hub cap <i>new</i>	1	\$195.62		✓
66	RH rear rim <i>new</i>	1	\$1,555.10		✓
67	RH rear tyre	1	\$250.00	S.N	?
68	RH side skirt <i>new</i>	1	\$721.50		X
69	RH side skirt clip <i>new</i>	10	\$45.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2724 41

5300

Spare Parts

Vehicle No. : **SLS 7558 U**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU803571068**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Roof lining <i>Tn</i>	1	\$2,331.40		—
71	Roof lining clip <i>Mn</i>	10	\$47.00		—
72	Roof Air bag RH <i>Rum</i>	1	\$1,774.56		—
73	Seat belt LHR <i>Tn</i>	1	\$828.60		—
74	Sear belt RHR <i>Tn</i>	1	\$828.60		—
75	LH front fender <i>r</i>	1	\$868.70		x
76	LH front fender undershield <i>Sn</i>	1	\$195.60		x
77	LH front fender undershield clip <i>nn</i>	10	\$25.00		x
78	LHF fender wording "HYBRID" <i>Abc</i>	1	\$44.17		✓
79	LH side skirt	1	\$721.50		?
80	LH side skirt clip	10	\$45.00		?
81	RH front lower arm	1	\$492.65		?
82	RH front shock absorber	1	\$462.70		?
83	RH front shock absorber top mouting	1	\$195.07		?
84	RH front shock absorber stopper	1	\$37.02		?
85	RH front knuckle arm	1	\$476.75		?
86	RH front knuckle bearing	1	\$573.20		?
87	RH front wheel hub	1			
88	RH front wheel hub lock nut	1	\$28.02		?
89	RH front tie rod end	1	\$116.40		?
90	RH front hub cab	1	\$195.62		?
91	RH front rim <i>nd</i>	1	\$1,555.10		✓
92	RH front tyre	1	\$250.00	S.N	?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

11241 66

\$250



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569636.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLS 7558 U** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,RHF FENDER,LH SIDE SKIRT,RH SIDE SKIRT,RHR DOOR, RHR FENDER,REAR BUMPER,TAILDOOR,END PANEL, SPARE TYRE WELL PANEL,RH"C" PILLAR)	\$2,800.00	1800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,RHF FENDER,LH SIDE SKIRT,RH SIDE SKIRT,RHR DOOR, RHR FENDER,REAR BUMPER,TAILDOOR,END PANEL, SPARE TYRE WELL PANEL,RH"C" PILLAR)	\$2,600.00	1800
3	To check wiring	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$500.00	X
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
8	To remove & refit rear windscreen.	\$120.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : SLS 7558 U Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
9	To refit airbag system.	\$250.00	200
10	To reset airbag control unit.	\$250.00	200
11	To tuff coat.	\$300.00	60
12	To remove & refit inner seat & upholstery to assist work load.	\$250.00	100
13	To remove & refit roof lining, inner trim to assist work load.	\$400.00	
14	To arrange express service to do PHV Sticker	\$120.00	?
15	To transfer boot mechanism to new boot	\$120.00	60
16	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30
17	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2019		11 Dec 2019 12:43 Edit Adj Rpt	S\$18,943.99 Edit Estimates	S\$18,943.99 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SL57558U	Date of Loss:	10/12/2019 14:00 - :59 [26 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205888C02	Policy/Cover Note No.:	DMCVSN18405718000						
Vehicle Reg. No. (Insured):	GBJ7165	Policy No. (Claimant):	A29114756MKF						
		Excess:	S\$350.00						
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS7558U (SNM19D205888C02)**
[GBJ716S]


TP

GRAB RENTALS PTE LTD





















Dec 10 2019 2:00PM

[-]

Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/20 17:19	General View	 Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 08:43	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 08:40	Police Report	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/19 08:40	Police Report	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/19 08:40	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/19 08:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/19 08:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/19 08:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	11/12/19 08:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	11/12/19 08:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	11/12/19 08:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 08:39	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/19 08:39	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021815/KVF3E2

Date: 23/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18405718000

Claimant Vehicle
No: SLS7558UInsured Vehicle
No: GBJ716S

Date of Loss: 10/12/2019

Nature of Claim: TP

Claim
No: SNM19D205888C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS7558U

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS089567

Reg. Date: 03/10/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU803571068

Colour: Metallic Silver

Odometer: 208011 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,946.57	14,443.99	11,502.58	44.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,360.00	4,500.00	3,860.00	46.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,306.57	18,943.99	15,362.58	44.78
+ GST 7.00/7.00% (S\$)	2,401.46	1,326.08	1,075.38	44.78
Nett Amount (S\$)	36,708.03	20,270.07	16,437.96	44.78

INSPECTION

Date of Assignment: 11/12/2019

Date Inspected: 11/12/2019 Inspected At:

Esteem Performance Pte Ltd - Sin Ming
(HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$9,325.65 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS7558U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	450.80 FL	*- FL
2	10	*FRONT BUMPER CLIP	Not Necessary	40.00 FL	*- FL
3	1	*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*- FL
4	1	*FRONT BUMPER EMBLEM	Not Necessary	87.10 FL	*- FL
5	1	*FRONT BUMPER TOW COVER RH	Serviceable	25.70 FL	*- FL
6	1	*REAR WINDSCREEN MOULDING	Necessary	97.70 FL	*97.70 FL
7	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
8	1	*REAR WINDSCREEN TOP GARNISH	Cracked	655.40 FL	*655.40 FL
9	1	*REAR WINDSCREEN TOP QUARTER GARNISH LH	* Check	189.60 FL	*- FL
10	1	*REAR WINDSCREEN TOP QUARTER GARNISH RH	* Check	189.60 FL	*- FL
11	1	*PHV STICKER	Necessary	20.00 FS	*20.00 FS
12	1	*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
13	1	*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
14	1	*REAR BUMPER	Buckled	497.50 FL	*497.50 FL
15	10	*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
16	1	*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
17	1	*REAR BUMPER SIDE RETAINER RH	Distorted	112.70 FL	*112.70 FL
18	1	*REAR BUMPER REINFORCEMENT	Bent	398.90 FL	*398.90 FL
19	1	*REAR BUMPER LOWER GARNISH CENTRE	Bent	582.60 FL	*582.60 FL
20	1	*REAR BUMPER LOWER GARNISH LH	Serviceable	149.70 FL	*- FL
21	1	*REAR BUMPER LOWER GARNISH RH	Mtg Cracked	149.70 FL	*149.70 FL
22	1	*REAR BUMPER TOW COVER	Serviceable	31.70 FL	*- FL
23	1	*REAR BUMPER UNDER COVER	Distorted	355.20 FL	*355.20 FL
24	1	*REAR BUMPER UNDER COVER LH	* Check	187.60 FL	*- FL
25	1	*REAR BUMPER UNDER COVER RH	* Check	187.60 FL	*- FL
26	4	*REAR BUMPER UNDER COVER CLIP	* Check	14.00 FL	*- FL
27	1	*TAIL DOOR	Bent	1,122.50 FL	*1,122.50 FL
28	1	*TAIL DOOR LOCK	Jammed	487.70 FL	*487.70 FL
29	1	*TAIL DOOR EMBLEM	Necessary	61.70 FL	*61.70 FL
30	1	*WORDING PRIUS	Necessary	51.90 FL	*51.90 FL
31	1	*WORDING HYBRID	Necessary	55.47 FL	*55.47 FL
32	1	*TAIL DOOR HINGE LH	Repair	87.60 FL	*- FL
33	1	*TAIL DOOR HINGE RH	Repair	87.60 FL	*- FL
34	1	*TAIL DOOR PLATE GARNISH	Cracked	782.50 FL	*782.50 FL
35	1	*TAIL DOOR INNER TRIM	Distorted	278.90 FL	*278.90 FL
36	10	*TAIL DOOR INNER TRIM CLIP	Necessary	28.00 FL	*28.00 FL
37	1	*TAILDOOR SPOILER	* Check	1,567.83 FL	*- FL
38	1	*TAIL END PANEL	Bent	596.60 FL	*596.60 FL
39	1	*TAIL END PANEL GARNISH	* Check	151.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	10	*TAIL END PANEL GARNISH CLIP	* Check	35.00 FL	*- FL
41	1	*BOOT WEATHERSTRIP	* Check	353.10 FL	*- FL
42	1	*SPARE TYRE WELL PANEL	* Check	793.15 FL	*- FL
43	1	*SPARE TYRE BOARD	* Check	566.79 FL	*- FL
44	1	*SPARE TYRE COMPARTMENT SPONGE LH	* Check	297.67 FL	*- FL
45	1	*SPARE TYRE COMPARTMENT SPONGE RH	* Check	297.67 FL	*- FL
46	1	*TAIL LAMP LH - UPPER	* Check	498.75 FL	*- FL
47	1	*TAIL LAMP RH - UPPER	Cracked	498.75 FL	*498.75 FL
48	1	*TAIL LAMP LH - LOWER	* Check	511.60 FL	*- FL
49	1	*TAIL LAMP RH - LOWER	* Check	511.60 FL	*- FL
50	1	*TAILDOOR GLASS	Shattered	598.70 FL	*598.70 FL
51	1	*TAILDOOR GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
52	1	*THIRD BRAKE LIGHT	Cracked	359.64 FL	*359.64 FL
53	1	*RH REAR FENDER	Bent	883.60 FL	*883.60 FL
54	1	*RH REAR FENDER UNDERSHIELD	Cracked	92.30 FL	*92.30 FL
55	10	*RH REAR FENDER UNDERSHIELD CLIP	Necessary	30.00 FL	*30.00 FL
56	1	*RH REAR INNER TRIM UPPER	* Check	386.75 FL	*- FL
57	1	*RH REAR LOWER ARM	Bent	398.65 FL	*398.65 FL
58	1	*RH REAR KNUCKLE ARM	* Check	895.60 FL	*- FL
59	1	*RH REAR KNUCKLE BEARING)	Bent / Necessary	421.90 FL	*421.90 FL
60	1	*RH REAR WHEEL HUB)		0.00 FL	*- FL
61	1	*RH REAR WHEEL HUB LOCK NUT	* Check	17.30 FL	*- FL
62	1	*RH REAR SHOCK ABSORBER	* Check	359.40 FL	*- FL
63	1	*RH REAR SHOCK ABSORBER TOP MOUNTING	* Check	165.70 FL	*- FL
64	1	*RH REAR SHOCK ABSORBER STOPPER	* Check	85.70 FL	*- FL
65	1	*RH REAR HUB CAB	Missing	195.62 FL	*195.62 FL
66	1	*RH REAR RIM	Dented	1,555.10 FL	*1,555.10 FL
67	1	*RH REAR TYRE	* Check	250.00 FS	*- FS
68	1	*RH SIDE SKIRT	Serviceable	721.50 FL	*- FL
69	10	*RH SIDE SKIRT CLIP	Not Necessary	45.00 FL	*- FL
70	1	*ROOF LINING	Torn	2,331.40 FL	*2,331.40 FL
71	10	*ROOF LINING CLIP	Necessary	47.00 FL	*47.00 FL
72	1	*ROOF AIR BAG RH	Burst	1,774.56 FL	*1,774.56 FL
73	1	*SEAT BELT LHR	Jammed	828.60 FL	*828.60 FL
74	1	*SEAT BELT RHR	Jammed	828.60 FL	*828.60 FL
75	1	*LH FRONT FENDER	Repair	868.70 FL	*- FL
76	1	*LH FRONT FENDER UNDERSHIELD	Serviceable	195.60 FL	*- FL
77	10	*LH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	25.00 FL	*- FL
78	1	*LHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
79	1	*LH SIDE SKIRT	* Check	721.50 FL	*- FL
80	10	*LH SIDE SKIRT CLIP	* Check	45.00 FL	*- FL
81	1	*RH FRONT LOWER ARM	* Check	492.65 FL	*- FL
82	1	*RH FRONT SHOCK ABSORBER	* Check	462.70 FL	*- FL
83	1	*RH FRONT SHOCK ABSORBER TOP MOUNTING	* Check	195.07 FL	*- FL
84	1	*RH FRONT SHOCK ABSORBER STOPPER	* Check	37.02 FL	*- FL
85	1	*RH FRONT KNUCKLE ARM	* Check	476.75 FL	*- FL
86	1	*RH FRONT KNUCKLE BEARING)	* Check	573.20 FL	*- FL
87	1	*RH FRONT WHEEL HUB)	* Check	0.00 FL	*- FL
88	1	*RH FRONT WHEEL HUB LOCK NUT	* Check	28.02 FL	*- FL
89	1	*RH FRONT TIE ROD END	* Check	116.40 FL	*- FL
90	1	*RH FRONT HUB CAB	* Check	195.62 FL	*- FL
91	1	*RH FRONT RIM	Dented	1,555.10 FL	*1,555.10 FL
92	1	*RH FRONT TYRE	* Check	250.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					34,307.10	19,143.66
- List Item Discount on L Items 25.00/25.00% (\$\$)					8,360.53	4,699.67
Total Parts (\$\$)					25,946.57	14,443.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, LHF FENDER, RHF FENDER, LH SIDE SKIRT, RH SIDE SKIRT, RHR DOOR, RHR FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHC PILLAR	New	2,800.00	1,600.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, LHF FENDER, RHF FENDER, LH SIDE SKIRT, RH SIDE SKIRT, RHR DOOR, RHR FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RHC PILLAR	New	2,600.00	1,800.00
3	TO CHECK WIRING	New	50.00	40.00
4	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD	New	150.00	100.00
5	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	500.00	0.00
6	TO DO WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	150.00	60.00
8	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
9	TO REFIT AIRBAG SYSTEM	New	250.00	200.00
10	TO RESET AIRBAG CONTROL UNIT	New	250.00	200.00
11	TO TUFF COAT	New	300.00	60.00
12	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD)	New	250.00	100.00
13	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD)	New	400.00	0.00
14	TO ARRANGE EXPRESS SERVICE TO DO PHV STICKER (* Check)	New	120.00	0.00
15	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
16	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	30.00
17	TOWING	New	60.00	50.00
Gross Labour Cost (\$\$)			8,360.00	4,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >