

Date: 10.12.2019
Vehicle No: SKV9796G
Model: HYUNDAI HD AVANTE 1.6A
Chassis: KMH DU41BR9U653690 - 2009
Reg.Year: 2009

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHC1470J
Date of Accident: 06.12.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH / buc	1		\$1,216.80
2	FRONT DOOR FRAME PROTECTIVE STICKER LH / MCL	1		\$67.20
3	REAR DOOR LH / buc	1		\$1,196.40
4	REAR DOOR FRAME PROTECTIVE STICKER LH / MCL	1		\$67.20
5	RUNNING BOARD PANEL LH x repair			REPAIR
SUB TOTAL				\$2,547.60
LESS 20%				-\$509.52
PARTS TOTAL				\$2,038.08

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & REPLACE, REPAIR, READJUST FRONT DOOR LH, REAR DOOR LH, RUNNING BOARD PANEL LH & ETC 400 \$500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR LH, REAR DOOR LH, INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS 120 } \$220.00

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC. BACK TO PROPER CONDITIONS \$80.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, RUNNING BOARD PANEL & ETC 600 \$800.00

TO TUFF KOTE & UNDERSEAL MATERIALS 3158.08 NN x \$200.00

4 Days.
ump Sam repair. 20% x 2500

LABOUR TOTAL \$1,800.00

ONG

After repair - photos.
Guo Qiang - 82880282
12/12/19.

LKK Auto Consultants hence notify the Repairer if the following: **TOTAL \$3,838.08**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9929

