

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : YUEN PEILING, ADELINE
BLK 275 TAMPINES STREET 22 #05-74
SINGAPORE 520275

ATTN: FIRST CAPITAL

Khanchan.

Your Ref No: TP 1219-5779
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SHA 1666 Y

Estimate No: **EST1505543**
Date: 06 Dec 2019
Policy No: MT/00632313
Veh Reg No: **SLL8136J**
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No: JM6BN22A8H0142370
Engine No: P520429972
Reg. Date: 10/03/2017

Estimate Repair Cost to Vehicle No :SLL8136J

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>Distorted</i>	1,128.000	1 PC	1,128.00	✓
2 REAR BUMPER CLIPS <i>m</i>	4.8000	10 PC	48.00	✓
3 REAR BUMPER SIDE HOLDER - LH <i>Not New</i>	38.0000	1 PCS	38.00	+
4 REAR BUMPER SIDE HOLDER - RH <i>Not New</i>	38.0000	1 PCS	38.00	+
5 REAR BUMPER REINFORCEMENT <i>Best</i>	563.0000	1 PC	563.00	✓
6 REAR BUMPER REFLECTORS - LH <i>Not New</i>	53.0000	1 PC	53.00	+
7 REAR BUMPER REFLECTORS - RH <i>Not New</i>	53.0000	1 PC	53.00	+
8 REAR BUMPER TOW COVER - LH <i>missing</i>	38.0000	1 PC	38.00	✓
9 REAR BUMPER TOW COVER - RH <i>Not New</i>	38.0000	1 PC	38.00	✓
10 REAR PANEL <i>Distorted</i>	530.0000	1 PCS	530.00	✓
11 REAR PANEL TOP GARNISH <i>Not New</i>	89.0000	1 PCS	89.00	+
12 REAR BOOT <i>Distorted</i>	1,005.000	1 PCS	1,005.00	✓
13 REAR BOOT MAZDA LOGO	78.0000	1 PCS	78.00	✓
14 REAR BOOT MAZDA W/3 WORDING <i>Not New</i>	56.0000	1 PCS	56.00	✓
15 REAR BOOT SKYACTIV LOGO	68.0000	1 PCS	68.00	✓
16 REAR BOOT TOP LOCK <i>Not New</i>	186.0000	1 PC	186.00	+
17 REAR BOOT BOTTOM LOCK <i>Not New</i>	41.0000	1 PC	41.00	+
18 REAR BOOT RUBBER <i>Not New</i>	113.0000	1 PC	113.00	✓
19 REAR BOOT REFLECTORS - LH <i>Not New</i>	278.0000	1 PC	278.00	+
20 REAR BOOT REFLECTORS - RH <i>Not New</i>	278.0000	1 PC	278.00	+
21 REAR BOOT INSULATOR CLIPS <i>Not New</i>	4.8000	10 PCS	48.00	+
22 TAILLAMP ASSY - LH <i>Not New</i>	534.0000	1 PCS	534.00	+
23 TAILLAMP ASSY - RH <i>Not New</i>	534.0000	1 PCS	534.00	+
24 FRONT BUMPER <i>Distorted</i>	866.0000	1 PC	866.00	✓
25 FRONT BUMPER CLIPS <i>Not New</i>	4.8000	10 PC	48.00	✓
26 FRONT BUMPER SIDE HOLDER - LH <i>Not New</i>	19.7000	1 PC	19.70	+
27 FRONT BUMPER SIDE HOLDER - RH <i>Not New</i>	19.7000	1 PC	19.70	+
28 FRONT BUMPER FOAM <i>Not New</i>	70.6000	1 PC	70.60	✓
29 FRONT BUMPER REINFORCEMENT <i>Best</i>	502.0000	1 PC	502.00	✓
30 FRONT BUMPER TOWING COVER - RH <i>Not New</i>	18.0000	1 PCS	18.00	+
31 FRONT BUMPER CENTRE LOWER GRILLE, LH - SMALL <i>Not New</i>	36.0000	1 PCS	36.00	+
32 FRONT BUMPER CENTRE LOWER GRILLE, RH - SMALL <i>Not New</i>	36.0000	1 PCS	36.00	+
33 GRILLE TOP RIVET CLIPS <i>Not New</i>	5.9000	7 PCS	41.30	✓
34 GRILLE CHROME MOULDING - LH <i>Not New</i>	191.0000	1 PCS	191.00	✓
35 GRILLE CHROME MOULDING - RH <i>Not New</i>	191.0000	1 PCS	191.00	+
36 GRILLE LOGO <i>missing</i>	61.0000	1 PCS	61.00	✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : YUEN PEILING, ADELINE
BLK 275 TAMPINES STREET 22 #05-74
SINGAPORE 520275

ATTN: FIRST CAPITAL

Your Ref No: TP 1219-5779
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SHA 1666 Y

Estimate No: **EST1505543**
Date: 06 Dec 2019
Policy No: MT/00632313
Veh Reg No: **SLL8136J**
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No: JM6BN22A8H0142370
Engine No: P520429972
Reg. Date: 10/03/2017

Estimate Repair Cost to Vehicle No :SLL8136J

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
37 GRILLE ASSY <i>could</i>	135.0000	1 PCS	135.00	✓
38 GRILLE TOP CLIPS <i>on</i>	4.8000	10 PCS	48.00	✓
39 GRILLE TOP GARNISH <i>Belld</i>	355.0000	1 PCS	355.00	✓
40 GRILLE TOP GARNISH, INNER <i>the in</i>	95.6000	1 PCS	95.60	✓
41 HEADLAMP ASSY - RH <i>the in</i>	1,070.000	1 PCS	1,070.00	✓
42 HEADLAMP ASSY - LH <i>the in</i>	1,070.000	1 PCS	1,070.00	✓
			10,708.90	
		Less 20%	2,141.78	8,567.12
Special Net				
43 REAR BUMPER SENSOR <i>Dmg</i>	220.0000	1 SET	220.00	✓
44 FRONT NUMBER PLATE WITH CASING <i>Best</i>	35.0000	1 PC	35.00	✓
			255.00	255.00
Labour				
45 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,200.000	1 JOB	1,200.00	✓
46 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.000	1 JOB	1,200.00	✓
47 TO CHECK WIRING	50.0000	1 JOB	50.00	✓
48 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	✓
49 TO TUFF-KOTE	120.0000	1 JOB	120.00	✓
50 TO REMOVE, REFIX REAR GARNISH, cushion, carpet & related parts	80.0000	1 JOB	80.00	✓
			2,750.00	2,750.00
Total				SS 11,572.12
Add GST @ 7%				810.05
Total Amount Payable				SS 12,382.17

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND THREE HUNDRED EIGHTY TWO AND CENTS SEVENTEEN ONLY

Supplementary: 14320 Adrian Lim
Total: 7344.52 P/P 10/12/19.
CP/P 10 days, 07 days.
For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : YUEN PEILING, ADELINE
BLK 275 TAMPINES STREET 22 #05-74
SINGAPORE 520275

Estimate No: EST1505543
Date: 11 Dec 2019
Policy No: MT/00632313
Veh Reg No: SLL8136J
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

ATTN: FIRST CAPITAL

Your Ref No: TP 1219-5779
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SHA 1666 Y

Chassis No: JM6BN22A8H0142370
Engine No: P520429972
Reg. Date: 10/03/2017

Estimate Repair Cost to Vehicle No :SLL8136J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
List Price				
1 GRILLE INNER SIDE BRACKET - LH	29.0000	1 PCS	29.00 ✓	
2 GRILLE INNER SIDE BRACKET - RH	29.0000	1 PCS	29.00 ✓	
3 REAR PANEL INNER TOP BRACKET	18.0000	1 PCS	18.00 ✓	
4 GRILLE, SIDE COVER - LH	27.0000	1 PCS	27.00 ✓	
5 FRONT NUMBER PLATE GARNISH	76.0000	1 PC	76.00 ✓	
			179.00	
	Less 20%		35.80	143.20

Total S\$ 143.20
GST Amount S\$ 10.02

Total Amount Payable S\$ 153.22

SUPP 143.20
PART. 4784.32
SN 255.00
LAB 2160.00
7344.52

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: