



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 402 Y

*Not Authorized
Resurvey By paint*

Parts	(a) Cost / List Price Items	\$	8,416.33
	Plus/Less 25%	\$	2,104.08
	Total of Cost / List	\$	6,312.25
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	1,870.00
Total		\$	8,182.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kennerly

Company

:

LKK

Survey conducted on

:

11/12/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *4-5* day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

:

Sc

Date:

11/12/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLP 402 Y**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU103559179**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp LH <i>CM</i>	1	\$2,531.60		✓
2	Front bumper <i>Bu</i>	1	\$450.80		✓
3	Front bumper clip <i>Mc</i>	10	\$40.00		✓
4	Front bumper reinforcement - upper	1	\$711.50		?
5	Front bumper side retainer RH <i>Sm</i>	1	\$107.20		X
6	Front bumper side retainer LH <i>Dir</i>	1	\$107.20		✓
7	Front bumper upper grille	1	\$321.90		?
8	Front bumper lower grille	1	\$148.60		?
9	Front bumper emblem <i>Mc</i>	1	\$87.10		✓
10	Front bumper tow cover LH <i>Sm</i>	1	\$25.70		X
11	Front bumper sponge - upper	1	\$89.81		?
12	Fog lamp LH	1	\$910.70		?
13	LH front fender <i>Bu</i>	1	\$868.70		✓
14	LH front fender undershield <i>CM</i>	1	\$195.60		✓
15	LH front fender undershield clip <i>Mc</i>	10	\$25.00		✓
16	LHF fender wording "HYBRID" <i>Mc</i>	1	\$44.17		✓
17	LH front rim <i>Mc</i>	1	\$1,555.10		✓
18	LH front hub cab	1	\$195.65		?
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.