

ASS. REC. BY:

REF: 08/ALG19021836/Ksd3<sup>37</sup>

Special Instruction:

Envelope: Kenneth

ASSIGNMENT (Office)

From (Person): Winnie Fan

of AIG

Date/Time: 11/12/19 @ 1:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC1533S

Insured:

at Workshop in/s

Esteem performance

Tel:

87990066

of BLK S033 Amk Ind. Park 2 #01-259

Policy No:

Claim No:

Sum Insured:

Excess:

TBA

Make of Veh:  
(Client's Record)

D.O.A. 03/12/2019

CA (REV) / REP. / REV 24 HRS

Jenny

6753 2112 / 6566 2112

H.O.D. Endorsement:

Date/Time: 2:04pm @ 11/12/19

Person Contacted:

Carmen

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate /

PC1533S - X

12/12/19 @ 14:35 pm revised PA to Yoke Sh. via memo.

12/12/19 @ 14:43 pm mandate requested authorize repair to

AIG via memo.

12/12/19 @ 15:47 pm mandate approved by Lois Chery via memo

12/12/19 @ 17:11 pm informed CIA to Carmen (repair) via memo

ASS. REC. BY:

REF:

AIGI

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$2,500 / ~~1000~~

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

835/c

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

3/12

8 4086.80 email & cabins  
(£ 4,594.60 Red - 53%)

RECEIVED 10 MAR 2020

Date/Time, File Pass to?

10/03/20

1)

Type SP

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

F. &amp; S.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum I.B.I. (\$) 4,086.80 p/r

## Nivitha (LKK Auto)

---

**From:** AIG SGP, Claims-Survey <AIGSGP\_ClaimsSurvey@aig.com>  
**Sent:** Wednesday, 11 December 2019 1:22 PM  
**To:** Admin A; assignments  
**Cc:** Fong, Andy-SY  
**Subject:** Aigencypt Request for survey - OD Claim PC1533S  
**Attachments:** 20191211122428918.pdf; PHOTO-2019-12-04-12-54-30.jpg;  
PHOTO-2019-12-04-12-54-30 (1).jpg

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**From:** jenny chong <jenny@esteemp Perf.com.sg>  
**Sent:** Wednesday, December 11, 2019 12:17 PM  
**To:** AIG SGP, Claims-Survey <AIGSGP\_ClaimsSurvey@aig.com>  
**Cc:** carmen lim <carmen@esteemp Perf.com.sg>; serence ctc <serence@esteemp Perf.com.sg>; Kaeley Ng <kaeley@esteemp Perf.com.sg>; Shanice Leong <shanice@esteemp Perf.com.sg>  
**Subject:** [EXTERNAL] Request for survey - OD Claim PC1533S

This message is from an external sender; be cautious with links and attachments.

Dear AIG,

### **NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)**

We act for Goldbell Car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.PC 1533 S

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 (S) 569536

Tel : 6484 1221  
Fax : 6484 7829

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

### Vehicle currently in our workshop

Thank you



Freundliche Grüße / Best Regards

**Jenny Chong**

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: [jenny@esteemperf.com.sg](mailto:jenny@esteemperf.com.sg)

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

[www.esteemperformance.com](http://www.esteemperformance.com)



----- Forwarded message -----

From: [<scan@esteemperf.com.sg>](mailto:scan@esteemperf.com.sg)

Date: Wed, Dec 11, 2019 at 12:15 PM

Subject: Message from "RNP002673F6F984"

To: jenny <[jenny@esteemperf.com.sg](mailto:jenny@esteemperf.com.sg)>

This E-mail was sent from "RNP002673F6F984" (MP C3004ex).

Scan Date: 12.11.2019 12:24:28 (+0800)

Queries to: [scan@esteemperf.com.sg](mailto:scan@esteemperf.com.sg)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Thursday, 12 December 2019 5:11 pm  
**To:** carmen@esteemperf.com.sg; jenny@esteemperf.com.sg; kaeley@esteemperf.com.sg  
**Cc:** SUR  
**Subject:** PC 1533S OD (AIG) DOA - 03/12/2019

Hi Carmen,

As instructed by our client, please proceed to repair the insured vehicle **PC 1533S (Excess S 2,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

*"Best Wishes for Merry Christmas & Happy New Year 2020"*

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*PC1533S (0700173943SG)**

OD

Dec 3 2019 8:00AM

[GOLDBELL CAR RENTAL PTE LTD]

Esteem Performance Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 12/12/2019 15:47 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$4676.00) - PC1533S - Claim Handler: Chan, Yoke Shi

Approved:4676.00:Reinspection require on check item with CLEAR photo

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 12 Dec 2019

**Preliminary Advice**

Vehicle No	: PC1533S	Accident Date	: 03/12/2019
Make	: TOYOTA HIACE	Policy No.	: 0999994304
Assignment Date	: 11/12/2019	Excess	: S\$2,500.00
Date of Inspection	: 11/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,571.40
Revised Amount	:S\$	4,675.30
Check Items (Estimated)	:S\$	430.30
Total	:S\$	5,105.60

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	18,790.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,210.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/12/2019 16:24
Date Of Accident	03/12/2019 08:20
Exact Location Of Accident	CHANGI AIRPORT TERMINAL 1 E20
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1533S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE H/ROOF 3.0 AT
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994313
Cover Note Number	

### Driver

Name of Driver	SAINODRDIN BIN ABDULLAH
NRIC No	S1731669I
Date Of Birth	18/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	16/12/2002
Driving Experience	16 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98579975
Fax Number	
Contact Number	
E-Mail Address	SAINODRDINABDULLAH@GMAIL.COM



Address	BLK 467 PASIR RIS DRIVE 6 #02-414
Postcode	510467
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO




#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	RU3735U
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




 10:00 AM  
 4-12-2019  
 Policyholder's Signature Date & Time  
 - 9 DEC 2019  
 Driver's Signature (if driver is not the policyholder) / Date & Time  
 Witnessed by Reporting Centre Personnel  
 Poh Kwee Choo



Sketch Plan Pg. 2


Describe Circumstance of the Accident \*

AFTER I DROP THE TECHNICIAN AT E-20  
 BAY I INTENT TO MAKE A U TURN AFTER  
 LOOKING AT MY LEFT SIDE INCOMING VEH WAS  
 CLEAR WITHOUT LOOKING AT MY RIGHT SIDE  
 INCOMING VEH ALREADY IN FRONT OF MY VEH.  
 THEN I KNOCK THE TRUCK REAR SIDE UNDER  
 DAMAGE REAR LEFT LIGHT RU 3735 U AND  
 ALSO DAMAGE PC 1533 FET BUMPER COME OFF  
 RIGHT HEADLIGHT, DENTED THE BONNET

Declaration

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature / Date  
 - 9 DEC 2019

  
 Driver's Signature (If driver is not the policyholder) / Date  
 & Time

11:00 A.M  
 4-12-2019

  
 Witnessed by Reporting Centre Personnel  
 Poh Kwee Choo

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	651D
<b>Vehicle Details</b>	
Vehicle No.:	PC1533S
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE H/ROOF 3.0 AT
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	1KD2255216
Chassis No.:	JTFST22P600015776
Maximum Power Output:	-
Open Market Value:	\$37,122.00
Original Registration Date:	31 Jan 2013
First Registration Date:	31 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$1,857.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jan 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$60,000.00
COE Rebate Amount:	\$18,790.00
<b>Total Rebate Amount:</b>	<b>\$18,790.00</b>

The information contained herein is correct as at 12 Dec 2019

OK



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

PC 1533 S

<b>Parts</b>	(a) Cost / List Price Items	_____
	Plus/Less	_____
	<b>Total of Cost / List</b>	=====
	(b) Nett Price Items	_____
	Less	_____
	<b>Total of Nett Item</b>	=====
	(c) <b>Special Nett Items</b>	_____
<b>Total Parts Cost</b>		=====
<b>Labour</b>	<b>\$</b>	<b>2,700.00</b>
<b>Total</b>		=====

The above total will be subjected to 7% G.S.T.

*Not Authorized  
61 Lmp &  
Resurvey After Pain*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kennedy  
Company : LKK  
Survey conducted on : 11/12/19 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 11/12/19



# ESTEEM PERFORMANCE

## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com

### Spare Parts

Vehicle No. : **PC 1533 S**  
Make & Model : **TOYOTA HIACE**  
Chassis No. : **JTFST22P6000015776**

Submit By : \_\_\_\_\_  
Year Manufacture : \_\_\_\_\_  
Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price
1	Front number plate <i>miy</i>	1	\$45.00	S.N ✓
2	Front number plate garnish	1		✓
3	Bonnet <i>Bj</i>	1		✓
4	Bonnet lock	1		✓
5	Bonnet emblem <i>mi</i>	1		✓
6	Bonnet heat insulator <i>nsp</i>	1		X
7	Bonnet heat insulator clip <i>nn</i>	10		X
8	Bonnet hinge LH <i>DiT</i>	1		✓
9	Bonnet hinge RH <i>Bj</i>	1		✓
10	Headlamp LH <i>mi Bj</i>	1		✓
11	Headlamp RH <i>Bj</i>	1		✓
12	Headlamp clip <i>mi</i>	10		✓
13	Headlamp LH Socket	1		?
14	Headlamp RH Socket <i>miy</i>	1		✓
15	RH Corner panel <i>Bj</i>	1		✓
16	Front support panel completed <i>K</i>	1		X
17	Front bumper <i>miy</i>	1		✓
18	Front bumper clip <i>miy</i>	10		✓
19	Front bumper reinforcement <i>Bj</i>	1		✓
20	Front bumper beam <i>Bj</i>	1		✓
21	Front bumper side retainer LH <i>CM</i>	1		✓
22	Front bumper side retainer RH <i>CM</i>	1		✓
23	Front bumper bracket LH <i>K</i>	1		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

### Spare Parts

Vehicle No. : **PC 1533 S**

Submit By : \_\_\_\_\_

Make & Model : TOYOTA HIACE  
Chassis No : JTFST22P6000015776

Year Manufacture :             
Engine No. :           

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price
24	Front bumper bracket RH <i>R</i>	1		<i>?</i>
25	Front bumper upper grille <i>CM</i>	1		<i>✓</i>
26	Front bumper lower grille <i>MR</i>	1		<i>✓</i>
27	Air Filter Box <i>BR</i>	1		<i>✓</i>
28	Condenser <i>SL</i>	1		<i>X</i>
29	Condenser fan motor <i>SL</i>	1		<i>X</i>
30	Condenser fan blade <i>SL</i>	1		<i>X</i>
31	Condenser fan cowling <i>SL</i>	1		<i>X</i>
32	Radiator <i>SL</i>	1		<i>X</i>
33	Radiator fan motor <i>SL</i>	1		<i>X</i>
34	Radiator fan blade <i>SL</i>	1		<i>X</i>
35	Radiator fan cowling <i>SL</i>			<i>X</i>
36	Coolant	1	\$20.00	S.N <i>?</i>
37	"Green" Sticker <i>MR</i>	1	\$20.00	S.N <i>✓</i>
38	RH front door <i>R</i>	1		<i>✓</i>
39				
40				
41				
42				
43				
44				
45				
46				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

**Spare Parts**

Vehicle No. : PC 1533 S  
Make & Model : TOYOTA HIACE  
Chassis No : JTFST22P6000015776

Submit By :             
Year Manufacture :             
Engine No. :

**Spare Parts**

Vehicle No. : **PC 1533 S**  
Make & Model : **T.HIACE**  
Chassis No. : **JTFST22P6000015776**


Submit By : **JENNY**  
Year Manufacture : **2012**  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Front windscreen <i>CN</i>	1			<i>✓</i>
25	Front windscreen moulding <i>me</i>	1			<i>✓</i>
26	Front windscreen sealant <i>me</i>	1			<i>40.50</i>
27	Front windscreen inner seal tape <i>me</i>	1			<i>30.50</i>
28	Front windscreen I.U. bracket <i>me</i>	1			<i>26.50</i>
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





Submit By : Carmen Lim  
Year of Manufacture : 2012

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569538.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

PC 1533 S

Parts	(a) Cost / List Price Items	\$	5,137.00
	Plus/Less 10%	\$	513.70
	Total of Cost / List	\$	5,650.70
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	135.00
Total Parts Cost		\$	5,785.70
Labour		\$	2,700.00
Total		\$	8,485.70

5164  
516.40  
5680.40

191/-

\$ 8541.70

8651.70

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_